January 25<sup>th</sup>, 2019 Project Number: MA-158-18

Mr. Marc Bennett Grand Rapids Public Schools 900 Union, NE Grand Rapids, MI 49503

Re: AHERA 3 Year Reinspection Report Grand Rapids Public Schools – **Central Innovations** 



119 West Cass Street P.O. Box 908 Grand Rapids, MI 48838 Phone: 616-302-0819 Web: microairconsulting.com Email: microairconsulting@gmail.com

Dear Mr. Bennett:

MicroAir Consulting, LLC (MicroAir) was retained by Grand Rapids Public Schools (GRPS), to conduct an AHERA 3-year reinspection of Central Innovations located at 421 Fountain NE in Grand Rapids, Michigan. The inspection was conducted according to the protocol described in the U.S. Environmental Protection Agency Asbestos Hazard Emergency Response Act of 1986 (40 CFR 763).

### CERTIFICATION

The building inspection was conducted on January 2<sup>nd</sup>, 2019 by Mr. Grant Edgerly, a State of Michigan accredited Asbestos Building Inspector. Mr. Edgerly's, Accreditation Number is A41792.

### **REGULATORY BACKGROUND**

As a public and commercial building, Central is governed by 29 CFR 1910.1001, Occupational Health Standards for Asbestos in Construction/General Industry and the EPA's NESHAP for the normal course of business activities by GRPS employees and occupants.

There are three state agencies in Michigan that regulate asbestos in Michigan: the Michigan Department of Environmental Quality (DEQ), the Michigan Department of Licensing and Regulatory Affairs (DLARA) and the Michigan Department of State Police (MSP). The DEQ is concerned about the release of asbestos fibers to the outer air and proper waste disposal, while DLARA focuses on worker protection during renovation and demolition activities, contractor licensing, and worker training.

During construction or renovation activities, the persons performing those activities would be governed by 29 CFR 1926.1101, Occupational Health Standards for Asbestos in Construction. The Asbestos Hazard Emergency Response Act (AHERA), 40 CFR 763, (partial) and/or its associated requirements. However, there are some portions of AHERA that are used as guidelines for compliance with 29 CFR 1910.1001. In particular, 29 CFR 1910.1001(j)(1) requires owners of buildings constructed prior to 1980 to presume that certain types of building materials are asbestos-containing materials (ACM), unless the owner demonstrates that those materials are not ACM.

40 CFR Part 61, Subpart M (NESHAP) requires that a thorough inspection be conducted prior to all renovations and all demolitions. A thorough inspection for asbestos is required no matter the age of the facility because all uses of asbestos are not banned. The inspection must be completed before the commencement of a subject renovation and/or demolition activity.

### **BUILDING DESCRIPTION**

The Central Innovations building was constructed in 1910 with additions in 1927, 1931 and 1982. Some building renovations have occurred throughout over the years.

### **PREVIOUS INSPECTION**

The most recent inspection was conducted by GRPS in 2018. MicroAir reviewed this report and incorporated the findings of the previous inspection and historical information into the current reinspection data.

In the previous inspection report suspect ACM materials were given a unique identification number (homogeneous material number), MicroAir has changed numbering from previous reports. The reinspection did

include the collection of bulk samples. Results of the sampling can be found in Appendix A along with locations of remaining ACM in the building.



### **REINSPECTION PROCEDURES**

With the assistance of GRPS maintenance staff, MicroAir re-inspected known and previously identified areas of the building including above suspended ceilings, pipe chases, and inside the tunnels.

It was beyond the scope of this reinspection to locate, identify, or quantify ACM in areas that were concealed and/or inaccessible areas, such as within walls, hard ceilings, or equipment.

### **2019 REINSPECTION FINDINGS**

The following suspect asbestos-containing materials were observed at Central Innovations during the asbestos inspection and the bulk sampling. Materials in **bold** were found to be greater than 1% ACM.

- Drywall, tape and mud
- Plaster
- White sink undercoating
- 12"x12" White w/multi-color vinyl floor tile w/mastic
- 1910 1'x1' Ceiling tile small holes and glue pods
- 1'x1' Ceiling tile large holes and glue pods
- 2'x2' Ceiling tile
- 12"x12" White w/green marks vinyl floor tile w/mastic
- Brown cove base
- Black counter tops
- 12"x12" White vinyl floor tile w/mastic
- Wood floor
- Chalkboards
- Fire doors
- Transite fume hood
- Roofing
- Concrete
- Grouts
- Mortars
- Caulks and sealants
- Pipe insulation
- Wire insulation
- White lab top
- Troweled on plaster

Some of the materials listed above are assumed to contain asbestos until bulk samples can be collected and analyzed.

Appendix A of this report is a table that identifies the confirmed and suspect ACM homogeneous materials in Central, their corresponding identification number and locations, and the general condition of ACMs identified during the reinspection.

### CONCLUSIONS AND RECOMMENDATIONS

MicroAir was retained by Grand Rapids Public Schools to conduct a 3-year asbestos-containing material (ACM) reinspection of Central Innovations located at 421 Fountain NE in Grand Rapids, Michigan. MicroAir completed the reinspection on January 2<sup>nd</sup>, 2019. The inspection was conducted by a State of Michigan accredited Asbestos Building Inspector.

During the reinspection, MicroAir identified and assessed 24 homogeneous materials remaining in Central Innovations.

Any personnel entering a tunnel or chase area must be notified of ACM locations and explained the requirement to wear personal protective equipment.

If GRPS plans to conduct any renovation or demolition, the identified ACMs should be removed by a licensed asbestos abatement contractor, as required by current federal, state, and local laws and regulations, should perform any necessary removal and disposal of the identified ACM. MicroAir notes that if suspect ACM other than those identified during this reinspection are encountered during any renovation or demolition, such materials should be sampled and analyzed using PLM to verify presence of asbestos.



We also recommend that visual observations, verification of removal and cleanup, and air monitoring or clearance air monitoring for asbestos fibers be performed by a third party retained by GRPS to demonstrate compliance with applicable regulations, and to confirm the suitability or the area for re-entry. MicroAir can perform these services.

Warning labels should be affixed in all non-public areas where ACM or assumed ACM is present. After completion of repairs or removal of the ACM, fill out an O&M Activities Form and file it in the management plan.

As required by AHERA, GRPS should continue to send the annual notifications including information on planned response actions and reinspections. Copies of the notifications should be kept in the Management Plan.

### LIMITATIONS

The conclusions drawn from the observations and sample results are only valid for the time the observations occurred. In the process of gathering the field data included in this report, procedures were followed that represent reasonable and acceptable industrial hygiene practices and procedures in a manner consistent with the level of care and skill ordinarily exercised by other members of this profession currently practicing under similar conditions. However, the information and opinions provided in this report are not to be construed as a warranty of the conditions of this site in any way, implied or explicit. MicroAir accepts no responsibility for the use, interpretation, or reliance by other parties on the information contained herein, nor does this report represent an instrument of regulatory compliance or an asbestos abatement specification.

In conducting the reinspection there are a number of obstacles and limitations that can affect the final outcome of the report. These limitations include but are not limited to the following factors: access concerns, materials that cannot be intrusively sampled or damaged, materials that have been replaced by renovation activities, materials with conflicting laboratory results, and materials that are located in inaccessible and/or concealed areas which limits its quantification. Due to these limitations, the results of this investigation cannot be construed as a certification of the presence or absence of ACM, beyond the materials identified, but rather a diligent and prudent review of available data within an established work scope, and time and budgetary constraints.

If you have any questions or require additional information, please contact me at 616-302-0819 or microairconsulting@gmail.com. Thank you.

Sincerely,

**MicroAir Consulting, LLC** 

tin T. Decker

Christian T. Decker Accredited Building Inspector and Management Planner

### **APPENDIX A**

### TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS

### **APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS CENTRAL INNOVATIONS INSPECTION DATE: JANUARY 2nd, 2019**



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
CHS-1	Drywall, tape and mud	No	SM		132(500 SF)	
CHS-2	All Plasters (1910 and 1930)	No	SM		1910's and 1930's plaster	
CHS-3	White sink undercoating	No	ММ		24(6 SF), 318(6 SF)	
CHS-4	12"x12" White w/multi-color vinyl floor tile w/mastic	Tile-No Mastic-No	MM		24(2700 SF)	
CHS-5	1910 - 1'x1' Ceiling tile small holes and glue pods	Tile- <b>Yes</b> Pod-No	MM	NF-II	Rooms 10, 17, 19, 29,138, 311, 312. Corridors 66, 67, 68, 70, 153, 161, 158, 157, 230, 231, 232, 234, 336, 337, 338 (35,000 SF total)	Good
CHS-6	1'x1' Ceiling tile large holes and glue pods	Tile-No Pod-No	MM		17(2500 SF),	
CHS-7	2'x2' Ceiling tile	No	ММ		17(2500 SF)	
CHS-8	12"x12" White w/green marks vinyl floor tile w/mastic	Tile- <b>Yes</b> Mastic-No	MM	NF-I	132(1250 SF)	Good
CHS-9	Brown cove base	No	MM		132(150 LF)	
CHS-10	Black counter tops	Yes	MM	NF-II	Science area	Good
CHS-11	12"x12" White vinyl floor tile w/mastic	Tile- <b>Yes</b> Mastic- <b>Yes</b>	MM	NF-I	400(1600 SF)	Good
CHS-12	Wood floor	No	MM	-	210, 211, 217, 219	
CHS-13	Chalkboards	No	MM		Classrooms	

### FRIABILITY: F: Friable

### MATERIAL TYPE:

### TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

### **CONDITION:**

Good: Little or no damage

Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

SF: Square feet LF: Linear feet FT: Fittings NQ: Not Quantified

NF-I: Non-friable Category I

NF-II: Non-friable Category II

### APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS CENTRAL INNOVATIONS INSPECTION DATE: JANUARY 2<sup>nd</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
CHS-14	Fire doors	Assumed	MM	MM	All tagged doors and frames	Good
CHS-15	Transite fume hood	Yes	MM	NF-II	Rom 132(70 SF)	Good
CHS-16	Roofing	Assumed	MM	NF-I	Exterior roof (roof caulk 15%)	Good
CHS-17	Concrete	Assumed	MM	NF-II	All concrete	Good
CHS-18	Grouts	Assumed	MM	NF-I	All ceramic tile areas	Good
CHS-19	Mortars	No	MM	NF-II	All block and brick walls	Good
CHS-20	Caulks and sealants	Assumed	MM	NF-II	All original caulks and sealants	Good
CHS-21	Pipe insulation	Yes	TSI	F	Rooms 221, 136, 128C, 5S, 9, 41, 42, 21, east of 21, Gym 101, Gym 001 and hidden in walls	Good
CHS-22	Wire insulation	Assumed	MM	NF-II	Original wirings	Good
CHS-23	White lab top	Yes	MM	NF-II	Room 225 (30 SF)	Good
CHS-24	Troweled on plaster	No	SM		Elevator shaft	

### FRIABILITY:

MATERIAL T

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II MATERIAL TYPE:

TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

### **CONDITION:**

Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

SF: Square feet LF: Linear feet FT: Fittings NQ: Not Quantified

This page has been left blank intentionally

January 25<sup>th</sup>, 2019 Project Number: MA-158-18

Mr. Marc Bennett Grand Rapids Public Schools 900 Union, NE Grand Rapids, MI 49503 Micro Air Consulting, LLC

Re: AHERA 3 Year Reinspection Report Grand Rapids Public Schools – **Ridgemoor Park Montessori**  119 West Cass Street P.O. Box 908 Grand Rapids, MI 48838 Phone: 616-302-0819 Web: microairconsulting.com Email: microairconsulting@gmail.com

Dear Mr. Bennett:

MicroAir Consulting, LLC (MicroAir) was retained by Grand Rapids Public Schools (GRPS), to conduct an AHERA 3-year reinspection of Ridgemoor Park Montessori (RPM) located at 2555 Inverness SE in Grand Rapids, Michigan. The inspection was conducted according to the protocol described in the U.S. Environmental Protection Agency Asbestos Hazard Emergency Response Act of 1986 (40 CFR 763).

### CERTIFICATION

The building inspection was conducted on January 3<sup>rd</sup>, 2019 by Mr. Grant Edgerly, a State of Michigan accredited Asbestos Building Inspector. Mr. Edgerly's, Accreditation Number is A41792.

### **REGULATORY BACKGROUND**

As a public and commercial building, Ridgemoor is governed by 29 CFR 1910.1001, Occupational Health Standards for Asbestos in Construction/General Industry and the EPA's NESHAP for the normal course of business activities by GRPS employees and occupants.

There are three state agencies in Michigan that regulate asbestos in Michigan: the Michigan Department of Environmental Quality (DEQ), the Michigan Department of Licensing and Regulatory Affairs (DLARA) and the Michigan Department of State Police (MSP). The DEQ is concerned about the release of asbestos fibers to the outer air and proper waste disposal, while DLARA focuses on worker protection during renovation and demolition activities, contractor licensing, and worker training.

During construction or renovation activities, the persons performing those activities would be governed by 29 CFR 1926.1101, Occupational Health Standards for Asbestos in Construction. The Asbestos Hazard Emergency Response Act (AHERA), 40 CFR 763, (partial) and/or its associated requirements. However, there are some portions of AHERA that are used as guidelines for compliance with 29 CFR 1910.1001. In particular, 29 CFR 1910.1001(j)(1) requires owners of buildings constructed prior to 1980 to presume that certain types of building materials are asbestos-containing materials (ACM), unless the owner demonstrates that those materials are not ACM.

40 CFR Part 61, Subpart M (NESHAP) requires that a thorough inspection be conducted prior to all renovations and all demolitions. A thorough inspection for asbestos is required no matter the age of the facility because all uses of asbestos are not banned. The inspection must be completed before the commencement of a subject renovation and/or demolition activity.

### **BUILDING DESCRIPTION**

The Ridgemoor Park Montessori building was constructed in 1972. The old part of the school was demolished in the summer of 2018 after all ACM was removed from the building. **In 2017, Ridgemoor underwent a large asbestos abatement. All asbestos was removed from Ridgemoor with the exception of the** 

### **PREVIOUS INSPECTION**

The most recent inspection was conducted by GRPS in 2018. MicroAir reviewed this report and incorporated the findings of the previous inspection and historical information into the current reinspection data.



In the previous inspection report suspect ACM materials were given a unique identification number (homogeneous material number), MicroAir has changed numbering from previous reports. The reinspection did include the collection of bulk samples. Results of the sampling can be found in Appendix A along with locations of remaining ACM in the building.

### **REINSPECTION PROCEDURES**

With the assistance of GRPS maintenance staff, MicroAir re-inspected known and previously identified areas of the building including above suspended ceilings, pipe chases, and inside the tunnels.

It was beyond the scope of this reinspection to locate, identify, or quantify ACM in areas that were concealed and/or inaccessible areas, such as within walls, hard ceilings, or equipment.

### **2019 REINSPECTION FINDINGS**

The following suspect asbestos-containing materials were observed at Ridgemoor Park Montessori during the asbestos inspection and the bulk sampling. Materials in **bold** were found to be greater than 1% ACM.

- Roof drain insulation
- Mudded fittings on cold water lines
- Mudded fittings on hot water lines
- Lag cloth
- Purple/White sink undercoating
- Cove base w/mastic
- 1'x2' white ceiling tile
- 12"x12" green floor tile w/mastic
- 12"x12" cream floor tile w/mastic
- Exterior overhang texture
- Vibration dampeners on ductwork
- Drywall
- Concrete
- Grouts
- Mortars
- Caulks and sealants
- Asphalt roofing under rubber
- Asphalt roofing under stones
- Fire doors

Some of the materials listed above are assumed to contain asbestos until bulk samples can be collected and analyzed.

Appendix A of this report is a table that identifies the confirmed and suspect ACM homogeneous materials in Ridgemoor, their corresponding identification number and locations, and the general condition of ACMs identified during the reinspection.

### CONCLUSIONS AND RECOMMENDATIONS

MicroAir was retained by Grand Rapids Public Schools to conduct a 3-year asbestos-containing material (ACM) reinspection of Ridgemoor Park Montessori located at 2555 Inverness SE in Grand Rapids, Michigan. MicroAir completed the reinspection on January 3<sup>rd</sup>, 2019. The inspection was conducted by a State of Michigan accredited Asbestos Building Inspector.

During the reinspection, MicroAir identified and assessed 19 homogeneous materials remaining in Ridgemoor Park Montessori.

Any personnel entering a tunnel or chase area must be notified of ACM locations and explained the requirement to wear personal protective equipment.

If GRPS plans to conduct any renovation or demolition, the identified ACMs should be removed by a licensed asbestos abatement contractor, as required by current federal, state, and local laws and regulations, should perform any necessary removal and disposal of the identified ACM. MicroAir notes that if suspect ACM other

than those identified during this reinspection are encountered during any renovation or demolition, such materials should be sampled and analyzed using PLM to verify presence of asbestos.



We also recommend that visual observations, verification of removal and cleanup, and air monitoring or clearance air monitoring for asbestos fibers be performed by a third party retained by GRPS to demonstrate compliance with applicable regulations, and to confirm the suitability or the area for re-entry. MicroAir can perform these services.

Warning labels should be affixed in all non-public areas where ACM or assumed ACM is present. After completion of repairs or removal of the ACM, fill out an O&M Activities Form and file it in the management plan.

As required by AHERA, GRPS should continue to send the annual notifications including information on planned response actions and reinspections. Copies of the notifications should be kept in the Management Plan.

### LIMITATIONS

The conclusions drawn from the observations and sample results are only valid for the time the observations occurred. In the process of gathering the field data included in this report, procedures were followed that represent reasonable and acceptable industrial hygiene practices and procedures in a manner consistent with the level of care and skill ordinarily exercised by other members of this profession currently practicing under similar conditions. However, the information and opinions provided in this report are not to be construed as a warranty of the conditions of this site in any way, implied or explicit. MicroAir accepts no responsibility for the use, interpretation, or reliance by other parties on the information contained herein, nor does this report represent an instrument of regulatory compliance or an asbestos abatement specification.

In conducting the reinspection there are a number of obstacles and limitations that can affect the final outcome of the report. These limitations include but are not limited to the following factors: access concerns, materials that can not be intrusively sampled or damaged, materials that have been replaced by renovation activities, materials with conflicting laboratory results, and materials that are located in inaccessible and/or concealed areas which limits its quantification. Due to these limitations, the results of this investigation cannot be construed as a certification of the presence or absence of ACM, beyond the materials identified, but rather a diligent and prudent review of available data within an established work scope, and time and budgetary constraints.

If you have any questions or require additional information, please contact me at 616-302-0819 or microairconsulting@gmail.com. Thank you.

Sincerely,

### **MicroAir Consulting, LLC**

uten T. Decker

Christian T. Decker Accredited Building Inspector and Management Planner

### **APPENDIX A**

### TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS



### APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS RIDGEMOOR PARK MONTESSORI INSPECTION DATE: JANUARY 3<sup>RD</sup>, 2019

HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
RD-1	Roof drain insulation	No	TSI		Pool Area	
MFC-2	Mudded fittings on cold water lines	No	TSI		Boiler room and air handler rooms	
MFH-3	Mudded fittings on hot water lines	No	TSI		Boiler room and air handler rooms	
LC-4	Lag cloth	No	TSI		Boiler room and air handler rooms	
SC-5	Purple/White sink undercoating	Yes	MM	NF-II	REMOVED IN 2017	Good
CB-6	Cove base w/mastic	No	MM		Interior walls	
CT-7	1'x2' white ceiling tile	No	MM		Center area	
FT-8	12"x12" green floor tile w/mastic	Tile- <b>Yes</b> Mastic- No	MM	NF-I	REMOVED IN 2017	Good
FT-9	12"x12" cream floor tile w/mastic	Tile- No Mastic- No	MM		All cream floor tile	
EO-10	Exterior overhang texture	No	MM		Outside overhangs	
VD-11	Vibration dampeners on ductwork	No	MM		Boiler room and air handler rooms	
DW-12	Drywall	No	SM		Interior walls	Good
CO-13	Concrete	Assumed	MM	NF-II	All concrete	Good
G-14	Grouts	Assumed	MM	NF-I	All ceramic tile areas	Good
M-15	Mortars	Assumed	MM	NF-II	All block and brick walls	Good
CS-16	Caulks and sealants	Assumed	MM	NF-II	All original caulks and sealants	Good

### FRIABILITY:

### MATERIAL TYPE:

### F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II

TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

### CONDITION:

Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

SF: Square feet LF: Linear feet FT: Fittings NQ: Not Quantified

### **APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS RIDGEMOOR PARK MONTESSORI** TON DATE, JANULADY 280 2010 INSP

ISPECIT	ON DATE: JANUARY $3^{\infty}$ , 2019					
HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
RF-1	Asphalt roofing under rubber	No	MM		Center area and towards perimeter of building	
RF-2	Asphalt roofing under stones	Yes	MM	NF-I	4 asphalt roofs around the building (525 SF)	Good
FD-1	Fire doors				REMOVED IN 2017	

FRIABILITY: F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II MATERIAL TYPE: SM: Surfacing Material

MM: Miscellaneous Material

### **CONDITION:** TSI: Thermal System Insulation

Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

SF: Square feet LF: Linear feet FT: Fittings NQ: Not Quantified

### **TESTED SUSPECT LEAD-CONTAINING PAINTS - 2017 RIDGEMOOR PARK MONTESSORI**

SAMPLE NO.	SAMPLE LOCATION	COMPONENT	COLOR	REPORTING LIMIT	LEAD CONCENTRATION
RM-1	Custodial area	Floor	Brown	0.017%	<rl%< td=""></rl%<>
RM-2	Boiler room	Louver	Gray	0.0051%	2.5%
RM-3	Interior walls	Wall	Blue	0.0025%	0.16%
RM-4	Interior walls	Wall	White	0.0025%	0.14%



This page has been left blank intentionally

March 11<sup>th</sup>, 2020 Project Number: MA-117-19

Mr. Marc Bennett Grand Rapids Public Schools 900 Union, NE Grand Rapids, MI 49503

Re: AHERA 3 Year Reinspection Report Grand Rapids Public Schools – Harrison Park Elementary School

Dear Mr. Bennett:



119 West Cass Street P.O. Box 908 Grand Rapids, MI 48838 Phone: 616-302-0819 Web: microairconsulting.com Email: microairconsulting@gmail.com

MicroAir Consulting, LLC (MicroAir) was retained by Grand Rapids Public Schools (GRPS), to conduct an AHERA 3-year reinspection of Harrison Park Elementary School located at 1440 Davis Avenue NW in Grand Rapids, Michigan. The inspection was conducted according to the protocol described in the U.S. Environmental Protection Agency Asbestos Hazard Emergency Response Act of 1986 (40 CFR 763).

### CERTIFICATION

The building inspection was conducted on February 21<sup>st</sup>, 2020 by Mr. Grant Edgerly, a State of Michigan accredited Asbestos Building Inspector. Mr. Edgerly's, Accreditation Number is A41792.

### **REGULATORY BACKGROUND**

As a public and commercial building, Harrison Park is governed by 29 CFR 1910.1001, Occupational Health Standards for Asbestos in Construction/General Industry and the EPA's NESHAP for the normal course of business activities by GRPS employees and occupants.

There are three state agencies in Michigan that regulate asbestos in Michigan: the Michigan Department of Environmental Quality (DEQ), the Michigan Department of Licensing and Regulatory Affairs (DLARA) and the Michigan Department of State Police (MSP). The DEQ is concerned about the release of asbestos fibers to the outer air and proper waste disposal, while DLARA focuses on worker protection during renovation and demolition activities, contractor licensing, and worker training.

During construction or renovation activities, the persons performing those activities would be governed by 29 CFR 1926.1101, Occupational Health Standards for Asbestos in Construction. The Asbestos Hazard Emergency Response Act (AHERA), 40 CFR 763, (partial) and/or its associated requirements. However, there are some portions of AHERA that are used as guidelines for compliance with 29 CFR 1910.1001. In particular, 29 CFR 1910.1001(j)(1) requires owners of buildings constructed prior to 1980 to presume that certain types of building materials are asbestos-containing materials (ACM), unless the owner demonstrates that those materials are not ACM.

40 CFR Part 61, Subpart M (NESHAP) requires that a thorough inspection be conducted prior to all renovations and all demolitions. A thorough inspection for asbestos is required no matter the age of the facility because all uses of asbestos are not banned. The inspection must be completed before the commencement of a subject renovation and/or demolition activity.

### BUILDING DESCRIPTION

The Harrison Park Elementary School building was built in 1925 and fully renovated in 2006.

### **PREVIOUS INSPECTION**

No previous inspection data.

### **REINSPECTION PROCEDURES**

With the assistance of GRPS maintenance staff, MicroAir re-inspected known and previously identified areas of the building including above suspended ceilings and pipe chases.

It was beyond the scope of this reinspection to locate, identify, or quantify ACM in areas that were concealed and/or inaccessible areas, such as within walls, hard ceilings, or equipment.



### **2020 REINSPECTION FINDINGS**

The following suspect asbestos-containing materials were observed at Harrison Park Elementary School during the asbestos inspection and the bulk sampling.

- 2'x2' ceiling tile
- Drywall, tape and mud
- Concrete
- Brick mortar
- Block mortar
- Exterior caulk

Some of the materials listed above are assumed to contain asbestos until bulk samples can be collected and analyzed.

Appendix A of this report is a table that identifies the confirmed and suspect ACM homogeneous materials in Harrison Park Elementary School, their corresponding identification number and locations, and the general condition of ACMs identified during the reinspection.

### CONCLUSIONS AND RECOMMENDATIONS

MicroAir was retained by Grand Rapids Public Schools to conduct a 3-year asbestos-containing material (ACM) reinspection of Harrison Park Elementary School located at 1440 Davis Avenue NW in Grand Rapids, Michigan. MicroAir completed the reinspection on February 21<sup>st</sup>, 2020. The inspection was conducted by a State of Michigan accredited Asbestos Building Inspector.

During the reinspection, MicroAir identified and assessed 6 homogeneous materials remaining in Harrison Park Elementary School.

If GRPS plans to conduct any renovation or demolition, the identified ACMs should be removed by a licensed asbestos abatement contractor, as required by current federal, state, and local laws and regulations, should perform any necessary removal and disposal of the identified ACM. MicroAir notes that if suspect ACM other than those identified during this reinspection are encountered during any renovation or demolition, such materials should be sampled and analyzed using PLM to verify presence of asbestos.

We also recommend that visual observations, verification of removal and cleanup, and air monitoring or clearance air monitoring for asbestos fibers be performed by a third party retained by GRPS to demonstrate compliance with applicable regulations, and to confirm the suitability or the area for re-entry. MicroAir can perform these services.

Warning labels should be affixed in all non-public areas where ACM or assumed ACM is present. After completion of repairs or removal of the ACM, fill out an O&M Activities Form and file it in the management plan.

As required by AHERA, GRPS should continue to send the annual notifications including information on planned response actions and reinspections. Copies of the notifications should be kept in the Management Plan.

### LIMITATIONS



The conclusions drawn from the observations and sample results are only valid for the time the observations occurred. In the process of gathering the field data included in this report, procedures were followed that represent reasonable and acceptable industrial hygiene practices and procedures in a manner consistent with the level of care and skill ordinarily exercised by other members of this profession currently practicing under similar conditions. However, the information and opinions provided in this report are not to be construed as a warranty of the conditions of this site in any way, implied or explicit. MicroAir accepts no responsibility for the use, interpretation, or reliance by other parties on the information contained herein, nor does this report represent an instrument of regulatory compliance or an asbestos abatement specification.

In conducting the reinspection there are a number of obstacles and limitations that can affect the final outcome of the report. These limitations include but are not limited to the following factors: access concerns, materials that cannot be intrusively sampled or damaged, materials that have been replaced by renovation activities, materials with conflicting laboratory results, and materials that are located in inaccessible and/or concealed areas which limits its quantification. Due to these limitations, the results of this investigation cannot be construed as a certification of the presence or absence of ACM, beyond the materials identified, but rather a diligent and prudent review of available data within an established work scope, and time and budgetary constraints.

If you have any questions or require additional information, please contact me at 616-302-0819 or microairconsulting@gmail.com.

Sincerely,

**MicroAir Consulting, LLC** 

pristen T. Decker

Christian T. Decker Accredited Building Inspector and Management Planner

### **APPENDIX A**

### TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS

4

d	Micro	Consulting, LLC

## **TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS INSPECTION DATE: FEBRUARY 21<sup>st</sup>, 2020** HARRISON PARK ELEMENTARY SCHOOL **APPENDIX A- 3 YEAR REINSPECTION**

 $\bigcirc$ 

-	HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
	HP-1	2'x2' ceiling tile	No	SM	1	Interior drop ceiling	1
	HP-2	Drywall, tape and mud	No	SM	I	Interior drywall	ſ
	HP-3	Concrete	Assumed	ΜМ	II-1	All concrete	Good
	HP-4	Brick mortar	Assumed	MM	NF-II	All brick walls	Good
-	HP-5	Block mortar	Assumed	MM	NF-II	All cinderblock walls	Good
	HP-6	Exterior caulk	Assumed	MM	NF-II	Around windows, doors and wall seams	Good
		MATCHIAL TURE.	- NOTITION				

NF-I: Non-friable Category I NF-II: Non-friable Category II FRIABILTIY: F: Friable

MATERIAL TYPE: TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

**CONDITION:** Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

NQ: Not Quantified FT: Fittings LF: Linear feet SF: Square feet This page has been left blank intentionally





Certificate of Laboratory Analysis Test Method, Polarized Light Microscopy (PLM) Project : GRPS- Horizon Park & Briggs



Report To: Mr. Chris Decker MicroAir Consuling P.O. Box 908 Greenville, MI 48838 Sample Information Lab ID#: 89058 - 01 Cust. #: HP-1 Materiai: 2x2 Ceiling Tie Doop In Location:	Asbestos Type/Percent Asbestos Present: NO No Asbestos Observed	ARI Report # 20-89058 Date Collected: 0221/20 Date Reported: 0228/20 Date Analyzed: 0228/20 Date Analyzed: 02/28/20 Date Reported: 03/02/20 Non-Asbestos Material Cellulose - 40% Mineral Wool - 5% Fiberglass - 30% Other - 25%			
Layer: 1 of 1 Lab ID #: 89058 - 02 Cust. #: HP-2-1 Material: Dryvall Location: Appearance: beige,fibrous,nonhomogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Cellulose - 20% Fiberglass - 2% Other - 78%			
Lab ID #: 89058 - 02a Cust. #: HP-2-1 Material: Joint Compound Location: Appearance: while,nonfibrous,homogenous Layer: 2 of 2	Asbestos Present: <b>NO</b> No Asbestos Observed	Other - 100%			
For Layered Samples, each component will be analyzed and reported separately.       Robert T. Letarte Jr., Laboratory Director       Tet Method IDA 600 R/00116 was used to analyze the dover samples. Matrix inteference and/or resolution limit any yield fidewingsive remains in sortion simumatoon. Supposit floor teles containing 4% should be tasked with 2DM or TDM. This coefficient of analyzes and or resolution limits any yield fidewingsive remains, any only for reported to fide fidewingsive remains. APXX Research is in an experiment. APXX Research is in an expension of the results for lyon and and remains. APXX Research is in an expension of the results for lyon and and remains. APXX Research is in an expension of the results for lyon and and remains.					
ार्ग् (युद्धु) NVLAF Lab Code (92118-0	lac, 11654 Hi Treh Drive, Whitmore Lake, MI 4 (734) 449-9993, Fax (734) 449-9991	159 Page 1 of 6			
<b>Certifica</b> Test Method, F Project :	te of Laboratory Anal Polarized Light Microscopy GRPS- Horizon Park & Brigg	ysis (PLM) s			
Report To: Mr. Cluis Decker MicroAit Consulting P.O. Box 908 Greenville, MI 48838		ARI Report # 20-89058 Date Collected: 02/21/20 Date Received: 02/28/20 Date Analyzed: 02/28/20 Date Reported: 03/02/20			

Sample Information	Asbestos Type/Percent	Non-Asbestos Material
Lab ID #: 89058 - 04 Cust. #: HP-2-3 Material: Dyswall Location: Appearance: beige,fibrous,nonhomogenous Layer: 1 of 2	Asbestos Present: <b>NO</b> No Asbestos Observed	Cellulose - 20% Fiberglass - 2% Other - 78%
Lab ID #: 89058 - 04a Cust. #: HP-2-3 Material: Joint Compound Location: Appearance: while,nonfibrous.homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 89038 - 05 Cust. #: HP-2-4 Material: Drywall Location: Appearance: beigg.fibrous.nonhomogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Cellulose - 20% Fiberglass - 2% Other - 78%

For Layered Samples, each component will be analyzed and reported separately.

Revt Jeff Robert T. Letarte Jr., Laboratory Director

Tel Media IDA 60342116 esta una la tradyar de advar angeles. Mettis inferience aciós escolan la limita nay idel Galengario renalta no esta incastinos. Super di oc tidas contining el 9% ochieva tel noto 14% IDA 17%. Tal conferience aciónyi esta esta oly la tenargia testa de advaria esta contining al 9% ochieva tenarda nay a del advaria testa de advaria testa de advaria d

RTVLAD NVLAP Lab Code 102118-0

APEX Research Inc., 11054 Hi Tech Drive, Whitmore Lake, MI 48189 (734) 449-9990, Fax (734) 449-9991

Page 3 of 6

Certificate of Laboratory Analysis Test Method, Polarized Light Microscopy (PLM) Project : GRPS- Horizon Park & Briggs



Report To: Mr. Chris Decker MicroAir Consulting P:O. Box 908 Greenville, MI 48838		ARI Report # 20-8905 Date Collected: 02/21/2 Date Received: 02/28/2 Date Analyzed: 02/28/2 Date Reported: 03/02/20
Sample Information	Asbestos Type/Percent	Non-Asbestos Mater
Lab ID #: 89058 - 03 Cust. #: HP-2-2 Material: Dywall Location: Appearance: beige,fibrous,nonhomogenous Layer: 1 of 3	Asbestos Present: NO No Asbestos Observed	Cellulose - 20% Fiberglass - 2% Other - 78%
Lab ID #: 89058 - 03a Cast. #: HP-22 Material: Joint Compound Location: Appearance: while,nonfibrous,hornogenous Layer: 2 of 3	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 89058 - 03b Cust. #: HP-2-2 Material: Glue on Paint Location: Appearance: beige_nonfibrous,homogenous Layer: 3 of 3	Asbestos Present: NO No Asbestos Observed	Other - 100%
For Layered Samples, each component will be analyzed and repo	orted separately.	
	16	ut fitt
	Robert T. L	etarte Jr., Laboratory Directo
NV (AQ) APEX Research I	nc., 11054 Hi Tech Drive, Whitmore Lake, MI 4	
	(734) 449-9990, Fax (734) 449-9991	Paga 2
<b>Certificat</b> Test Method, P Project : (	cuo 4499999, Fax Cuo 44999991 <b>ce of Laboratory Anal</b> olarized Light Microscopy GRPS- Horizon Park & Brigg	ysis / (PLM) s
Certificat Test Method, P Project : 0 Report To: Mr. Cluis Decker Microsoftic Consulting Pro. No: 708 Greenville, MI 48838	(230 4499999, Pax (230) 4499999 <b>ie of Laboratory Anal</b> olarized Light Microscopy GRPS- Horizon Park & Brigg	ARI Report # 20-89055 bate Collected: 0221/2 Date Recoved: 02228/2 Date Recoved: 0228/2 Date Recoved: 0230/2
Certificat Test Method, P Project : 4 Mr. Cluis Decker Microkir Consulting P.O. Box 908 Greenville, MI 48838 Sample Information	(230 4499999, Pax (230) 4499991 <b>ie of Laboratory Anal</b> olarized Light Microscopy GRPS- Horizon Park & Brigg Asbestos Type/Percent	ARI Report # 20-85058 Date Collected: 02/21/20 Date Reported: 02/21/20 Date Reported: 02/21/20 Date Reported: 02/21/20 Date Reported: 02/21/20 Date Reported: 02/21/20 Date Reported: 03/02/20 Date Reported: 03/02/20
Certificat Test Method, P Project : 0 Mr. Chris Decker MicroAir Consulting PO. Box 908 Greenville, MI 48838 Sample Information Lab ID #: 89058 - 05a Cust. #: HP-24 Materiai: Joint Compound Location: Appearance: white, nonlibrous, homogenous Layer: 2 of 2	(35) 4499999, Pax (35) 4499991 te of Laboratory Anal; olarized Light Microscopy GRPS- Horizon Park & Brigg Asbestos Type/Percent Asbestos Present: NO No Asbestos Observed	ARI Report # 20-89058 Date Collected: 02/28/20 Date Report # 02/28/20 Date Report # 03/02/20 Date Reported: 03/02/20 Date Reported: 03/02/20 Date Reported: 03/02/20 Non-Asbestos Materi Other - 100%
Certificat Test Method, P Project : 6 Mr. Chris Deker MicroAir Consulting P.O. Jos 908 Greenville, MI 45838 Sample Information Lab ID #: 89058 - 05a Cust. #: HP-2-4 Materiai: Joint Compound Location: Appearance: white.nonfibrous.homogenous Layer: 2 of 2 Lab ID #: 89058 - 06 Cust. #: HP-2-5 Materiai: Dywall Location: Appearance: beigg.fibrous.nonhomogenous Layer: 1 of 2	(230) 449 9999, Fax (230) 449 9991 are of Laboratory Anal- olarized Light Microscopy GRPS- Horizon Park & Brigg Asbestos Type/Percent Asbestos Type/Percent Asbestos Observed Asbestos Present: NO No Asbestos Observed	ARI Report # 20-89055 (PLM) s ARI Report # 20-89055 Date Collected: 02/21/2 Date Received: 02/21/2 Date Received: 02/21/2 Date Analysic: 0/2/8/2 Date Analysic: 0/2/8/2 Date Reported: 0/3/02/20 Non-Asbestos Mater Other - 100%

Tet Mehd EPA 6007.49116 was used to malyze the above samples. Matix interfacence and/or rescheina limits may juid false/segator results in actualis aircumaternes. Support flow tables containing v(4), should be totals with SEM or TEM. This confidence of analysis relates only to be samples and a loss more the integrity of the media, may only be providence in fall. This confidence must the total with the integrity of the media integrity of the same table integrity of the media, and you only be total and the integrity of the media, and you only be above the integrity of the media in the integrity of the media for layered and the integrity of the media in the integrity of the media for layer and and the integrity of the media for layer layer and the integrity of the media for layered analysis on samples or manyles or mapping multiple materials. Likeling formation to cost analysis.

NVLAP Lab Code 102118-9

APEX Research Inc., 11054 Hi Tech Drive, Whitmore Lake, MI 48189 (734) 449-9990, Fax (734) 449-9991

Page 4 of 6

Certificate of Laboratory Analysis Test Method, Polarized Light Microscopy (PLM) Project : GRPS- Horizon Park & Briggs



Sample Information	Asbestos Type/Percent	Non-Asbesto	os Material
Greenville, MI 48838		Date Reported:	03/02/20
P.O. Box 908		Date Analyzed:	02/28/20
MicroAir Consulting		Date Received:	02/28/20
Mr. Chris Decker		Date Collected:	02/21/20
Report To:		ARI Report #	20-89058

Lab ID #: 82058 - 07 Cust. #: HP-2-6 Material: Drywall Location: Appearance: beige,fibrous,nonhomogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Cellulose - 20% Fiberglass - 2% Other - 78%
Lab ID #: 89058 - 07a Cust. #: HP-2-6 Material: Joint Compound Location: Appearance: while,nonfibrous,homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Odher - 100%
Lab ID #: 80058 - 08 Cust. #: HP-2-7 Material: Dyyvall Location: Appearance: beige,fibrous,nonhomogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Cellulose - 20% Fiberglass - 2% Other - 78%

For Layered Samples, each component will be analyzed and reported separately.

Kut ft T. Let

Teal MADA (2010) 2011 (A sound to analyze the above samples. Match is indications and/or read-fair leads to any fair MADA (and fair leads to any fair MADA) and the above samples of the above samples

HTVLAD NVLAP Lab Code 102118-0

APEX Research Inc., 11054 Hi Tech Drive, Whitmore Lake, MI 48189 (734) 449-9990, Fax (734) 449-9991

Page 5 of 6

KTVLAD NVLAP Lab Code 102118-0

APEX Research Inc., 11054 Hi Tech Drive, Whitmore Lake, MI 48189 (734) 449-9990, Fax (734) 449-9991

Paga 6 of 6

### Certificate of Laboratory Analysis Test Method, Polarized Light Microscopy (PLM) Project : GRPS- Horizon Park & Briggs



Report To:	ARI Report #	20-89058
Mr. Chris Decker	Date Collected:	02/21/20
dicroAir Consulting	Date Received:	02/28/20
O. Box 908	Date Analyzed:	02/28/20
Freenville, MI 48838	Date Reported:	03/02/20

Sample Information	Asbestos Type/Percent	Non-Asbestos Material
Lab ID #: 89058-08a Cust #: HP-2-7 Material: Joint Compound Location: Appearance: white nonfibrous homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: X0HKSKOZOX Cust. #: 2000X Material: 2000Xg Location: Appearance: 2000C205000C000000000 Layer; X of X	Asbestos Present: <b>X10</b> No Asbestos Observed	Fiberglass - XXX Other - XXX
Lab ID #: Cust. #: Material: Location: Appearance: Layer: of	Asbestos Present:	

For Layered Samples, each component will be analyzed and reported separately

Ret Jeff Robert T. Letarte Jr., Laboratory Director

Tot Mehol EFA 600749/116 was used to analyze the above samples. Matix intraference and/or resolution limits may yield fides/negative meth in costain circumstances. Support floor tides costaining 9/3, should be total with SEM or TEM. This confidence of analysis relates only to the analyst in state and to incure the integrity of the results, may only be reproduced in fif. This confident must relate used by the custores to the important emportance of any state many test and and to incure the integrity of the results, may only be reproduced in fif. This confident must relate used by the custores to the important emportant emportant dependence of the product of the first state of the sources of the results for layered samples or samples or samples and the integrity in the first state of the sources of the results for layered samples or samples or samples or samples for the sources of the results for layered samples or samples January 25<sup>th</sup>, 2019 Project Number: MA-158-18 – **Updated September 18, 2019** 

Mr. Marc Bennett Grand Rapids Public Schools 900 Union, NE Grand Rapids, MI 49503

Re: AHERA 3 Year Reinspection Report Grand Rapids Public Schools – Union High School Consulting, LLC 119 West Cass Street P.O. Box 908 Greenville, MI 48838 Phone: 616-302-0819 Web: microairconsulting.com Email: microairconsulting@gmail.com

Dear Mr. Bennett:

MicroAir Consulting, LLC (MicroAir) was retained by Grand Rapids Public Schools (GRPS), to conduct an AHERA 3-year reinspection of Union High School (UHS) located at 1800 Tremont NW in Grand Rapids, Michigan. The inspection was conducted according to the protocol described in the U.S. Environmental Protection Agency Asbestos Hazard Emergency Response Act of 1986 (40 CFR 763).

### CERTIFICATION

The building inspection was conducted on December 24<sup>th</sup>, 2018 and updated with bulk sampling in January 2019. Mr. Grant Edgerly is a State of Michigan accredited Asbestos Building Inspector. Mr. Edgerly's, Accreditation Number is A41792.

### **REGULATORY BACKGROUND**

As a public and commercial building, UHS is governed by 29 CFR 1910.1001, Occupational Health Standards for Asbestos in Construction/General Industry and the EPA's NESHAP for the normal course of business activities by GRPS employees and occupants.

There are three state agencies in Michigan that regulate asbestos in Michigan: the Michigan Department of Environmental Quality (DEQ), the Michigan Department of Licensing and Regulatory Affairs (DLARA) and the Michigan Department of State Police (MSP). The DEQ is concerned about the release of asbestos fibers to the outer air and proper waste disposal, while DLARA focuses on worker protection during renovation and demolition activities, contractor licensing, and worker training.

During construction or renovation activities, the persons performing those activities would be governed by 29 CFR 1926.1101, Occupational Health Standards for Asbestos in Construction. The Asbestos Hazard Emergency Response Act (AHERA), 40 CFR 763, (partial) and/or its associated requirements. However, there are some portions of AHERA that are used as guidelines for compliance with 29 CFR 1910.1001. In particular, 29 CFR 1910.1001(j)(1) requires owners of buildings constructed prior to 1980 to presume that certain types of building materials are asbestos-containing materials (ACM), unless the owner demonstrates that those materials are not ACM.

40 CFR Part 61, Subpart M (NESHAP) requires that a thorough inspection be conducted prior to all renovations and all demolitions. A thorough inspection for asbestos is required no matter the age of the facility because all uses of asbestos are not banned. The inspection must be completed before the commencement of a subject renovation and/or demolition activity.

### **BUILDING DESCRIPTION**

The Union High School is a two-story building constructed in 1967 with an additions in 1980 and 2005. The building is approximately 200,000 square feet in size. Since its construction, the building has undergone various renovations.

### PREVIOUS INSPECTION

The most recent inspection was conducted by GRPS in 2018. MicroAir reviewed this report and incorporated the findings of the previous inspection and historical information into the current reinspection data.

In the previous inspection report suspect ACM materials were given a unique identification number (homogeneous material number), MicroAir has changed numbering from previous reports. The reinspection did include the collection of bulk samples. Results of the sampling can be found in Appendix A along with locations of remaining ACM in the building.

### **REINSPECTION PROCEDURES**



With the assistance of GRPS maintenance staff, MicroAir re-inspected known and previously identified areas of the building including above suspended ceilings, pipe chases, and inside the tunnels.

It was beyond the scope of this reinspection to locate, identify, or quantify ACM in areas that were concealed and/or inaccessible areas, such as within walls, hard ceilings, or equipment.

### **2019 REINSPECTION FINDINGS**

The following suspect asbestos-containing materials were observed at Union High School during the asbestos inspection and the bulk sampling. Materials in **bold** were found to be greater than 1% ACM.

- Pool ceiling plaster
- Roof louver caulking
- Textured wall plaster
- Smooth plaster
- Black lab counter tops
- Transite
- Tank insulation
- Mudded fittings on fiberglass lines
- Mudded roof drains
- Ceramic grout
- 9"x9" Floor Tile and mastic
- 12"x12" Floor Tile and mastic
- 1'x1' ceiling tile textured w/holes and glue pods
- Block mortar
- Brick mortar
- 2'x2' drop ceiling tile textured w/holes
- 2'x2' drop ceiling tile w/holes
- Ceiling texture
- Stage floor underlayment
- Vibration dampener
- Boiler breeching
- Boiler materials
- Fire doors
- Concrete
- Sealants
- Roofing materials
- Sink undercoating
- Gym flooring undercoating
- Vibration dampener
- Boiler door mud
- Wood floor mastic
- Boiler gasket
- Boiler door gasket
- Rear boiler gasket
- Window glazing (boiler room windows)
- Office spray-on
- Wall board pod
- Fiberglass duct lining
- Aluminum framed windows (glazing)
- 2'x4' Ceiling tile
- Black floor mastic
- Boiler room roofing

Some of the materials listed above are assumed to contain asbestos until bulk samples can be collected and analyzed.

Appendix A of this report is a table that identifies the confirmed and suspect ACM homogeneous materials in UHS, their corresponding identification number and locations, and the general condition of ACMs identified during the reinspection.



### CONCLUSIONS AND RECOMMENDATIONS

MicroAir was retained by Grand Rapids Public Schools to conduct a 3-year asbestos-containing material (ACM) reinspection of Union High School located at 1800 Tremont NW in Grand Rapids, Michigan. MicroAir completed the reinspection on December 24<sup>th</sup>, 2018. The inspection was conducted by a State of Michigan accredited Asbestos Building Inspector.

Since 2017, the floor tile and mastic has been removed from Rooms 123, 139, 141, 160, 172, 173, 183, 203, 204, 209, 211, 216, 218, 231, 233 and 235.

Any personnel entering a tunnel or chase area must be notified of ACM locations and explained the requirement to wear personal protective equipment.

If GRPS plans to conduct any renovation or demolition, the identified ACMs should be removed by a licensed asbestos abatement contractor, as required by current federal, state, and local laws and regulations, should perform any necessary removal and disposal of the identified ACM. MicroAir notes that if suspect ACM other than those identified during this reinspection are encountered during any renovation or demolition, such materials should be sampled and analyzed using PLM to verify presence of asbestos.

We also recommend that visual observations, verification of removal and cleanup, and air monitoring or clearance air monitoring for asbestos fibers be performed by a third party retained by GRPS to demonstrate compliance with applicable regulations, and to confirm the suitability or the area for re-entry. MicroAir can perform these services.

Warning labels should be affixed in all non-public areas where ACM or assumed ACM is present. After completion of repairs or removal of the ACM, fill out an O&M Activities Form and file it in the management plan.

As required by AHERA, GRPS should continue to send the annual notifications including information on planned response actions and reinspections. Copies of the notifications should be kept in the Management Plan.

### LIMITATIONS

The conclusions drawn from the observations and sample results are only valid for the time the observations occurred. In the process of gathering the field data included in this report, procedures were followed that represent reasonable and acceptable industrial hygiene practices and procedures in a manner consistent with the level of care and skill ordinarily exercised by other members of this profession currently practicing under similar conditions. However, the information and opinions provided in this report are not to be construed as a warranty of the conditions of this site in any way, implied or explicit. MicroAir accepts no responsibility for the use, interpretation, or reliance by other parties on the information contained herein, nor does this report represent an instrument of regulatory compliance or an asbestos abatement specification.

In conducting the reinspection there are a number of obstacles and limitations that can affect the final outcome of the report. These limitations include but are not limited to the following factors: access concerns, materials that cannot be intrusively sampled or damaged, materials that have been replaced by renovation activities, materials with conflicting laboratory results, and materials that are located in inaccessible and/or concealed areas which limits its quantification. Due to these limitations, the results of this investigation cannot be construed as a certification of the presence or absence of ACM, beyond the materials identified, but rather a diligent and prudent review of available data within an established work scope, and time and budgetary constraints.

If you have any questions or require additional information, please contact me at 616-302-0819 or microairconsulting@gmail.com. Thank you.

Sincerely,

**MicroAir Consulting, LLC** 

nisten T. Decker

Christian T. Decker Accredited Building Inspector and Management Planner

### **APPENDIX A**

### TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIAL

Air Project No. MA-158-18

Page 5 of 10

localized area

**<u>CONDITION</u>:** Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a

SF: Square feet LF: Linear feet FT: Fittings NQ: Not Quantified

APPENDIX TESTED AN UNION HIG	A – 3-YEAR REINSPECTIONS D SUSPECT ASBESTOS-CONTAINII iH SCHOOL iN DATE: AUGUST 12-30, 2019	NG MATERIALS 19	67 BUILDI.	NG		Consu
HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITI
U-2	Roof louver caulking	No	MM	1	Roof	1
U-4	Smooth plaster	No	MS	I	Interior walls and ceilings	
U-2	Black lab counter tops	Yes	MM	NF-II	Rooms 150, 152, 153, 155, 156, 158, 160 and 161	Good
0-6	Transite	Yes	MM	NF-II	Room 119 on north wall, 120 on east and west walls, 174, 174A and Greenhouse growing tables	Good
U-7	Tank insulation	Yes	TSI	п	Boiler room and pool mechanical room on hot water storage tanks	Good
U-8	Mudded fittings on fiberglass lines	Yes	TSI	п	All tunnels; Boiler room; Above all ceilings on 1 <sup>st</sup> floor, locker rooms, hallways, 99A and pool mechanical rooms. Rooms 3, 3A, 4, 6, 9, 10, 29, 31, 39, 40, 45, 54A, 100, 114, 116B, 118, 119E, 124, 138, 144, 175C, 178, 182 in pit, 220 and 226	Good
0-9	Mudded roof drains	Yes	TSI	п	All roof drains including 145A and mechanical room	Good
U-10	Ceramic grout	No	MM	1	Restrooms	
U-11 U-12	Floor tile w/mastic Both sizes 9"x9" and 12"x12"	Yes Tile and Mastic	MM	NF-I	Most hallways and not previously abated classrooms.	Good
U-13	1'x1' ceiling tile textured w/holes and glue pods	No	MM	I	Rooms 122, 122A, 122B, 122C, 122D, 122E and Corridor 199D	1
U-14	Block mortar	No	MM	I	All cinderblock walls	1
U-15	Brick mortar	No	MM	1	All brick walls	1
U-16	2'x2' drop ceiling tile textured w/holes	No	MM	1	Classrooms	1
U-17	2'x2' drop ceiling tile w/holes	No	MM	1	Possible around wall heater units	



F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II

MATERIAL TYPE: TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

sulting, LLC

0	1
9	
ISI	$\leq 1$
E	
n n	
Ē	
C	

<b>IX A – 3-YEAR REINSPECTIONS AND SUSPECT ASBESTOS-CONTAIN HIGH SCHOOL TION DATE: AUGUST 12-30, 2019</b>
---

TNSPEC	TTON DATE: AUGUST 12-30, 2019	1	967 BUILDI	NG		Constituing,
HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
U-20	Vibration dampener	No	MM	ι	HVAC equipment and ductwork	
U-21	Boiler breeching	Yes	TSI	п	Boiler exhaust	Good
U-22	Boiler materials	Assumed (not sampled)	TSI	F	Inside boiler	Good
U-23	Fire doors	Yes	MM	NF-II	All tagged fire doors	Good
U-24	Concrete	No	MM	l	All concrete	
U-25	Sealants	No	MM	I	All original caulk	,
U-26	Roofing materials	No	MM	ι	Exterior roof	1
U-27 & U-27B	Sink undercoating – Purple and Grey	No	MM	I	Under metal sinks	
U-29	Vibration dampener	No	TSI	l	Boiler Room	ı
U-30	Boiler door mud	Yes	TSI	NF-II	Boiler Room	Good
U-31	Wood floor mastic	Yes	MM	NE-I	Room 182 (Removed in 2019)	Good
U-32	Boiler gasket	Yes	MM	NF-II	Boiler Room	Good
U-33	Boiler door gasket	No	MM	l	Boiler Room	
U-34	Rear boiler gasket	No	MM	l	Boiler Room	
U-35	Window caulking (boiler windows)	Yes	ММ	NF-II	Boiler Room (Removed in 2019)	1

FRIABILITY: F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II MATERIAL TYPE: TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

SF: Square feet LF: Linear feet FT: Fittings NQ: Not Quantified

**CONDITION:** Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

Air Project No. MA-158-18

Page 6 of 10

 $\bigcirc$ 

 $\bigcirc$ 

Consulting, LLC	

# APPENDIX A – 3-YEAR REINSPECTIONS TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS UNION HIGH SCHOOL TNCDECTTON DATE: AUGUST 12-30. 2019

the state of the s	INSPECTIO	N DATE: AUGUST 12-30, 2019	1	967 BUILDI	NG		
	HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
	U-36	Office spray-on insulation	No	MS	1	Office area	-
	U-37	Wall board pod	No	MM	I	Hallways and classrooms	1
	U-38	Fiberglass duct lining	No	MM	I	Duct work throughout	I
	U-39	Roofing	No	MM	ł	Exterior roof	1
	U-40	Aluminum framed windows glazing	Yes	MM	NE-II	Hallways, classrooms, and offices	Good
	U-44	2'x4' Ceiling tile	No	MM	I	Hallways, classrooms, and offices	ł
	U-45	Black floor mastic	No	MM	1	Under wood floors	I
	U-46	Boiler room roofing	No	MM	I	Exterior boiler room	I

### FRIABILITY:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II

## MATERIAL TYPE: TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

SF: Square feet LF: Linear feet FT: Fittings NQ: Not Quantified

**CONDITION:** Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

DAir Project No. MA-158-18

Page 7 of 10

Page 8 of 10

 $\bigcirc$ 

MAir Project No. MA-158-18

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II

FRIABILITY:

SF: Square feet LF: Linear feet

FT: Fittings NQ: Not Quantified

**MATERIAL TYPE:** TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

**CONDITION:** Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

Z	SPECTIO	N DATE: AUGUST 12-30, 2019	19	80 BUILDI	VG		
	HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
T	Ŀ.	Pool ceiling plaster	No	MS	1	Pool area	I
T	U-2B	Roof louver caulking	No	MM	I	Roof	1
T	u-3	Textured wall plaster	No	MS	I	Pool mechanical room	ı
T	U-4B	Smooth plaster	No	MS	T	Interior walls and ceilings	1
	U-7B	Tank insulation	Yes	TSI	п	Boiler room and pool mechanical room on hot water storage tanks	Good
	U-8B	Mudded fittings on fiberglass lines	Yes	TSI	п	All tunnels; Boiler room; Above all ceilings on 1 <sup>st</sup> floor, locker rooms, hallways, 99A and pool mechanical rooms. Rooms 3, 3A, 4, 6, 9, 10, 29, 31, 39, 40, 45, 54A, 100, 114, 116B, 118, 119E, 124, 138, 144, 175C, 178, 182 in pit, 220 and 226	Good
1	U-9B	Mudded roof drains	Yes	TSI	п	All roof drains including 145A and mechanical room	Good
	U-10B	Ceramic grout	No	MM	I	Pool area, locker rooms and restrooms	
	U-14B	Block mortar	No	MM	1	All cinderblock walls	1
	U-15B	Brick mortar	Assumed	MM	NF-II	All brick walls	Good
I	U-16B	2'x2' drop ceiling tile textured w/holes	No	MM	1	Pool area	1
	U-18	Ceiling texture	Assumed (not sampled)	MS	п	Auditorium	Good
	U-19	Stage floor underlayment	Assumed (not sampled)	ММ	NE-I	Auditorium	Good
Т	U-20B	Vibration dampener	No	MM	I	HVAC equipment and ductwork	
1	U-23	Fire doors	Yes	MM	NF-II	All tagged fire doors	Good
-	U-24B	Concrete	No	MM	I	All concrete	ı



APPENDIX A - 3-YEAR REINSPECTIONS TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS UNION HIGH SCHOOL

Consulting, LLC	

# APPENDIX A - 3-YEAR REINSPECTIONS TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS UNION HIGH SCHOOL 1980 RIITI DING

INSPEC	ILUN DAIE: AUGUSI 12-30, 2019	1	TOTTOD DOTTOT	NG		
HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
U-25B	Sealants	No	MM	ł	All original caulk	1
U-26B	Roofing materials	Assumed	MM	NF-I	Roof	Good
U-28	Gym floor undercoating	No	MM	ı	Gym floors	1
U-40B	Aluminum framed windows glazing	No	MM	ı	Hallways, classrooms, and offices	1
U-41	Drywall, tape and mud	No	SM	I	Interior drywall areas	1
U-44	2'x4' Ceiling tile	No	MM	I	Hallways, classrooms, and offices	1
U-45	Black floor mastic	No	MM	ł	Under wood floors	1
<b>FRIABILITY</b> F: Friable NF-I: Non-fri NF-II: Non-fri	MATERIAL TYPE:       TSI: Thermal System       able Category I     SM: Surfacing Materia       Table Category II     MM: Miscellaneous Materia	Insulation G	<b>ONDITION:</b> lood: Little or no lamaged: Less t ignificantly Dam	o damage han 10% da aged: Greate	mage of total surface area, or less than 25% damage in a localized av r than 10% damage of total surface area, or greater than 25% dama	area age in a

bood: Little of ito damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

SF: Square feet LF: Linear feet FT: Fittings NQ: Not Quantified

Air Project No. MA-158-18

Page 9 of 10

This page has been left blank intentionally

Certificate of Laboratory Analysis Test Method, Polarized Light Microscopy (PLM) Project : GRPS- Union HS



Report To:		
Mr. Chris Deeker MicroAir Consulting P.O. Box 908 Greenville, MI 48838		ARI Report #     20-90987       Date Collected:     08/13/20       Date Received:     08/19/20       Date Analyzed:     08/21/20       Date Reported:     08/24/20
Sample Information	Asbestos Type/Percent	Non-Asbestos Material
Lab ID #: 90987 - 01 Cust. #: U-10B Materiai: Ceranic Grout Location: Appearance: grey, ponfibrous, homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 90987 - 02 Cust #: U-14B Materiai: Block Mortar Location: Appearance: grey_nonfibrous,homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 90987-03 Cust. #: U-158 Material: Brick Mortar Location: Appearance: grey.nonfibrous.homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Other - 100%
Layered Samples, each component will be analyzed and reported	separately.	
	14	at fitt
	Robert T. 1	Letarte Jr., Laboratory Director
Selbod EFA 600R-93/116 was used to analyze the above samples. Matrix: ning <15: shocd at tested with SEM or TEM. This certificate of analysis one mast not by used by the customer to slaim product certification, appro- nitile for the accuracy of the results for layered samples or samples compri- nitile for the accuracy of the results for layered samples or samples compri-	interforence and/or reaclation limits may yield fide/or relates cody to the samples tested and to insure the inf val, or endorsmannet by NYLAP, NATS, or any approx- sing multiple materials. Liability limited to cost of a	agative results in certain disconstanots. Suspect floor tiles againty of the results, may only be reproduced in full. This of the Foderal Government. APEX Research Ion. is not allysis.
Certificate Test Method, Pol Proje	of Laboratory Anal arized Light Microscop cct : GRPS- Union HS	lysis y (PLM)
Certificate Test Method, Pol Proje Report To: Mr. Chris Decker MicroAir Consuling P.O. Das 508 Greenville, MI 48838	of Laboratory Anal arized Light Microscop et : GRPS- Union HS	ARI Report # 20-90987 Date Collected: 08/13/20 Date Received: 08/19/20 Date Received: 08/19/20 Date Received: 08/21/20 Date Reported: 08/24/20
Certificate Test Method, Pol Proje Mr. Chris Deker Mircohir Comulting P.O. Box 908 Greenville, MI 48838 Sample Information	of Laboratory Anal arized Light Microscop bet : GRPS- Union HS Asbestos Type/Percent	ARI Report # 20-90987 Date Collected: 08/13/20 Date Analyzed: 08/21/20 Date Reported: 08/21/20 Date Analyzed: 08/21/20 Date Analyzed: 08/21/20 Date Analyzed: 08/21/20
Certificate Test Method, Pol Proje Mr. Chris Decker Mircohir Consulting P.O. Box 908 Greenville, MI 48838 Sample Information Lab ID #: 90987 - 07 Cust. #: U-23B Material: Sealants Location: Appearance: grey.confibrous,homogenous Layer: 1 of 1	of Laboratory Anal arized Light Microscop et : GRPS- Union HS <u>Asbestos Type/Percent</u> Asbestos Present: NO No Asbestos Observed	hysis by (PLM) ARI Report # 20-90987 Date Collected: 08/1320 Date Analyzed: 08/21/20 Date Reported: 08/24/20 Date Reported: 08/24/20 Date Reported: 08/24/20 Non-Asbestos Material Other - 100%
Certificate Test Method, Pol Proje Report To: Mr. Chris Desker Miscohir Comulting P.O. Box 908 Greenville, MI 48838 Sample Information Lab ID#: 90987 - 07 Cust. #: U-23B Material: Sealants Leoetion: Appearance: grey.nonfibrous.homogenous Layer: 1 of 1 Lab ID#: 90987 - 08 Cust. #: U-40B Material: Aluminum Window Glaze Location: Appearance: grey.nonfibrous.homogenous Layer: 1 of 1	of Laboratory Anal arized Light Microscop ext : GRPS- Union HS Asbestos Type/Percent Asbestos Present: NO No Asbestos Observed Asbestos Present: NO No Asbestos Observed	Nysis yr (PLM) Excert the second seco
Certificate Test Method, Pol Proje	of Laboratory Anal arized Light Microscop bet : GRPS- Union HS Asbestos Type/Percent Asbestos Present: NO No Asbestos Observed Asbestos Present: NO No Asbestos Observed Asbestos Present: NO No Asbestos Observed	ARI Report # 20-90987 Date Collected: 08/13/20 Date Collected: 08/21/20 Date Analyzed: 08/21/20 Date Analyzed: 08/21/20 Date Analyzed: 08/21/20 Date Analyzed: 08/21/20 Other - 100% Other - 100%
Certificate Test Method, Pol Proje	of Laboratory Anal arized Light Microscop bet : GRPS- Union HS Asbestos Type/Percent Asbestos Present: NO No Asbestos Observed Asbestos Present: NO No Asbestos Observed Asbestos Present: NO No Asbestos Observed	ARI Report # 20-90987 Date Collected: 08/13/20 Date Collected: 08/21/20 Date Analyzed: 08/21/20 Date Analyzed: 08/21/20 Date Analyzed: 08/21/20 Date Analyzed: 08/21/20 Other - 100% Other - 100%
Report To:   Mr. Chris Decker     Mr. Chris Decker   Miscohi Consulting     P.O. Box 508   Greenville, MI 48838     Sample Information   Identified and the second se	of Laboratory Anal arized Light Microscop bet : GRPS- Union HS Asbestos Type/Percent Asbestos Present: NO No Asbestos Observed Asbestos Present: NO No Asbestos Observed Asbestos Present: NO No Asbestos Observed Asbestos Observed	ARI Report # 20-90987 Date Collected: 08/13/20 Date Collected: 08/13/20 Date Analyzed: 08/21/20 Date A

Certificate of Laboratory Analysis Test Method, Polarized Light Microscopy (PLM) Project : GRPS- Union HS



Mr. Chris Decker MicroAir Consuling P.O. Box 908 Greenville, MI 48838		Date Collected: 08/13/2   Date Received: 08/19/2   Date Analyzed: 08/21/2   Date Reported: 08/24/2
Sample Information	Asbestos Type/Percent	Non-Asbestos Mate
Lab ID #: 90987 - 04 Cust. #: U-16B Material: 2x2 Celling Tile (Fiberglass) Location: Appearance: yellow,fibrous,nonhomogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Fiberglass - 65% Other - 35%
Lab ID #: 90987 - 05 Cust. #: U-20B Material: Vibration Dampener Location: Appearance: black,fibrous,nonhomogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Synthetie - 25% Other - 75%
Lab ID #: 90987-06 Cust. #: U-24B Material: Concrete Location: Appearance: grey,aonfibrous,homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Other - 100%
For Layered Samples, each component will be analyzed and report	ted separately.	
	14	at fift
	Robert T. 1	Letarte Jr., Laboratory Direc
RV신스위 APEX Research Ia	c., 11654 Hi Tech Drive, Whitmore Lake, MI 73-0, 449-2999, Fax (73-0, 449-5991	48189 Page
Certificat Test Method, Pro	<b>e of Laboratory Ana</b> l olarized Light Microscop ject : GRPS- Union HS	lysis y (PLM)
Certificat Test Method, Pro	e of Laboratory Anal olarized Light Microscop ject : GRPS- Union HS	lysis y (PLM)
Certificat Test Method, Pr Pro	<b>e of Laboratory Ana</b> l olarized Light Microscop ject : GRPS- Union HS	lysis by (PLM)
Certificat Test Method, Po Pro Report To: Mr. Chris Decker MicroAir Consulting	e of Laboratory Anal olarized Light Microscop ject : GRPS- Union HS	ARI Report # 20-909 Date Collected: 08/13/ Date Received: 08/13/
Certificat Test Method, Pa Pro Report To: Mr. Chris Decker MicroAir Consulting P.O. Bas 908 Greenville, MI 48838	e of Laboratory Anal olarized Light Microscop ject : GRPS- Union HS	ARI Report # 20-909 Date Collected: 08/13/ Date Received: 08/19/ Date Reported: 08/19/ Date Analyzed: 08/21/ Date Reported: 08/24/
Certificat Test Method, Pe Pro Report To: Mr. Chris Decker MicroAir Consulting P.O. Box 508 Greenville, MI 48838 Sample Information	e of Laboratory Anal olarized Light Microscop ject : GRPS- Union HS Asbestos Type/Percent	ARI Report # 20-909 Date Collected: 08/33/ Date Report=08/21/ Date Rep
Report To: Microal Consulting P.O. Box 908 Greenville, MI 48838 Sample Information	e of Laboratory Anal olarized Light Microscop ject : GRPS- Union HS <u>Asbestos Type/Percent</u>	Iysis by (PLM) ARI Report # 20-909 Date Collected: 08/13/ Date Reported: 08/21/ Date Analyzed: 08/21/ Date Analyzed: 08/21/ Date Analyzed: 08/21/ Date Analyzed: 08/21/ Date Analyzed: 08/21/ Date Reported: 08/21/ Date R
Certificat Test Method, Pe Pro Report To: Mrc.Chris Decker MicroAir Consulting P.O. Box 908 Greenville, MI 48838 Sample Information Lab ID #: 90987 - 09a Cust. #: U-41-1 Materiai: Plaster Finish Coat Location: Appearance: white,nonfibrus,homogenous Layer: 2 of 3	e of Laboratory Anal olarized Light Microscop ject : GRPS- Union HS <u>Asbestos Type/Percent</u> Asbestos Present: NO No Asbestos Observed	ysis by (PLM) ARI Report # 20-909 Date Collected: 08/13/ Date Recorted: 08/21/ Date Analyzed: 08/21/ Date A
Certificat Test Method, Po Pro Report To: Mr. Chris Decker MicroAir Consulting P:O. Box 908 Greenville, MI 48838 Sample Information Lab ID#: 90987 - 09a Cust. #: U-41-1 Material: Plaster Brish Cost Location: Appearance: while,nonfibrous, homogenous Layer: 2 of 3 Lab ID#: 90987 - 09b Cust. #: U-41-1 Material: Plaster Base Cost Location: Appearance: grey, nonfibrous, homogenous	e of Laboratory Anal olarized Light Microscop ject : GRPS- Union HS <u>Asbestos Type/Percent</u> Asbestos Present: NO No Asbestos Observed Asbestos Present: NO No Asbestos Observed	ARI Report # 20-909 Date Collected: 08/13/ Date Analyzed: 08/21/ Date Analyzed: 08/21/ Date Analyzed: 08/21/ Date Analyzed: 08/21/ Other - 100%
Certificat Test Method, P Test Method, P Pro Report To: Mr. Chris Decker MicroAir Consulting P.O. Box 908 Greenville, MI 48838 Sample Information Lab ID #: 90987 - 09a Cut. #: U-41-1 Material: Plaster Finish Coat Location: Appearance: while, nonfibrous, homogenous Location: Appearance: while, nonfibrous, homogenous Lab ID #: 90987 - 09b Cut. #: U-41-1 Material: Plaster Base Coat Location: Appearance: grey, nonfibrous, homogenous Layer: 3 of 3	e of Laboratory Anal olarized Light Microscop ject : GRPS- Union HS <u>Asbestos Type/Percent</u> Asbestos Present: NO No Asbestos Observed Asbestos Observed	by sis by (PLM) ARI Report # 20-909 Date Collected: 08/13/ Date Collected: 08/24/ Date Analyzed: 08/24/ Date Analyzed: 08/24/ Date Analyzed: 08/24/ Date Analyzed: 08/24/ Other - 100%
Certificat     Test Method, Pi     Test Method, Pi     Pro     MicroAir Consulting     P.O. Box 508   Greenville, MI 48838     Sample Information     Lab ID #: 90987 - 09a   Cast. #: U-41-1     Material: Plaster Finish Coat   Location:     Appearance: while, and fibrous, homogenous   Layer: 2 of 3     Lab ID #: 90987 - 10b   Cust. #: U-41-1     Material: Plaster Base Coat   Location:     Appearance: grey_nonfibrous_homogenous   Layer: 3 of 3     Lab ID #: 90987 - 10   Cust. #: U-41-2     Material: 1980 Drywall   Location:     Appearance: while, fibrous, nonhomogenous   Layer: 3 of 3	e of Laboratory Anal olarized Light Microscop ject : GRPS- Union HS <u>Asbestos Type/Percent</u> Asbestos Present: NO No Asbestos Observed Asbestos Present: NO No Asbestos Observed Asbestos Present: NO No Asbestos Observed	ARI Report # 20-909 Date Collection: 08/13/ Date Report # 20-909 Date Collection: 08/13/ Date Analyzed: 08/21/ Date Analyzed: 08/21/ Other - 100% Cellulose - 20% Fiberglass - 2% Other - 78%
Certificat Test Method, Pa Pro Report To: Mr. Chris Decker MicroAir Consulting P.O. Box 608 Greenville, MI 48838 Sample Information Lab ID#: 90987 - 09a Cust. #: U-41-1 Materiai: Plaster Enish Cost Location: Appearance: while, on fibrous, homogenous Layer: 2 of 3 Lab ID#: 90987 - 10 Cust. #: U-41-2 Materiai: Plaster Base Cost Location: Appearance: grey, nonfibrous, homogenous Layer: 3 of 3 Lab ID#: 90987 - 10 Cust. #: U-41-2 Materiai: 1980 Dryvall Location: Appearance: while, fibrous, nonhomogenous Layer: 1 of 1	e of Laboratory Anal olarized Light Microscop ject : GRPS- Union HS <u>Asbestos Type/Percent</u> Asbestos Present: NO No Asbestos Observed Asbestos Present: NO No Asbestos Observed	lysis (PLM) Constant ARI Report # 20-909 Dule Collected 08/13/ Dute Reported: 08/19/ Dute Reported: 08/24/ Dute Reported: 08/24/ Non-Asbestos Mate Other - 100% Other - 100% Cellulose - 20% Fiberglass - 2% Other - 78%
Certificat Test Method, Pe Test Method, Pe Pro Report To: Mrc Chris Decker MicroAir Consulting P.O. Box 908 Greenville, MI 48838 Sample Information Lab ID #: 90987 - 09a Cust. #: U-41-1 Material: Plaster Finish Coat Location: Appearance: while,nonfibrous,homogenous Layer: 2 of 3 Lab ID #: 90987 - 09b Cust. #: U-41-1 Material: Plaster Base Coat Location: Appearance: grey,nonfibrous,homogenous Layer: 3 of 3 Lab ID #: 90987 - 10 Cust. #: U-41-2 Material: 1980 Drywall Location: Appearance: while,fibrous,nonhomogenous Layer: 1 of 1 Fer Layered Samples, each component will be mslyzed and rep	e of Laboratory Anal olarized Light Microscop ject : GRPS- Union HS Asbestos Type/Percent Asbestos Present: NO No Asbestos Observed Asbestos Present: NO No Asbestos Observed Asbestos Present: NO No Asbestos Observed	ARI Report # 20-909 Dute Collected: 08/13/ Dute Record: 08/21/ Date Analyzed: 08/21/ Date Analyzed: 08/21/ Date Analyzed: 08/21/ Date Analyzed: 08/21/ Other - 100% Other - 100% Collected: 08/21/ Other - 100%
Certificat     Test Method, Perest     Test Method, Perest     Metodir Consulting     P.O. Box 908     Greenville, MI 48838     Sample Information     Lab ID #: 90987 - 09a     Cust. #: U-41-1     Material: Plaster Finish Coat     Location:     Appearance: while, nonfibrous, homogenous     Layer: 2 of 3     Lab ID #: 90987 - 09b     Cust. #: U-41-1     Material: Plaster Ense Coat     Location:     Appearance: grey, nonfibrous, homogenous     Layer: 3 of 3     Lab ID #: 90987-10     Cust. #: U-41-2     Material: 1980 Dynvall     Leation:     Appearance: while, fibrous, nonhomogenous     Layer: 1 of 1     Starter 1 set 1980 Dynvall     Leation:     Appearance: while, fibrous, nonhomogenous     Layer: 1 of 1     Starter 1 set 10     Material: 1980 Dynvall     Leation:     Appearance: while, fibrous, nonhomogenous     Layer: 1 of 1     Fer Layerd Samples, each component will be analyzed and repression <td>e of Laboratory Anal plarized Light Microscop ject : GRPS- Union HS <u>Asbestos Type/Percent</u> <u>Asbestos Present: NO</u> No Asbestos Observed <u>Asbestos Present: NO</u> No Asbestos Observed <u>Asbestos Present: NO</u> No Asbestos Observed <u>Asbestos Observed</u> <u>Asbestos Observed</u></td> <td>ARI Report # 20-909 Date Collected: 08/13/ Date Report # 20-909 Date Collected: 08/13/ Date Report # 08/13/ Date Analyzed: 08/21/ Date Analyzed: 08/21/ Da</td>	e of Laboratory Anal plarized Light Microscop ject : GRPS- Union HS <u>Asbestos Type/Percent</u> <u>Asbestos Present: NO</u> No Asbestos Observed <u>Asbestos Present: NO</u> No Asbestos Observed <u>Asbestos Present: NO</u> No Asbestos Observed <u>Asbestos Observed</u> <u>Asbestos Observed</u>	ARI Report # 20-909 Date Collected: 08/13/ Date Report # 20-909 Date Collected: 08/13/ Date Report # 08/13/ Date Analyzed: 08/21/ Date Analyzed: 08/21/ Da
Certificat Test Method, P Test Method, P Pro Report To: Mr. Chris Decker MicroAir Consulting P.O. Box 908 Greenville, MI 48838 Sample Information Lab ID #: 90987-09a Cust. #: U-41-1 Materiai: Plaster Finish Coat Location: Appearance: while, nonfibrous, homogenous Layer: 2 of 3 Lab ID #: 90987-09b Cust. #: U-41-1 Materiai: Plaster Base Coat Location: Appearance: grey, nonfibrous, homogenous Layer: 3 of 3 Lab ID #: 90987-10 Cust. #: U-41-2 Materiai: 1980 Drywall Location: Appearance: while, fibrous, nonhomogenous Layer: 1 of 1 Zer Layerd Samples, each component will be analyzed and rep	e of Laboratory Anal olarized Light Microscop ject : GRPS- Union HS <u>Asbestos Type/Percent</u> Asbestos Present: NO No Asbestos Observed Asbestos Present: NO No Asbestos Observed Asbestos Observed Asbestos Observed Asbestos Observed	ARI Report # 20-909 Date Collected: 08/13/ Date Report # 20-909 Date Collected: 08/13/ Date Report # 08/21/ Date Report # 08/21/ Other - 100% Cellulose - 20% Fiberglass - 2% Other - 78%

NVLAP Lab Code 102118-0

KY (A) NVLAP LAD Code 102118-0

APEX Research Inc., 11054 HI Tech Drive, Whitmore Lake, MI 48189 (734) 449-9990, Fax (734) 449-9991

Page 4 of 6

**Certificate of Laboratory Analysis** Test Method, Polarized Light Microscopy (PLM) Project : GRPS- Union HS



Report To: Mr. Chris Decker MicroAir Consulling P.O. Box 908 Greenville, MI 48838		ARI Report # 20-90987   Date Collected: 08/13/20   Date Received: 08/19/20   Date Analyzed: 08/21/20   Date Reported: 08/24/20
Sample Information	Asbestos Type/Percent	Non-Asbestos Material
Lab ID #: 90987 - 11 Cust. #: U-41-3 Material: 1980 Drywall Location: Appearance: white,fibrous,nonhomogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Cellulose - 20% Fiberglass - 2% Other - 78%
Lab ID #: 90987 - 12 Cust #: U-41-4 Material: 1980 Drywall Location: Appearance: white,fibrous,nonhomogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Cellulose - 20% Fiberglass - 2% Other - 78%
Lab ID #: 90987 - 13 Cust #: H-41-5 Material: 1980 Dywall Location: Appearance: white,fibrous,nonhomogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Cellulose - 20% Fiberglass - 2% Other - 78%

Fo

.10 T Letar Directo

EFA 600 R-93/116 was used to analyze the above : with SEM or TEM. This certif dl. This tes tested and to many agence NVLAP, NIST, or any agence y of the e repro

(KTV(AQ) NVLAP Lab Code 102118-0

APEX Research Inc., 11054 Hi Tech Drive, Whitmore Lake, MI 48189 (734) 449-9990, Fax (734) 449-9991

Page 5 of 6

Certificate of Laboratory Analysis Test Method, Polarized Light Microscopy (PLM) Project : GRPS- Union HS



Report To: Mr. Chris Decker MicroAir Consuling P.O. Bax 908 Greenville, MI 48838		ARI Report #20-90987Date Collected:08/13/20Date Received:08/19/20Date Analyzed:08/21/20Date Reported:08/24/20
Sample Information	Asbestos Type/Percent	Non-Asbestos Material
Lab ID #: 90987 - 14 Cust. #: H-41-6 Material: 1980 Drywall Location: Appearance: white,fibrous,nonhomogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Cellulose - 20% Fiberglass - 2% Other - 78%
Lab ID #: 90987 - 15 Cust #: H-41-7 Material: 1980 Drywall Location: Appearance: white,fibrous,nonhomogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Cellulose - 20% Fiberglass - 2% Other - 78%
Lab ID #: Cust. #: Material: Location: Appearance: Layer: of	Asbestos Present:	

For Layered Samples, each co nt will be analyzed and reported sep chy

Rut Jett Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above containing <1% should be tested with SEM or TEM. This cert s relates only to the wal, or endorser-ising r-\* in full. This must not be used by for the accuracy of AFEX Res certifica response mples tested and to more the megnty by NVLAP, NIST, or any agency of the ids. Liability limited to cost of analysis

KTV (AQ) NVLAP Lab Code 102118-0

APEX Research Inc., 11054 HI Tech Drive, Whitmore Lake, MI 48189 (734) 449-9990, Fax (734) 449-9991

Page 6 of 6
# GRPS Asbestos 6-Month Surveillance Form

The reinspection was performed based on the requirements outlined in Asbestos Hazard Emergency Response Act (AHERA), EPA 40CFR, Part 763.85, Section (b), titled "Re-Inspection" for school buildings. The initial inspection was conducted 1988. MicroAir Consulting, LLC reviewed GRPS's management plan and incorporated the findings of the previous reinspections and historical information into the current management plan.

# School Building Name: Union High School

# **Tested Building Materials Containing Asbestos:**

1967, 1980 Tagged Fire Doors and Frames 1967 Black Lab Counter Tops 1967 Transite 1967 Tank Insulation (Boiler and Pool Mechanical Areas) 1967 Mudded Fittings on Fiberglass Lines 1967 Mudded Roof Drains 1967 12"X12" Floor Tile and Mastic 1967 9"x9" Floor Tile and Mastic 1967 Aluminum Framed Window Glazing 1980 Tank Insulation 1980 Mudded Fittings on Fiberglass Lines 1980 Mudded Roof Drains

Date(s): January 1, 2020 / July 6, 2020 Condition of Tested/Assumed Materials: No Change in Materials

Additional Notes:

**1967 Boiler Room Materials were Removed in 2019/2020 1967 Wood Floor Mastic in Room 182 was removed in 2019** 

1967 Chalkboards tested negative

Signature: Chris Decker

Date: 02/01/2020 + 7/30/20

MicroAir Consulting, LLC (616-302-0819) October 31<sup>st</sup>, 2019 Project Number: MA-117-19

Mr. Marc Bennett Grand Rapids Public Schools 900 Union, NE Grand Rapids, MI 49503

Re: AHERA 3 Year Reinspection Report Grand Rapids Public Schools – Congress Elementary School

Dear Mr. Bennett:



119 West Cass Street P.O. Box 908 Grand Rapids, MI 48838 Phone: 616-302-0819 Web: microairconsulting.com Email: microairconsulting@gmail.com

MicroAir Consulting, LLC (MicroAir) was retained by Grand Rapids Public Schools (GRPS), to conduct an AHERA 3-year reinspection of Congress Elementary School located at 940 Baldwin Street SE in Grand Rapids, Michigan. The inspection was conducted according to the protocol described in the U.S. Environmental Protection Agency Asbestos Hazard Emergency Response Act of 1986 (40 CFR 763).

# CERTIFICATION

The building inspection was conducted on October 14<sup>th</sup>, 2019 by Mr. Ryan Emmons, a State of Michigan accredited Asbestos Building Inspector. Mr. Emmons's, Accreditation Number is A55220.

## **REGULATORY BACKGROUND**

As a public and commercial building, Congress is governed by 29 CFR 1910.1001, Occupational Health Standards for Asbestos in Construction/General Industry and the EPA's NESHAP for the normal course of business activities by GRPS employees and occupants.

There are three state agencies in Michigan that regulate asbestos in Michigan: the Michigan Department of Environmental Quality (DEQ), the Michigan Department of Licensing and Regulatory Affairs (DLARA) and the Michigan Department of State Police (MSP). The DEQ is concerned about the release of asbestos fibers to the outer air and proper waste disposal, while DLARA focuses on worker protection during renovation and demolition activities, contractor licensing, and worker training.

During construction or renovation activities, the persons performing those activities would be governed by 29 CFR 1926.1101, Occupational Health Standards for Asbestos in Construction. The Asbestos Hazard Emergency Response Act (AHERA), 40 CFR 763, (partial) and/or its associated requirements. However, there are some portions of AHERA that are used as guidelines for compliance with 29 CFR 1910.1001. In particular, 29 CFR 1910.1001(j)(1) requires owners of buildings constructed prior to 1980 to presume that certain types of building materials are asbestos-containing materials (ACM), unless the owner demonstrates that those materials are not ACM.

40 CFR Part 61, Subpart M (NESHAP) requires that a thorough inspection be conducted prior to all renovations and all demolitions. A thorough inspection for asbestos is required no matter the age of the facility because all uses of asbestos are not banned. The inspection must be completed before the commencement of a subject renovation and/or demolition activity.

### **BUILDING DESCRIPTION**

The Congress Elementary School building was constructed in 1920. Some building renovations have occurred throughout over the years as well.

### **PREVIOUS INSPECTION**

The most recent inspection was conducted by GRPS. MicroAir reviewed this report and incorporated the findings of the previous inspection and historical information into the current reinspection data.

In the previous inspection report suspect ACM materials were given a unique identification number (homogeneous material number), MicroAir has changed numbering from previous reports. The reinspection did include the collection of bulk samples. Results of the sampling can be found in Appendix A along with locations of remaining ACM in the building.

# **REINSPECTION PROCEDURES**

With the assistance of GRPS maintenance staff, MicroAir re-inspected known and previously identified areas of the building including above suspended ceilings, pipe chases, and inside the tunnels.



It was beyond the scope of this reinspection to locate, identify, or quantify ACM in areas that were concealed and/or inaccessible areas, such as within walls, hard ceilings, or equipment.

## **2019 REINSPECTION FINDINGS**

The following suspect asbestos-containing materials were observed at Congress Elementary School during the asbestos inspection and the bulk sampling. Materials in **bold** were found to be greater than 1% ACM.

- Vinyl stair tread
- Plaster
- 1'x1' ceiling tiles
- 12"x12" Green floor tile w/mastic
- Brick mortar
- Concrete
- Fire doors and frames
- Ceramic grout
- Wood floor underlayment
- 12"x12" Tan floor tile w/mastic
- 12"x12" Black floor tile w/mastic
- Older chalkboards
- 2'x2' ceiling tile w/holes and fissures
- Sink undercoating
- 2'x2' ceiling tile w/holes
- 2'x2' ceiling tile smooth
- Drywall, tape and mud
- Blue cove base w/mastic
- Black cove base w/mastic
- 12"x12" Multi-colored floor tile w/mastic
- 2'x2' ceiling tile w/pins and fissures
- 12"x12" Creme floor tile w/mastic
- Brown cove base w/mastic
- EIFS
- Decorative concrete
- Block mortar

Some of the materials listed above are assumed to contain asbestos until bulk samples can be collected and analyzed.

Appendix A of this report is a table that identifies the confirmed and suspect ACM homogeneous materials in Congress, their corresponding identification number and locations, and the general condition of ACMs identified during the reinspection.

# CONCLUSIONS AND RECOMMENDATIONS

MicroAir was retained by Grand Rapids Public Schools to conduct a 3-year asbestos-containing material (ACM) reinspection of Congress Elementary School located at 940 Baldwin Street SE in Grand Rapids, Michigan. MicroAir completed the reinspection on October 14<sup>th</sup>, 2019. The inspection was conducted by a State of Michigan accredited Asbestos Building Inspector.

During the reinspection, MicroAir identified and assessed 26 homogeneous materials remaining in Congress Elementary School.

Any personnel entering a tunnel or chase area must be notified of ACM locations and explained the requirement to wear personal protective equipment.

If GRPS plans to conduct any renovation or demolition, the identified ACMs should be removed by a licensed asbestos abatement contractor, as required by current federal, state, and local laws and regulations, should perform any necessary removal and disposal of the identified ACM. MicroAir notes that if suspect ACM other than those identified during this reinspection are encountered during any renovation or demolition, such materials should be sampled and analyzed using PLM to verify presence of Consulting, LLC asbestos.



We also recommend that visual observations, verification of removal and cleanup, and air monitoring or clearance air monitoring for asbestos fibers be performed by a third party retained by GRPS to demonstrate compliance with applicable regulations, and to confirm the suitability or the area for re-entry. MicroAir can perform these services.

Warning labels should be affixed in all non-public areas where ACM or assumed ACM is present. After completion of repairs or removal of the ACM, fill out an O&M Activities Form and file it in the management plan.

As required by AHERA, GRPS should continue to send the annual notifications including information on planned response actions and reinspections. Copies of the notifications should be kept in the Management Plan.

# LIMITATIONS

The conclusions drawn from the observations and sample results are only valid for the time the observations occurred. In the process of gathering the field data included in this report, procedures were followed that represent reasonable and acceptable industrial hygiene practices and procedures in a manner consistent with the level of care and skill ordinarily exercised by other members of this profession currently practicing under similar conditions. However, the information and opinions provided in this report are not to be construed as a warranty of the conditions of this site in any way, implied or explicit. MicroAir accepts no responsibility for the use, interpretation, or reliance by other parties on the information contained herein, nor does this report represent an instrument of regulatory compliance or an asbestos abatement specification.

In conducting the reinspection there are a number of obstacles and limitations that can affect the final outcome of the report. These limitations include but are not limited to the following factors: access concerns, materials that can not be intrusively sampled or damaged, materials that have been replaced by renovation activities, materials with conflicting laboratory results, and materials that are located in inaccessible and/or concealed areas which limits its quantification. Due to these limitations, the results of this investigation cannot be construed as a certification of the presence or absence of ACM, beyond the materials identified, but rather a diligent and prudent review of available data within an established work scope, and time and budgetary constraints.

If you have any questions or require additional information, please contact me at 616-302-0819 or microairconsulting@gmail.com.

Sincerely,

**MicroAir Consulting, LLC** 

uten T. Deeker

Christian T. Decker Accredited Building Inspector and Management Planner

# **APPENDIX A**

# TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS

# APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS CONGRESS ELEMENTARY SCHOOL INSPECTION DATE: OCTOBER 13<sup>th</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
CES-1	Vinyl stair tread	Assumed	MM	NF-I	Entrance stairway	Good
CES-2	Plaster	Yes	SM	F	Interior walls and ceilings	Good
CES-3	1'x1' ceiling tiles	Assumed	MM	NF-II	Interior ceilings	Good
CES-4	12"x12" Green floor tile w/mastic	Assumed	ММ	NF-I	Classrooms	Good
CES-5	Brick mortar	Assumed	ММ	NF-II	All brick walls	Good
CES-6	Concrete	Assumed	ММ	NF-II	All concrete	Good
CES-7	Fire doors and frames	Yes	ММ	NF-II	All tagged fire doors	Good
CES-8	Ceramic grout	Assumed	ММ	NF-I	Bathrooms	Good
CES-9	Wood floor underlayment	Assumed	MM	NF-I	Classrooms and gym	Good
CES-10	12"x12" Tan floor tile w/mastic	Assumed	MM	NF-I	3 <sup>rd</sup> floor hallway	Good
CES-11	12"x12" Black floor tile w/mastic	Assumed	MM	NF-I	Hallway	Good
CES-12	Older chalkboards	Assumed	MM	NF-II	Classrooms and hallways	Good
CES-13	2'x2' ceiling tile w/holes and fissures	Assumed	MM	NF-II	Printing room by office	Good
CES-14	Sink undercoating	Assumed	MM	NF-II	Under metal sinks	Good
CES-15	2'x2' ceiling tile w/holes	Assumed	ММ	NF-II	Library	Good
CES-16	2'x2' ceiling tile smooth	Assumed	ММ	NF-II	Bathrooms	Good
CES-17	Drywall, tape and mud	No	SM		Lower floor bathrooms and closets	
CES-18	Blue cove base w/mastic	Assumed	MM	NF-II	Bathrooms and closets	Good

#### FRIABILITY:

MATERIAL TYPE:

#### **CONDITION:**

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

# APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS CONGRESS ELEMENTARY SCHOOL INSPECTION DATE: OCTOBER 13<sup>th</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
CES-19	Black cove base w/mastic	Assumed	MM	NF-II	Lower level hallways	Good
CES-20	12"x12" Multi-colored floor tile w/mastic	Assumed	ММ	NF-I	Music room	Good
CES-21	2'x2' ceiling tile w/pins and fissures	Assumed	MM	NF-II	Music room	Good
CES-22	12"x12" Creme floor tile w/mastic	Assumed	ММ	NF-I	Lower level	Good
CES-23	Brown cove base w/mastic	Assumed	ММ	NF-II	Under lockers	Good
CES-24	EIFS	Assumed	ММ	NF-II	Exterior around windows and doors	Good
CES-25	Decorative concrete	Assumed	ММ	NF-II	Exterior façade	Good
CES-26	Block mortar	Assumed	ММ	NF-II	All cinderblock walls	Good

#### FRIABILITY: F: Friable

NF-I: Non-friable Category I

NF-II: Non-friable Category II

#### MATERIAL TYPE: TSI: Thermal System Insulation

SM: Surfacing Material

MM: Miscellaneous Material

#### **CONDITION:**

Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

This page has been left blank intentionally

October 31<sup>st</sup>, 2019 Project Number: MA-117-19

Mr. Marc Bennett Grand Rapids Public Schools 900 Union, NE Grand Rapids, MI 49503

Re: AHERA 3 Year Reinspection Report Grand Rapids Public Schools – Ken-o-sha Elementary School Micro Air Consulting LLC

119 West Cass Street P.O. Box 908 Grand Rapids, MI 48838 Phone: 616-302-0819 Web: microairconsulting.com Email: microairconsulting@gmail.com

Dear Mr. Bennett:

MicroAir Consulting, LLC (MicroAir) was retained by Grand Rapids Public Schools (GRPS), to conduct an AHERA 3-year reinspection of Ken-o-sha Elementary School located at 1353 Van Auken Street SE in Grand Rapids, Michigan. The inspection was conducted according to the protocol described in the U.S. Environmental Protection Agency Asbestos Hazard Emergency Response Act of 1986 (40 CFR 763).

## CERTIFICATION

The building inspection was conducted on October 14<sup>th</sup>, 2019 by Mr. Ryan Emmons, a State of Michigan accredited Asbestos Building Inspector. Mr. Emmons's, Accreditation Number is A55220.

## **REGULATORY BACKGROUND**

As a public and commercial building, Ken-o-sha is governed by 29 CFR 1910.1001, Occupational Health Standards for Asbestos in Construction/General Industry and the EPA's NESHAP for the normal course of business activities by GRPS employees and occupants.

There are three state agencies in Michigan that regulate asbestos in Michigan: the Michigan Department of Environmental Quality (DEQ), the Michigan Department of Licensing and Regulatory Affairs (DLARA) and the Michigan Department of State Police (MSP). The DEQ is concerned about the release of asbestos fibers to the outer air and proper waste disposal, while DLARA focuses on worker protection during renovation and demolition activities, contractor licensing, and worker training.

During construction or renovation activities, the persons performing those activities would be governed by 29 CFR 1926.1101, Occupational Health Standards for Asbestos in Construction. The Asbestos Hazard Emergency Response Act (AHERA), 40 CFR 763, (partial) and/or its associated requirements. However, there are some portions of AHERA that are used as guidelines for compliance with 29 CFR 1910.1001. In particular, 29 CFR 1910.1001(j)(1) requires owners of buildings constructed prior to 1980 to presume that certain types of building materials are asbestos-containing materials (ACM), unless the owner demonstrates that those materials are not ACM.

40 CFR Part 61, Subpart M (NESHAP) requires that a thorough inspection be conducted prior to all renovations and all demolitions. A thorough inspection for asbestos is required no matter the age of the facility because all uses of asbestos are not banned. The inspection must be completed before the commencement of a subject renovation and/or demolition activity.

### **BUILDING DESCRIPTION**

The Ken-o-sha Elementary School building was constructed in 1964 with an addition in 1975. Some building renovations have occurred throughout over the years as well.

### **PREVIOUS INSPECTION**

The most recent inspection was conducted by GRPS. MicroAir reviewed this report and incorporated the findings of the previous inspection and historical information into the current reinspection data.

In the previous inspection report suspect ACM materials were given a unique identification number (homogeneous material number), MicroAir has changed numbering from previous reports. The reinspec-

tion did include the collection of bulk samples. Results of the sampling can be found in Appendix A along with locations of remaining ACM in the building.



## **REINSPECTION PROCEDURES**

With the assistance of GRPS maintenance staff, MicroAir re-inspected known and previously identified Consulting, LLC areas of the building including above suspended ceilings, pipe chases, and inside the tunnels.

It was beyond the scope of this reinspection to locate, identify, or quantify ACM in areas that were concealed and/or inaccessible areas, such as within walls, hard ceilings, or equipment.

### **2019 REINSPECTION FINDINGS**

The following suspect asbestos-containing materials were observed at Ken-o-sha Elementary School during the asbestos inspection and the bulk sampling. Materials in **bold** were found to be greater than 1% ACM.

- Plaster
- Block mortar
- Brick mortar
- 1'x1' ceiling tiles w/glue pod
- 2'x2' ceiling tile
- Ceramic grout
- Fire doors and frames
- 12"x12" White/specs floor tile w/mastic
- Sink undercoating
- Curtains
- 9"x9" White w/black floor tile w/mastic
- Wood floor underlayment
- 2'x2' ceiling tile smooth white
- Tall black cove base w/mastic
- Dark cove base w/mastic
- 12"x12" Peppered floor tile w/mastic
- Brown cove base w/mastic
- Drywall, tape and mud
- Overhead plaster
- 2'x2' ceiling tile w/holes and fissures
- Roofing

Some of the materials listed above are assumed to contain asbestos until bulk samples can be collected and analyzed.

Appendix A of this report is a table that identifies the confirmed and suspect ACM homogeneous materials in Ken-o-sha, their corresponding identification number and locations, and the general condition of ACMs identified during the reinspection.

### CONCLUSIONS AND RECOMMENDATIONS

MicroAir was retained by Grand Rapids Public Schools to conduct a 3-year asbestos-containing material (ACM) reinspection of Ken-o-sha Elementary School located at 1353 Van Auken Street SE in Grand Rapids, Michigan. MicroAir completed the reinspection on October 14<sup>th</sup>, 2019. The inspection was conducted by a State of Michigan accredited Asbestos Building Inspector.

During the reinspection, MicroAir identified and assessed 21 homogeneous materials remaining in Ken-o-sha Elementary School.

Any personnel entering a tunnel or chase area must be notified of ACM locations and explained the requirement to wear personal protective equipment.

If GRPS plans to conduct any renovation or demolition, the identified ACMs should be removed by a licensed asbestos abatement contractor, as required by current federal, state, and local laws and regulations, should perform any necessary removal and disposal of the identified ACM. MicroAir notes that if suspect ACM other than those identified during this reinspection are encountered during any

renovation or demolition, such materials should be sampled and analyzed using PLM to verify presence of asbestos.



We also recommend that visual observations, verification of removal and cleanup, and air monitoring or clearance air monitoring for asbestos fibers be performed by a third party retained by GRPS to demonstrate compliance with applicable regulations, and to confirm the suitability or the area for re-entry. MicroAir can perform these services.

Warning labels should be affixed in all non-public areas where ACM or assumed ACM is present. After completion of repairs or removal of the ACM, fill out an O&M Activities Form and file it in the management plan.

As required by AHERA, GRPS should continue to send the annual notifications including information on planned response actions and reinspections. Copies of the notifications should be kept in the Management Plan.

# LIMITATIONS

The conclusions drawn from the observations and sample results are only valid for the time the observations occurred. In the process of gathering the field data included in this report, procedures were followed that represent reasonable and acceptable industrial hygiene practices and procedures in a manner consistent with the level of care and skill ordinarily exercised by other members of this profession currently practicing under similar conditions. However, the information and opinions provided in this report are not to be construed as a warranty of the conditions of this site in any way, implied or explicit. MicroAir accepts no responsibility for the use, interpretation, or reliance by other parties on the information contained herein, nor does this report represent an instrument of regulatory compliance or an asbestos abatement specification.

In conducting the reinspection there are a number of obstacles and limitations that can affect the final outcome of the report. These limitations include but are not limited to the following factors: access concerns, materials that cannot be intrusively sampled or damaged, materials that have been replaced by renovation activities, materials with conflicting laboratory results, and materials that are located in inaccessible and/or concealed areas which limits its quantification. Due to these limitations, the results of this investigation cannot be construed as a certification of the presence or absence of ACM, beyond the materials identified, but rather a diligent and prudent review of available data within an established work scope, and time and budgetary constraints.

If you have any questions or require additional information, please contact me at 616-302-0819 or microairconsulting@gmail.com.

Sincerely,

**MicroAir Consulting, LLC** 

tin T. Decker

Christian T. Decker Accredited Building Inspector and Management Planner

# **APPENDIX A**

# TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS

# APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS KEN-O-SHA ELEMENTARY SCHOOL INSPECTION DATE: OCTOBER 13<sup>th</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
KES-1	Plaster	No	SM		Interior walls and ceilings	
KES-2	Block mortar	Assumed	ММ	NF-II	All cinderblock walls	Good
KES-3	Brick mortar	Assumed	MM	NF-II	All brick walls	Good
KES-4	1'x1' ceiling tiles w/glue pod	Assumed	MM	NF-II	Hallways and classrooms	Good
KES-5	2'x2' ceiling tile	Assumed	ММ	NF-II	Classrooms	Good
KES-6	Ceramic grout	Assumed	ММ	NF-I	Hallways, bathrooms and windowsills	Good
KES-7	Fire doors and frames	Yes	ММ	NF-II	All tagged fire doors	Good
KES-8	12"x12" White/specs floor tile w/mastic	Assumed	ММ	NF-I	Under carpet in classrooms	Good
KES-9	Sink undercoating	Assumed	ММ	NF-II	Under metal sinks	Good
KES-10	Curtains	Assumed	MM	NF-II	Music room and stage	Good
KES-11	9"x9" White w/black floor tile w/mastic	Assumed	MM	NF-I	Closets and some rooms	Good
KES-12	Wood floor underlayment	Assumed	MM	NF-I	Gym and stage	Good
KES-13	2'x2' ceiling tile smooth white	Assumed	MM	NF-II	Hallways	Good
KES-14	Tall black cove base w/mastic	Assumed	ММ	NF-II	Library	Good
KES-15	Dark cove base w/mastic	Assumed	MM	NF-II	Hallways	Good
KES-16	12"x12" Peppered floor tile w/mastic	Assumed	MM	NF-I	Health office	Good
KES-17	Brown cove base w/mastic	Assumed	MM	NF-II	Hallways and classrooms	Good
KES-18	Drywall, tape and mud	Yes	SM	F	Interior drywall walls and ceilings	Good

#### FRIABILITY:

MATERIAL TYPE:

# nculation

## CONDITION:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

# APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS KEN-O-SHA ELEMENTARY SCHOOL INSPECTION DATE: OCTOBER 13<sup>th</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
KES-19	Overhead plaster	No	SM		Exterior entrances	
KES-20	2'x2' ceiling tile w/holes and fissures	Assumed	ММ	NF-II	Classrooms	Good
KES-21	Roofing	Assumed	MM	NF-I	Exterior asphalt roofing	Good

#### FRIABILITY:

#### MATERIAL TYPE:

#### F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II

TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

## CONDITION:

Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

This page has been left blank intentionally

November 4<sup>th</sup>, 2019 Project Number: MA-117-19

Mr. Marc Bennett Grand Rapids Public Schools 900 Union, NE Grand Rapids, MI 49503

Re: AHERA 3 Year Reinspection Report Grand Rapids Public Schools – Kent Hills Elementary School

Dear Mr. Bennett:



119 West Cass Street P.O. Box 908 Grand Rapids, MI 48838 Phone: 616-302-0819 Web: microairconsulting.com Email: microairconsulting@gmail.com

MicroAir Consulting, LLC (MicroAir) was retained by Grand Rapids Public Schools (GRPS), to conduct an AHERA 3-year reinspection of Kent Hills Elementary School located at 1445 Emerald Avenue NE in Grand Rapids, Michigan. The inspection was conducted according to the protocol described in the U.S. Environmental Protection Agency Asbestos Hazard Emergency Response Act of 1986 (40 CFR 763).

# CERTIFICATION

The building inspection was conducted on October 17<sup>th</sup>, 2019 by Mr. Ryan Emmons, a State of Michigan accredited Asbestos Building Inspector. Mr. Emmons's, Accreditation Number is A55220.

## **REGULATORY BACKGROUND**

As a public and commercial building, Kent Hills is governed by 29 CFR 1910.1001, Occupational Health Standards for Asbestos in Construction/General Industry and the EPA's NESHAP for the normal course of business activities by GRPS employees and occupants.

There are three state agencies in Michigan that regulate asbestos in Michigan: the Michigan Department of Environmental Quality (DEQ), the Michigan Department of Licensing and Regulatory Affairs (DLARA) and the Michigan Department of State Police (MSP). The DEQ is concerned about the release of asbestos fibers to the outer air and proper waste disposal, while DLARA focuses on worker protection during renovation and demolition activities, contractor licensing, and worker training.

During construction or renovation activities, the persons performing those activities would be governed by 29 CFR 1926.1101, Occupational Health Standards for Asbestos in Construction. The Asbestos Hazard Emergency Response Act (AHERA), 40 CFR 763, (partial) and/or its associated requirements. However, there are some portions of AHERA that are used as guidelines for compliance with 29 CFR 1910.1001. In particular, 29 CFR 1910.1001(j)(1) requires owners of buildings constructed prior to 1980 to presume that certain types of building materials are asbestos-containing materials (ACM), unless the owner demonstrates that those materials are not ACM.

40 CFR Part 61, Subpart M (NESHAP) requires that a thorough inspection be conducted prior to all renovations and all demolitions. A thorough inspection for asbestos is required no matter the age of the facility because all uses of asbestos are not banned. The inspection must be completed before the commencement of a subject renovation and/or demolition activity.

### **BUILDING DESCRIPTION**

The Kent Hills building was constructed in 1954 with additions in 1956 and 2008. Some building renovations have occurred throughout over the years as well.

### **PREVIOUS INSPECTION**

The most recent inspection was conducted by GRPS. MicroAir reviewed this report and incorporated the findings of the previous inspection and historical information into the current reinspection data.

In the previous inspection report suspect ACM materials were given a unique identification number (homogeneous material number), MicroAir has changed numbering from previous reports. The reinspection did include the collection of bulk samples. Results of the sampling can be found in Appendix A along with locations of remaining ACM in the building.

### **REINSPECTION PROCEDURES**

With the assistance of GRPS maintenance staff, MicroAir re-inspected known and previously identified areas of the building including above suspended ceilings, pipe chases, and inside the tunnels.

It was beyond the scope of this reinspection to locate, identify, or quantify ACM in areas that were concealed onsulting, LLC and/or inaccessible areas, such as within walls, hard ceilings, or equipment.

# **2019 REINSPECTION FINDINGS**

The following suspect asbestos-containing materials were observed at Kent Hills Elementary School during the asbestos inspection and the bulk sampling. Materials in **bold** were found to be greater than 1% ACM.

- Brick mortar
- Block mortar
- Roofing
- Fire doors and frames
- EIFS
- Concrete
- Tan cove base w/mastic
- 12"x12" Brown/Blue floor tile w/mastic
- 2'x2' ceiling tile w/pins and fissures
- Ceramic grout
- Sink undercoating
- Brown cove base w/mastic
- 1'x1' ceiling tile w/glue pods
- Leveling compound
- Green rolled vinyl flooring w/mastic
- Orange rolled vinyl flooring w/mastic
- Drywall, tape and mud
- Dark gray cove base w/mastic
- 12"x12" Tan floor tile w/mastic
- Orange cove base w/mastic
- Blue rolled vinyl flooring w/mastic
- Rolled vinyl flooring w/mastic
- Fireplace materials

Some of the materials listed above are assumed to contain asbestos until bulk samples can be collected and analyzed.

Appendix A of this report is a table that identifies the confirmed and suspect ACM homogeneous materials in Kent Hills Elementary School, their corresponding identification number and locations, and the general condition of ACMs identified during the reinspection.

# CONCLUSIONS AND RECOMMENDATIONS

MicroAir was retained by Grand Rapids Public Schools to conduct a 3-year asbestos-containing material (ACM) reinspection of Kent Hills Elementary School located at 1445 Emerald Avenue NE in Grand Rapids, Michigan. MicroAir completed the reinspection on October 17<sup>th</sup>, 2019. The inspection was conducted by a State of Michigan accredited Asbestos Building Inspector.

During the reinspection, MicroAir identified and assessed 23 homogeneous materials remaining in Kent Hills Elementary School.

Any personnel entering a tunnel or chase area must be notified of ACM locations and explained the requirement to wear personal protective equipment.

If GRPS plans to conduct any renovation or demolition, the identified ACMs should be removed by a licensed asbestos abatement contractor, as required by current federal, state, and local laws and regulations, should perform any necessary removal and disposal of the identified ACM. MicroAir notes that if suspect ACM other than those identified during this reinspection are encountered during any renovation or demolition, such materials should be sampled and analyzed using PLM to verify presence of asbestos.



We also recommend that visual observations, verification of removal and cleanup, and air monitoring or clearance air monitoring for asbestos fibers be performed by a third party retained by GRPS to demonstrate compliance with applicable regulations, and to confirm the suitability or the area for reentry. MicroAir can perform these services.



Warning labels should be affixed in all non-public areas where ACM or assumed ACM is present. After completion of repairs or removal of the ACM, fill out an O&M Activities Form and file it in the management plan.

As required by AHERA, GRPS should continue to send the annual notifications including information on planned response actions and reinspections. Copies of the notifications should be kept in the Management Plan.

# LIMITATIONS

The conclusions drawn from the observations and sample results are only valid for the time the observations occurred. In the process of gathering the field data included in this report, procedures were followed that represent reasonable and acceptable industrial hygiene practices and procedures in a manner consistent with the level of care and skill ordinarily exercised by other members of this profession currently practicing under similar conditions. However, the information and opinions provided in this report are not to be construed as a warranty of the conditions of this site in any way, implied or explicit. MicroAir accepts no responsibility for the use, interpretation, or reliance by other parties on the information contained herein, nor does this report represent an instrument of regulatory compliance or an asbestos abatement specification.

In conducting the reinspection there are a number of obstacles and limitations that can affect the final outcome of the report. These limitations include but are not limited to the following factors: access concerns, materials that cannot be intrusively sampled or damaged, materials that have been replaced by renovation activities, materials with conflicting laboratory results, and materials that are located in inaccessible and/or concealed areas which limits its quantification. Due to these limitations, the results of this investigation cannot be construed as a certification of the presence or absence of ACM, beyond the materials identified, but rather a diligent and prudent review of available data within an established work scope, and time and budgetary constraints.

If you have any questions or require additional information, please contact me at 616-302-0819 or microairconsulting@gmail.com.

Sincerely,

# **MicroAir Consulting, LLC**

stin T. Deeker

Christian T. Decker Accredited Building Inspector and Management Planner

# **APPENDIX A**

# TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS

# APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS KENT HILLS ELEMENTARY SCHOOL INSPECTION DATE: OCTOBER 17<sup>th</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
KHE-1	Brick mortar	Assumed	MM	NF-II	All brick walls	Good
KHE-2	Block mortar	Assumed	ММ	NF-II	All cinderblock walls	Good
KHE-3	Roofing	Assumed	ММ	NF-I	Exterior asphalt roofing	Good
KHE-4	Fire doors and frames	Yes	MM	NF-II	All tagged fire doors	Good
KHE-5	EIFS	Assumed	MM	NF-II	Exterior around doors and windows	Good
KHE-6						
KHE-7	Concrete	Assumed	MM	NF-II	All concrete	Good
KHE-8	Tan cove base w/mastic	Assumed	MM	NF-II	Hallways, office and entrance	Good
KHE-9	12"x12" Brown/Blue floor tile w/mastic	Assumed	MM	NF-I	Hallways	Good
KHE-10	2'x2' ceiling tile w/pins and fissures	Assumed	ММ	NF-II	Hallways and classrooms	Good
KHE-11	Ceramic grout	Assumed	MM	NF-I	Bathrooms and hallways	Good
KHE-12	Sink undercoating	Assumed	ММ	NF-II	Under metal sinks	Good
KHE-13	Brown cove base w/mastic	Assumed	MM	NF-II	Hallways and classrooms	Good
KHE-14	1'x1' ceiling tile w/glue pods	Assumed	MM	NF-II	Lounge, bathrooms and closets	Good
KHE-15	Leveling compound	Assumed	MM	NF-I	Under carpeting	Good
KHE-16	Green rolled vinyl flooring w/mastic	Assumed	MM	NF-I	Teacher's lounge	Good
KHE-17	Orange rolled vinyl flooring w/mastic	Assumed	MM	NF-I	Art room and roof ladder room	Good

#### FRIABILITY:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II MATERIAL TYPE: TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

#### CONDITION:

Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

# APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS KENT HILLS ELEMENTARY SCHOOL INSPECTION DATE: OCTOBER 17<sup>th</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
KHE-18	Drywall, tape and mud	No	SM		Interior walls and ceilings	
KHE-19	Dark gray cove base w/mastic	Assumed	ММ	NF-II	Janitor's room by boiler	Good
KHE-20	12"x12" Tan floor tile w/mastic	Assumed	ММ	NF-I	Room 114 nurse's office	Good
KHE-21	Orange cove base w/mastic	Assumed	MM	NF-II	Health room	Good
KHE-22	Blue rolled vinyl flooring w/mastic	Assumed	MM	NF-I	Health room	Good
KHE-23	Rolled vinyl flooring w/mastic	Assumed	ММ	NF-I	Gym	Good
KHE-24	Fireplace materials	Assumed	ММ	NF-II	In and around fireplace	Good

#### FRIABILITY:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II

#### MATERIAL TYPE:

TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

#### **CONDITION:**

Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

This page has been left blank intentionally

November 4<sup>th</sup>, 2019 Project Number: MA-117-19

Mr. Marc Bennett Grand Rapids Public Schools 900 Union, NE Grand Rapids, MI 49503

Re: AHERA 3 Year Reinspection Report Grand Rapids Public Schools – Sibley School

Dear Mr. Bennett:



119 West Cass Street P.O. Box 908 Grand Rapids, MI 48838 Phone: 616-302-0819 Web: microairconsulting.com Email: microairconsulting@gmail.com

MicroAir Consulting, LLC (MicroAir) was retained by Grand Rapids Public Schools (GRPS), to conduct an AHERA 3-year reinspection of Sibley School located at 943 Sibley Street NW in Grand Rapids, Michigan. The inspection was conducted according to the protocol described in the U.S. Environmental Protection Agency Asbestos Hazard Emergency Response Act of 1986 (40 CFR 763).

# CERTIFICATION

The building inspection was conducted on October 16<sup>th</sup>, 2019 by Mr. Ryan Emmons, a State of Michigan accredited Asbestos Building Inspector. Mr. Emmons's, Accreditation Number is A55220.

## **REGULATORY BACKGROUND**

As a public and commercial building, Sibley School is governed by 29 CFR 1910.1001, Occupational Health Standards for Asbestos in Construction/General Industry and the EPA's NESHAP for the normal course of business activities by GRPS employees and occupants.

There are three state agencies in Michigan that regulate asbestos in Michigan: the Michigan Department of Environmental Quality (DEQ), the Michigan Department of Licensing and Regulatory Affairs (DLARA) and the Michigan Department of State Police (MSP). The DEQ is concerned about the release of asbestos fibers to the outer air and proper waste disposal, while DLARA focuses on worker protection during renovation and demolition activities, contractor licensing, and worker training.

During construction or renovation activities, the persons performing those activities would be governed by 29 CFR 1926.1101, Occupational Health Standards for Asbestos in Construction. The Asbestos Hazard Emergency Response Act (AHERA), 40 CFR 763, (partial) and/or its associated requirements. However, there are some portions of AHERA that are used as guidelines for compliance with 29 CFR 1910.1001. In particular, 29 CFR 1910.1001(j)(1) requires owners of buildings constructed prior to 1980 to presume that certain types of building materials are asbestos-containing materials (ACM), unless the owner demonstrates that those materials are not ACM.

40 CFR Part 61, Subpart M (NESHAP) requires that a thorough inspection be conducted prior to all renovations and all demolitions. A thorough inspection for asbestos is required no matter the age of the facility because all uses of asbestos are not banned. The inspection must be completed before the commencement of a subject renovation and/or demolition activity.

### **BUILDING DESCRIPTION**

The Sibley School building was constructed in 2006.

## **PREVIOUS INSPECTION**

The most recent inspection was conducted by GRPS. MicroAir reviewed this report and incorporated the findings of the previous inspection and historical information into the current reinspection data.

In the previous inspection report suspect ACM materials were given a unique identification number (homogeneous material number), MicroAir has changed numbering from previous reports. The reinspection did include the collection of bulk samples. Results of the sampling can be found in Appendix A along with locations of remaining ACM in the building.

### **REINSPECTION PROCEDURES**



With the assistance of GRPS maintenance staff, MicroAir re-inspected known and previously identified areas of the building including above suspended ceilings, pipe chases, and inside the tunnels.

It was beyond the scope of this reinspection to locate, identify, or quantify ACM in areas that were Consulting, LLC concealed and/or inaccessible areas, such as within walls, hard ceilings, or equipment.

# **2019 REINSPECTION FINDINGS**

The following suspect asbestos-containing materials were observed at Sibley School during the asbestos inspection and the bulk sampling.

- Brick mortar
- Block mortar
- Concrete
- Dark gray cove base w/mastic
- 2'x2' ceiling tile w/holes and fissures
- 12"x12" white w/gray floor tile w/mastic
- Sink undercoating
- Black cove base w/mastic
- Drywall, tape and mud
- Duct putty
- Vibration dampener
- 12"x12" off white w/spots floor tile w/mastic
- Wood floor underlayment
- Rolled vinyl flooring w/mastic
- Curtain
- Divider wall
- Ceramic grout
- Vinyl stair tread
- Tall black cove base w/mastic
- Fire doors and frames
- Overhead soffit
- Roofing

Some of the materials listed above are assumed to contain asbestos until bulk samples can be collected and analyzed.

Appendix A of this report is a table that identifies the confirmed and suspect ACM homogeneous materials in Sibley School, their corresponding identification number and locations, and the general condition of ACMs identified during the reinspection.

# CONCLUSIONS AND RECOMMENDATIONS

MicroAir was retained by Grand Rapids Public Schools to conduct a 3-year asbestos-containing material (ACM) reinspection of Sibley School located at 943 Sibley Street NW in Grand Rapids, Michigan. MicroAir completed the reinspection on October 16<sup>th</sup>, 2019. The inspection was conducted by a State of Michigan accredited Asbestos Building Inspector.

During the reinspection, MicroAir identified and assessed 22 homogeneous materials remaining in Sibley School.

Any personnel entering a tunnel or chase area must be notified of ACM locations and explained the requirement to wear personal protective equipment.

If GRPS plans to conduct any renovation or demolition, the identified ACMs should be removed by a licensed asbestos abatement contractor, as required by current federal, state, and local laws and regulations, should perform any necessary removal and disposal of the identified ACM. MicroAir notes that if suspect ACM other than those identified during this reinspection are encountered during any renovation or demolition, such materials should be sampled and analyzed using PLM to verify presence of asbestos.

We also recommend that visual observations, verification of removal and cleanup, and air monitoring or clearance air monitoring for asbestos fibers be performed by a third party retained by GRPS to demonstrate compliance with applicable regulations, and to confirm the suitability or the area for reentry. MicroAir can perform these services.



Warning labels should be affixed in all non-public areas where ACM or assumed ACM is present. After completion of repairs or removal of the ACM, fill out an O&M Activities Form and file it in the management plan.

As required by AHERA, GRPS should continue to send the annual notifications including information on planned response actions and reinspections. Copies of the notifications should be kept in the Management Plan.

# LIMITATIONS

The conclusions drawn from the observations and sample results are only valid for the time the observations occurred. In the process of gathering the field data included in this report, procedures were followed that represent reasonable and acceptable industrial hygiene practices and procedures in a manner consistent with the level of care and skill ordinarily exercised by other members of this profession currently practicing under similar conditions. However, the information and opinions provided in this report are not to be construed as a warranty of the conditions of this site in any way, implied or explicit. MicroAir accepts no responsibility for the use, interpretation, or reliance by other parties on the information contained herein, nor does this report represent an instrument of regulatory compliance or an asbestos abatement specification.

In conducting the reinspection there are a number of obstacles and limitations that can affect the final outcome of the report. These limitations include but are not limited to the following factors: access concerns, materials that cannot be intrusively sampled or damaged, materials that have been replaced by renovation activities, materials with conflicting laboratory results, and materials that are located in inaccessible and/or concealed areas which limits its quantification. Due to these limitations, the results of this investigation cannot be construed as a certification of the presence or absence of ACM, beyond the materials identified, but rather a diligent and prudent review of available data within an established work scope, and time and budgetary constraints.

If you have any questions or require additional information, please contact me at 616-302-0819 or microairconsulting@gmail.com.

Sincerely,

**MicroAir Consulting, LLC** 

tin T. Decker

Christian T. Decker Accredited Building Inspector and Management Planner

# **APPENDIX A**

# TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS

# **APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS SIBLEY SCHOOL INSPECTION DATE: OCTOBER 16th**, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
SES-1	Brick mortar	Assumed	MM	NF-II	All brick walls	Good
SES-2	Block mortar	Assumed	ММ	NF-II	All cinderblock walls	Good
SES-3	Concrete	Assumed	MM	NF-II	All concrete	Good
SES-4	Dark gray cove base w/mastic	Assumed	MM	NF-II	Office	Good
SES-5	2'x2' ceiling tile w/holes and fissures	Assumed	MM	NF-II	Hallways, office and classrooms	Good
SES-6	12"x12" white w/gray floor tile w/mastic	Assumed	MM	NF-I	Office and nurse's office	Good
SES-7	Sink undercoating	Assumed	MM	NF-II	Under metal sinks	Good
SES-8	Black cove base w/mastic	Assumed	MM	NF-II	Hallways, office and nurse's office	Good
SES-9	Drywall, tape and mud	No	SM		Interior walls and ceiling	
SES-10	Duct putty	Assumed	MM	NF-II	HVAC ductwork seams	Good
SES-11	Vibration dampener	Assumed	ММ	NF-II	HVAC ductwork	Good
SES-12	12"x12" off white w/spots floor tile w/mastic	Assumed	MM	NF-I	Mechanical room and kitchen storage	Good
SES-13	Wood floor underlayment	Assumed	MM	NF-I	Gym	Good
SES-14	Rolled vinyl flooring w/mastic	Assumed	MM	NF-I	Hallways and cafeteria	Good
SES-15	Curtain	Assumed	MM	NF-II	Music room	Good
SES-16	Divider wall	Assumed	ММ	NF-II	Music room	Good
SES-17	Ceramic grout	Assumed	ММ	NF-I	Bathrooms	Good

#### FRIABILITY:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II MATERIAL TYPE:

## **CONDITION:**

TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

# APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS SIBLEY SCHOOL



# **INSPECTION DATE: OCTOBER 16th**, 2019

HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
SES-18	Vinyl stair tread	Assumed	MM	NF-I	Stairways	Good
SES-19	Tall black cove base w/mastic	Assumed	MM	NF-II	2 <sup>nd</sup> floor hallways	Good
SES-20	Fire doors and frames	Assumed	MM	NF-II	All tagged fire doors	Good
SES-21	Overhead soffit	Assumed	MM	NF-II	Entrance soffit	Good
SES-22	Roofing	Assumed	MM	NF-I	Exterior asphalt roofing	Good

### FRIABILITY:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II MATERIAL TYPE:

TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

# **CONDITION:**

Good: Little or no damage

Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

This page has been left blank intentionally

November 6<sup>th</sup>, 2019 Project Number: MA-117-19

Mr. Marc Bennett Grand Rapids Public Schools 900 Union, NE Grand Rapids, MI 49503

Re: AHERA 3 Year Reinspection Report Grand Rapids Public Schools – Mulick Park Elementary School

Dear Mr. Bennett:



119 West Cass Street P.O. Box 908 Grand Rapids, MI 48838 Phone: 616-302-0819 Web: microairconsulting.com Email: microairconsulting@gmail.com

MicroAir Consulting, LLC (MicroAir) was retained by Grand Rapids Public Schools (GRPS), to conduct an AHERA 3-year reinspection of Mulick Park Elementary School located at 1761 Rosewood Avenue SE in Grand Rapids, Michigan. The inspection was conducted according to the protocol described in the U.S. Environmental Protection Agency Asbestos Hazard Emergency Response Act of 1986 (40 CFR 763).

# CERTIFICATION

The building inspection was conducted on October 10<sup>th</sup>, 2019 by Mr. Ryan Emmons, a State of Michigan accredited Asbestos Building Inspector. Mr. Emmons's, Accreditation Number is A55220.

## **REGULATORY BACKGROUND**

As a public and commercial building, Mulick Park is governed by 29 CFR 1910.1001, Occupational Health Standards for Asbestos in Construction/General Industry and the EPA's NESHAP for the normal course of business activities by GRPS employees and occupants.

There are three state agencies in Michigan that regulate asbestos in Michigan: the Michigan Department of Environmental Quality (DEQ), the Michigan Department of Licensing and Regulatory Affairs (DLARA) and the Michigan Department of State Police (MSP). The DEQ is concerned about the release of asbestos fibers to the outer air and proper waste disposal, while DLARA focuses on worker protection during renovation and demolition activities, contractor licensing, and worker training.

During construction or renovation activities, the persons performing those activities would be governed by 29 CFR 1926.1101, Occupational Health Standards for Asbestos in Construction. The Asbestos Hazard Emergency Response Act (AHERA), 40 CFR 763, (partial) and/or its associated requirements. However, there are some portions of AHERA that are used as guidelines for compliance with 29 CFR 1910.1001. In particular, 29 CFR 1910.1001(j)(1) requires owners of buildings constructed prior to 1980 to presume that certain types of building materials are asbestos-containing materials (ACM), unless the owner demonstrates that those materials are not ACM.

40 CFR Part 61, Subpart M (NESHAP) requires that a thorough inspection be conducted prior to all renovations and all demolitions. A thorough inspection for asbestos is required no matter the age of the facility because all uses of asbestos are not banned. The inspection must be completed before the commencement of a subject renovation and/or demolition activity.

### **BUILDING DESCRIPTION**

The Mulick Park Elementary School building was constructed in 1953 with an addition in 1955. Some building renovations have occurred throughout over the years as well.

### **PREVIOUS INSPECTION**

The most recent inspection was conducted by GRPS. MicroAir reviewed this report and incorporated the findings of the previous inspection and historical information into the current reinspection data.

In the previous inspection report suspect ACM materials were given a unique identification number (homogeneous material number), MicroAir has changed numbering from previous reports. The reinspection did include the collection of bulk samples. Results of the sampling can be found in Appendix A along with locations of remaining ACM in the building.

### **REINSPECTION PROCEDURES**

With the assistance of GRPS maintenance staff, MicroAir re-inspected known and previously identified areas of the building including above suspended ceilings, pipe chases, and inside the tunnels.



It was beyond the scope of this reinspection to locate, identify, or quantify ACM in areas that were **Consulting**, LLC concealed and/or inaccessible areas, such as within walls, hard ceilings, or equipment.

# **2019 REINSPECTION FINDINGS**

The following suspect asbestos-containing materials were observed at Mulick Park Elementary School during the asbestos inspection and the bulk sampling. Materials in **bold** were found to be greater than 1% ACM.

- 9"x9" floor tile and mastic
- Brown cove base and mastic
- 9"x9" Green floor tile w/lines and mastic
- Wall and ceiling plaster
- Black cove base and mastic
- Linoleum on walls and counters
- Pipe insulation and fittings
- Vibration dampener
- 12"x12" Tan/brown floor tile and mastic
- 1'x1' ceiling tile smooth w/glue pod
- 1'x1' ceiling tile w/holes w/glue pod
- 2'x2' ceiling tile w/holes and fissures
- Light fixture heat shield
- Fire doors and frames
- 12"x12" Blue/beige w/streaks and mastic
- Glue pod above drop ceiling
- Drywall, tape and mud
- Plaster
- Brick mortar
- Concrete
- Blue cove base w/mastic
- Wood floor underlayment
- Sink undercoating
- Ceramic grout
- EIFS
- Older chalkboards
- Decorative block mortar
- Block mortar
- Wallboard glue pods

Some of the materials listed above are assumed to contain asbestos until bulk samples can be collected and analyzed.

Appendix A of this report is a table that identifies the confirmed and suspect ACM homogeneous materials in Mulick Park Elementary School, their corresponding identification number and locations, and the general condition of ACMs identified during the reinspection.

# CONCLUSIONS AND RECOMMENDATIONS

MicroAir was retained by Grand Rapids Public Schools to conduct a 3-year asbestos-containing material (ACM) reinspection of Mulick Park Elementary School located at 1761 Rosewood Avenue SE in Grand Rapids, Michigan. MicroAir completed the reinspection on October 10<sup>th</sup>, 2019. The inspection was conducted by a State of Michigan accredited Asbestos Building Inspector.

During the reinspection, MicroAir identified and assessed 29 homogeneous materials remaining in Mulick Park Elementary School.

Any personnel entering a tunnel or chase area must be notified of ACM locations and explained the requirement to wear personal protective equipment.

If GRPS plans to conduct any renovation or demolition, the identified ACMs should be removed by a licensed asbestos abatement contractor, as required by current federal, state, and local laws and regulations, should perform any necessary removal and disposal of the identified ACM. MicroAir notes that if suspect ACM other than those identified during this reinspection are encountered during any renovation or demolition, such materials should be sampled and analyzed using PLM to verify presence of asbestos.



We also recommend that visual observations, verification of removal and cleanup, and air monitoring or clearance air monitoring for asbestos fibers be performed by a third party retained by GRPS to demonstrate compliance with applicable regulations, and to confirm the suitability or the area for re-entry. MicroAir can perform these services.

Warning labels should be affixed in all non-public areas where ACM or assumed ACM is present. After completion of repairs or removal of the ACM, fill out an O&M Activities Form and file it in the management plan.

As required by AHERA, GRPS should continue to send the annual notifications including information on planned response actions and reinspections. Copies of the notifications should be kept in the Management Plan.

# LIMITATIONS

The conclusions drawn from the observations and sample results are only valid for the time the observations occurred. In the process of gathering the field data included in this report, procedures were followed that represent reasonable and acceptable industrial hygiene practices and procedures in a manner consistent with the level of care and skill ordinarily exercised by other members of this profession currently practicing under similar conditions. However, the information and opinions provided in this report are not to be construed as a warranty of the conditions of this site in any way, implied or explicit. MicroAir accepts no responsibility for the use, interpretation, or reliance by other parties on the information contained herein, nor does this report represent an instrument of regulatory compliance or an asbestos abatement specification.

In conducting the reinspection there are a number of obstacles and limitations that can affect the final outcome of the report. These limitations include but are not limited to the following factors: access concerns, materials that cannot be intrusively sampled or damaged, materials that have been replaced by renovation activities, materials with conflicting laboratory results, and materials that are located in inaccessible and/or concealed areas which limits its quantification. Due to these limitations, the results of this investigation cannot be construed as a certification of the presence or absence of ACM, beyond the materials identified, but rather a diligent and prudent review of available data within an established work scope, and time and budgetary constraints.

If you have any questions or require additional information, please contact me at 616-302-0819 or microairconsulting@gmail.com.

Sincerely,

**MicroAir Consulting, LLC** 

isten T. Decker

Christian T. Decker Accredited Building Inspector and Management Planner

# **APPENDIX A**

# TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS

# APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS MULICK PARK ELEMENTARY SCHOOL INSPECTION DATE: OCTOBER 10<sup>th</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
MP-HA1	9"x9" floor tile and mastic	Tile – <b>Yes</b> Mastic – No	MM	NF-I	Rooms 130, 131, 138, 140 and across from 112	Good
MP-HA2	Brown cove base and mastic	Both- No	MM		Interior wall bases	
MP-HA3	9"x9" Green floor tile w/lines and mastic	Tile – <b>Yes</b> Mastic – No	MM		Removed	
MP-HA4	Wall and ceiling plaster	No	SM		Interior walls and ceilings	
MP-HA5	Black cove base and mastic	Both- No	MM		Room 106 and corridor 152	
MP-HA6	Linoleum on walls and counters	Both- No	ММ		Room 108	
MP-HA7	Pipe insulation and fittings	Yes	TSI	F	West and east stage mechanical rooms and tunnels	Good
MP-HA8	Vibration dampener	Yes	MM	NF-II	West and east stage mechanical rooms	Good
MP-HA9	12"x12" Tan/brown floor tile and mastic	Both- No	MM		Room 149	
MP-HA10	1'x1' ceiling tile smooth w/glue pod	Both- No	ММ		Remaining ceilings	
MP-HA11	1'x1' ceiling tile w/holes w/glue pod	Both- No	ММ		Removed	
MP-HA12	2'x2' ceiling tile w/holes and fissures	Both- No	MM		Rooms 111-121	
MP-HA13	Light fixture heat shield	Yes	MM	NF-II	Older surface mounted lights	Good
MP-HA14	Fire doors and frames	Yes	MM	NF-II	All tagged fire doors	Good
MP-HA15	12"x12" Blue/beige w/streaks and mastic	Both- No	MM		Room 119	
MP-HA16	Glue pod above drop ceiling	No	MM		Above ceilings	

#### FRIABILITY:

#### MATERIAL TYPE:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

#### CONDITION:

Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

# APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS MULICK PARK ELEMENTARY SCHOOL INSPECTION DATE: OCTOBER 10<sup>th</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
MP-HA17	Drywall, tape and mud	No	SM		Interior drywall, Room 149	
MP-HA18	Plaster	No	SM		All plaster	
MP-HA19	Brick mortar	Assumed	ММ	NF-II	All brick walls	Good
MP-HA20	Concrete	Assumed	ММ	NF-II	All concrete	Good
MP-HA21	Blue cove base w/mastic	Assumed	ММ	NF-II	Interior wall base	Good
MP-HA22	Wood floor underlayment	Assumed	ММ	NF-I	Under wood flooring	Good
MP-HA23	Sink undercoating	Assumed	ММ	NF-II	Under metal sinks	Good
MP-HA24	Ceramic grout	Assumed	ММ	NF-I	Bathrooms, Hallways and classrooms	Good
MP-HA25	EIFS	Assumed	SM	F	Exterior around windows and doors	Good
MP-HA26	Older chalkboards	Assumed	ММ	NF-II	Classrooms	Good
MP-HA27	Decorative block mortar	Assumed	ММ	NF-II	Exterior decorative block	Good
MP-HA28	Block mortar	Assumed	ММ	NF-II	All cinderblock walls	Good
MP-HA29	Wallboard glue pods	Assumed	MM	NF-II	Hallways	Good

#### FRIABILITY: F: Friable

NF-I: Non-friable Category I

NF-II: Non-friable Category II

#### MATERIAL TYPE:

TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

#### **<u>CONDITION:</u>** Good: Little or no damage

Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

This page has been left blank intentionally
November 6<sup>th</sup>, 2019 Project Number: MA-117-19

Mr. Marc Bennett Grand Rapids Public Schools 900 Union, NE Grand Rapids, MI 49503

Re: AHERA 3 Year Reinspection Report Grand Rapids Public Schools – Houseman Field

Dear Mr. Bennett:



119 West Cass Street P.O. Box 908 Grand Rapids, MI 48838 Phone: 616-302-0819 Web: microairconsulting.com Email: microairconsulting@gmail.com

MicroAir Consulting, LLC (MicroAir) was retained by Grand Rapids Public Schools (GRPS), to conduct an AHERA 3-year reinspection of Houseman Field located at 162 Houseman Ave NE, in Grand Rapids, Michigan. The inspection was conducted according to the protocol described in the U.S. Environmental Protection Agency Asbestos Hazard Emergency Response Act of 1986 (40 CFR 763).

### CERTIFICATION

The building inspection was conducted on October 29<sup>th</sup>, 2019 by Mr. Ryan Emmons, a State of Michigan accredited Asbestos Building Inspector. Mr. Emmons's, Accreditation Number is A55220.

### **REGULATORY BACKGROUND**

As a public and commercial building, Houseman Field is governed by 29 CFR 1910.1001, Occupational Health Standards for Asbestos in Construction/General Industry and the EPA's NESHAP for the normal course of business activities by GRPS employees and occupants.

There are three state agencies in Michigan that regulate asbestos in Michigan: the Michigan Department of Environmental Quality (DEQ), the Michigan Department of Licensing and Regulatory Affairs (DLARA) and the Michigan Department of State Police (MSP). The DEQ is concerned about the release of asbestos fibers to the outer air and proper waste disposal, while DLARA focuses on worker protection during renovation and demolition activities, contractor licensing, and worker training.

During construction or renovation activities, the persons performing those activities would be governed by 29 CFR 1926.1101, Occupational Health Standards for Asbestos in Construction. The Asbestos Hazard Emergency Response Act (AHERA), 40 CFR 763, (partial) and/or its associated requirements. However, there are some portions of AHERA that are used as guidelines for compliance with 29 CFR 1910.1001. In particular, 29 CFR 1910.1001(j)(1) requires owners of buildings constructed prior to 1980 to presume that certain types of building materials are asbestos-containing materials (ACM), unless the owner demonstrates that those materials are not ACM.

40 CFR Part 61, Subpart M (NESHAP) requires that a thorough inspection be conducted prior to all renovations and all demolitions. A thorough inspection for asbestos is required no matter the age of the facility because all uses of asbestos are not banned. The inspection must be completed before the commencement of a subject renovation and/or demolition activity.

### **BUILDING DESCRIPTION**

The Houseman Field construction date is newer. Some building renovations have occurred throughout over the years as well.

### **PREVIOUS INSPECTION**

The most recent inspection was conducted by GRPS. MicroAir reviewed this report and incorporated the findings of the previous inspection and historical information into the current reinspection data.

In the previous inspection report suspect ACM materials were given a unique identification number (homogeneous material number), MicroAir has changed numbering from previous reports. The reinspection did include the collection of bulk samples. Results of the sampling can be found in Appendix A along with locations of remaining ACM in the building.

## **REINSPECTION PROCEDURES**

With the assistance of GRPS maintenance staff, MicroAir re-inspected known and previously identified areas of the building including above suspended ceilings, pipe chases, and inside the tunnels.



It was beyond the scope of this reinspection to locate, identify, or quantify ACM in areas that were concealed and/or inaccessible areas, such as within walls, hard ceilings, or equipment.

### **2019 REINSPECTION FINDINGS**

The following suspect asbestos-containing materials were observed at Houseman Field during the asbestos inspection and the bulk sampling. Materials in **bold** were found to be greater than 1% ACM.

- Older brick mortar
- Newer brick mortar
- Roofing
- Block mortar
- Concrete
- Fire doors and frames
- Black cove base w/mastic
- Drywall, tape and mud- Concessions
- Duct putty
- Rolled vinyl flooring w/mastic
- Vinyl stair tread w/mastic
- Drywall, tape and mud- Info booth
- EIÉS
- 2'x2' ceiling tile smooth
- Drywall, tape and mud- Ticket booth
- Drywall, tape and mud- Announcer's booth
- Drywall, tape and mud- Visitor ticket booth

Some of the materials listed above are assumed to contain asbestos until bulk samples can be collected and analyzed.

Appendix A of this report is a table that identifies the confirmed and suspect ACM homogeneous materials in Houseman Field, their corresponding identification number and locations, and the general condition of ACMs identified during the reinspection.

### CONCLUSIONS AND RECOMMENDATIONS

MicroAir was retained by Grand Rapids Public Schools to conduct a 3-year asbestos-containing material (ACM) reinspection of Houseman Field located at 162 Houseman Ave NE, in Grand Rapids, Michigan. MicroAir completed the reinspection on October 29<sup>th</sup>, 2019. The inspection was conducted by a State of Michigan accredited Asbestos Building Inspector.

During the reinspection, MicroAir identified and assessed 17 homogeneous materials remaining in Houseman Field.

Any personnel entering a tunnel or chase area must be notified of ACM locations and explained the requirement to wear personal protective equipment.

If GRPS plans to conduct any renovation or demolition, the identified ACMs should be removed by a licensed asbestos abatement contractor, as required by current federal, state, and local laws and regulations, should perform any necessary removal and disposal of the identified ACM. MicroAir notes that if suspect ACM other than those identified during this reinspection are encountered during any renovation or demolition, such materials should be sampled and analyzed using PLM to verify presence of asbestos.

We also recommend that visual observations, verification of removal and cleanup, and air monitoring or clearance air monitoring for asbestos fibers be performed by a third party retained by GRPS to demonstrate compliance with applicable regulations, and to confirm the suitability or the area for re-entry. MicroAir can perform these services.

Warning labels should be affixed in all non-public areas where ACM or assumed ACM is present. After completion of repairs or removal of the ACM, fill out an O&M Activities Form and file it in the management plan.



As required by AHERA, GRPS should continue to send the annual notifications including information on planned response actions and reinspections. Copies of the notifications should be kept in the Management Plan.

## LIMITATIONS

The conclusions drawn from the observations and sample results are only valid for the time the observations occurred. In the process of gathering the field data included in this report, procedures were followed that represent reasonable and acceptable industrial hygiene practices and procedures in a manner consistent with the level of care and skill ordinarily exercised by other members of this profession currently practicing under similar conditions. However, the information and opinions provided in this report are not to be construed as a warranty of the conditions of this site in any way, implied or explicit. MicroAir accepts no responsibility for the use, interpretation, or reliance by other parties on the information contained herein, nor does this report represent an instrument of regulatory compliance or an asbestos abatement specification.

In conducting the reinspection there are a number of obstacles and limitations that can affect the final outcome of the report. These limitations include but are not limited to the following factors: access concerns, materials that cannot be intrusively sampled or damaged, materials that have been replaced by renovation activities, materials with conflicting laboratory results, and materials that are located in inaccessible and/or concealed areas which limits its quantification. Due to these limitations, the results of this investigation cannot be construed as a certification of the presence or absence of ACM, beyond the materials identified, but rather a diligent and prudent review of available data within an established work scope, and time and budgetary constraints.

If you have any questions or require additional information, please contact me at 616-302-0819 or microairconsulting@gmail.com.

Sincerely,

**MicroAir Consulting, LLC** 

ten T. Deeker

Christian T. Decker Accredited Building Inspector and Management Planner

# **APPENDIX A**

# TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS

## APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS GRPS – HOUSEMAN FIELD INSPECTION DATE: OCTOBER 29<sup>th</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
HMF-1	Older brick mortar	Assumed	MM	NF-II	Older standard brick mortar	Good
HMF-2	Newer brick mortar	Assumed	MM	NF-II	Newer larger brick mortar	Good
HMF-3	Roofing	Assumed	MM	NF-I	Asphalt roofing	Good
HMF-4	Block mortar	Assumed	MM	NF-II	All cinderblock walls	Good
HMF-5	Concrete	Assumed	MM	NF-II	All concrete	Good
HMF-6	Fire doors and frames	Yes	MM	NF-II	All tagged fire doors	Good
HMF-7	Black cove base w/mastic	Assumed	MM	NF-II	Interior walls	Good
HMF-8	Drywall, tape and mud	No	SM		Concessions	
HMF-9	Duct putty	Assumed	MM	NF-II	Concessions HVAC ductwork	Good
HMF-10	Rolled vinyl flooring w/mastic	Assumed	MM	NF-I	Concessions elevator	Good
HMF-11	Vinyl stair tread w/mastic	Assumed	MM	NF-I	Announcer's booth	Good
HMF-12	Drywall, tape and mud	No	SM		Info booth	
HMF-13	EIFS	Assumed	SM	F	Exterior of concessions	Good
HMF-14	2'x2' ceiling tile smooth	Assumed	MM	NF-II	Concessions	Good
HMF-15	Drywall, tape and mud	No	SM		Ticket booth	
HMF-16	Drywall, tape and mud	No	SM		Announcer's booth	
HMF-17	Drywall, tape and mud	No	SM		Visitor ticket booth	

#### FRIABILITY:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II

#### MATERIAL TYPE: TSI: Thermal System Insulation

SM: Surfacing Material MM: Miscellaneous Material

## CONDITION:

Good: Little or no damage

Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

This page has been left blank intentionally

November 4<sup>th</sup>, 2019 Project Number: MA-117-19

Mr. Marc Bennett Grand Rapids Public Schools 900 Union, NE Grand Rapids, MI 49503

Re: AHERA 3 Year Reinspection Report Grand Rapids Public Schools – Southeast Career Pathways

Dear Mr. Bennett:



119 West Cass Street P.O. Box 908 Grand Rapids, MI 48838 Phone: 616-302-0819 Web: microairconsulting.com Email: microairconsulting@gmail.com

MicroAir Consulting, LLC (MicroAir) was retained by Grand Rapids Public Schools (GRPS), to conduct an AHERA 3-year reinspection of Southeast Career Pathways located at 1356 Jefferson Ave, SE in Grand Rapids, Michigan. The inspection was conducted according to the protocol described in the U.S. Environmental Protection Agency Asbestos Hazard Emergency Response Act of 1986 (40 CFR 763).

### CERTIFICATION

The building inspection was conducted on October 21<sup>st</sup>, 2019 by Mr. Ryan Emmons, a State of Michigan accredited Asbestos Building Inspector. Mr. Emmons's, Accreditation Number is A55220.

### **REGULATORY BACKGROUND**

As a public and commercial building, Southeast Career Pathways is governed by 29 CFR 1910.1001, Occupational Health Standards for Asbestos in Construction/General Industry and the EPA's NESHAP for the normal course of business activities by GRPS employees and occupants.

There are three state agencies in Michigan that regulate asbestos in Michigan: the Michigan Department of Environmental Quality (DEQ), the Michigan Department of Licensing and Regulatory Affairs (DLARA) and the Michigan Department of State Police (MSP). The DEQ is concerned about the release of asbestos fibers to the outer air and proper waste disposal, while DLARA focuses on worker protection during renovation and demolition activities, contractor licensing, and worker training.

During construction or renovation activities, the persons performing those activities would be governed by 29 CFR 1926.1101, Occupational Health Standards for Asbestos in Construction. The Asbestos Hazard Emergency Response Act (AHERA), 40 CFR 763, (partial) and/or its associated requirements. However, there are some portions of AHERA that are used as guidelines for compliance with 29 CFR 1910.1001. In particular, 29 CFR 1910.1001(j)(1) requires owners of buildings constructed prior to 1980 to presume that certain types of building materials are asbestos-containing materials (ACM), unless the owner demonstrates that those materials are not ACM.

40 CFR Part 61, Subpart M (NESHAP) requires that a thorough inspection be conducted prior to all renovations and all demolitions. A thorough inspection for asbestos is required no matter the age of the facility because all uses of asbestos are not banned. The inspection must be completed before the commencement of a subject renovation and/or demolition activity.

### **BUILDING DESCRIPTION**

The Southeast Career Pathways building was constructed in the 1950's. Some building renovations have occurred throughout over the years as well. Formerly Jefferson

### **PREVIOUS INSPECTION**

The most recent inspection was conducted by GRPS. MicroAir reviewed this report and incorporated the findings of the previous inspection and historical information into the current reinspection data.

In the previous inspection report suspect ACM materials were given a unique identification number (homogeneous material number), MicroAir has changed numbering from previous reports. The reinspection did include the collection of bulk samples. Results of the sampling can be found in Appendix A along with locations of remaining ACM in the building.

## **REINSPECTION PROCEDURES**

With the assistance of GRPS maintenance staff, MicroAir re-inspected known and previously identified areas of the building including above suspended ceilings, pipe chases, and inside the tunnels.



It was beyond the scope of this reinspection to locate, identify, or quantify ACM in areas that were concealed and/or inaccessible areas, such as within walls, hard ceilings, or equipment.

### **2019 REINSPECTION FINDINGS**

The following suspect asbestos-containing materials were observed at Southeast Career Pathways during the asbestos inspection and the bulk sampling. Materials in **bold** were found to be greater than 1% ACM.

- Hard Plaster ceiling
- 12"x12" Brown/Tan floor tile w/mastic
- Brick mortar
- Fire doors and frames
- Block mortar
- 2'x4' ceiling tile smooth
- Brown cove base w/mastic
- Dark grey cove base w/mastic
- Drywall, tape and mud
- Ceramic grout
- Concrete
- Mudded fittings
- Cream cove base w/mastic
- 2'x2' ceiling tile smooth
- Wood floor underlayment
- Mudded roof drains
- 12"x12" White/gray floor tile w/mastic
- Sink undercoating
- Vibration dampener
- Textured drywall, tape and mud
- Tall gray cove base w/mastic
- 1'x1' ceiling tile w/glue pod
- 2'x4' ceiling tiles w/pins and fissures
- Black cove base w/mastic
- 9"x9" floor tile w/mastic
- Older chalkboards
- 2'x2' ceiling tile w/pins and fissures
- 12"x12" light brown floor tile w/mastic
- Older Drywall, tape and mud

Some of the materials listed above are assumed to contain asbestos until bulk samples can be collected and analyzed.

Appendix A of this report is a table that identifies the confirmed and suspect ACM homogeneous materials in Southeast Career Pathways, their corresponding identification number and locations, and the general condition of ACMs identified during the reinspection.

### CONCLUSIONS AND RECOMMENDATIONS

MicroAir was retained by Grand Rapids Public Schools to conduct a 3-year asbestos-containing material (ACM) reinspection of Southeast Career Pathways located at 1356 Jefferson Ave, SE in Grand Rapids, Michigan. MicroAir completed the reinspection on October 21<sup>st</sup>, 2019. The inspection was conducted by a State of Michigan accredited Asbestos Building Inspector.

During the reinspection, MicroAir identified and assessed 29 homogeneous materials remaining in Southeast Career Pathways.

Any personnel entering a tunnel or chase area must be notified of ACM locations and explained the requirement to wear personal protective equipment.



If GRPS plans to conduct any renovation or demolition, the identified ACMs should be removed by a licensed asbestos abatement contractor, as required by current federal, state, and local laws and regulations, should perform any necessary removal and disposal of the identified ACM. MicroAir notes that if suspect ACM other than those identified during this reinspection are encountered during any renovation or demolition, such materials should be sampled and analyzed using PLM to verify presence of asbestos.

We also recommend that visual observations, verification of removal and cleanup, and air monitoring or clearance air monitoring for asbestos fibers be performed by a third party retained by GRPS to demonstrate compliance with applicable regulations, and to confirm the suitability or the area for re-entry. MicroAir can perform these services.

Warning labels should be affixed in all non-public areas where ACM or assumed ACM is present. After completion of repairs or removal of the ACM, fill out an O&M Activities Form and file it in the management plan.

As required by AHERA, GRPS should continue to send the annual notifications including information on planned response actions and reinspections. Copies of the notifications should be kept in the Management Plan.

### LIMITATIONS

The conclusions drawn from the observations and sample results are only valid for the time the observations occurred. In the process of gathering the field data included in this report, procedures were followed that represent reasonable and acceptable industrial hygiene practices and procedures in a manner consistent with the level of care and skill ordinarily exercised by other members of this profession currently practicing under similar conditions. However, the information and opinions provided in this report are not to be construed as a warranty of the conditions of this site in any way, implied or explicit. MicroAir accepts no responsibility for the use, interpretation, or reliance by other parties on the information contained herein, nor does this report represent an instrument of regulatory compliance or an asbestos abatement specification.

In conducting the reinspection there are a number of obstacles and limitations that can affect the final outcome of the report. These limitations include but are not limited to the following factors: access concerns, materials that cannot be intrusively sampled or damaged, materials that have been replaced by renovation activities, materials with conflicting laboratory results, and materials that are located in inaccessible and/or concealed areas which limits its quantification. Due to these limitations, the results of this investigation cannot be construed as a certification of the presence or absence of ACM, beyond the materials identified, but rather a diligent and prudent review of available data within an established work scope, and time and budgetary constraints.

If you have any questions or require additional information, please contact me at 616-302-0819 or microairconsulting@gmail.com.

Sincerely,

**MicroAir Consulting, LLC** 

isten T. Decker

Christian T. Decker Accredited Building Inspector and Management Planner

# **APPENDIX A**

# TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS

# APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS GRPS – SOUTHEAST CAREER PATHWAYS INSPECTION DATE: OCTOBER 21<sup>st</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
CPS - 1	Hard Plaster ceiling	No	SM		Interior hard ceilings, storage and closets	
CPS - 2	12"x12" Brown/Tan floor tile w/mastic	Assumed	ММ	NF-I	Kitchen area	Good
CPS - 3	Brick mortar	Assumed	MM	NF-II	All brick walls	Good
CPS-4	Fire doors and frames	Yes	ММ	NF-II	All tagged doors	Good
CPS-5	Block mortar	Assumed	ММ	NF-II	All cinderblock walls	Good
CPS-6	2'x4' ceiling tile smooth	Assumed	ММ	NF-II	Hallways and classrooms	Good
CPS-7	Brown cove base w/mastic	Assumed	ММ	NF-II	Classrooms	Good
CPS-8	Dark grey cove base w/mastic	Assumed	ММ	NF-II	Classrooms	Good
CPS-9	Drywall, tape and mud	No	SM		Interior drywall	
CPS-10	Ceramic grout	Assumed	ММ	NF-I	Hallways and bathrooms	Good
CPS-11	Concrete	Assumed	ММ	NF-II	All concrete	Good
CPS-12	Mudded fittings	No	TSI		Mechanical areas	
CPS-13	Cream cove base w/mastic	Assumed	ММ	NF-II	Storage	Good
CPS-14	2'x2' ceiling tile smooth	Assumed	MM	NF-II	Kitchen	Good
CPS-15	Wood floor underlayment	Assumed	ММ	NF-I	Under wood flooring	Good
CPS-16	Mudded roof drains	Assumed	TSI	F	Gym and throughout building	Good
CPS-17	12"x12" White/gray floor tile w/mastic	Assumed	MM	NF-I	Gym floor and storage	Good
CPS-18	Sink undercoating	Assumed	MM	NF-II	All metal sinks	Good

#### FRIABILITY: F: Friable

#### MATERIAL TYPE:

#### TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

## CONDITION:

ulation Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area ial Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

NF-I: Non-friable Category I

NF-II: Non-friable Category II

# APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS GRPS – SOUTHEAST CAREER PATHWAYS INSPECTION DATE: OCTOBER 21<sup>st</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
CPS-19	Vibration dampener	Assumed	MM	NF-II	HVAC ductwork	Good
CPS-20	Textured drywall, tape and mud	No	SM		Bathroom ceilings and storage	
CPS-21	Tall gray cove base w/mastic	Assumed	MM	NF-II	Near gym entrance/exit	Good
CPS-22	1'x1' ceiling tile w/glue pod	Assumed	MM	NF-II	Ceilings in hallways and some classrooms	Good
CPS-23	2'x4' ceiling tiles w/pins and fissures	Assumed	ММ	NF-II	Classrooms	Good
CPS-24	Black cove base w/mastic	Assumed	ММ	NF-II	Classrooms	Good
CPS-25	9"x9" floor tile w/mastic	Assumed	MM	NF-I	Laundry area	Good
CPS-26	Older chalkboards	Assumed	MM	NF-II	Classrooms	Good
CPS-27	2'x2' ceiling tile w/pins and fissures	Assumed	MM	NF-II	Classrooms	Good
CPS-28	12"x12" light brown floor tile w/mastic	Assumed	MM	NF-I	Classrooms	Good
CPS-29	Older Drywall, tape and <b>mud</b>	Yes	SM	F	Mechanical room	Good

#### FRIABILITY:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II

#### MATERIAL TYPE:

TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

#### **CONDITION:**

Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

SF: Square feet LF: Linear feet FT: Fittings NQ: Not Quantified

This page has been left blank intentionally

October 31<sup>st</sup>, 2019 Project Number: MA-117-19

Mr. Marc Bennett Grand Rapids Public Schools 900 Union, NE Grand Rapids, MI 49503 Micro Air Consulting, LLC

Re: AHERA 3 Year Reinspection Report Grand Rapids Public Schools – Aberdeen Elementary School 119 West Cass Street P.O. Box 908 Grand Rapids, MI 48838 Phone: 616-302-0819 Web: microairconsulting.com Email: microairconsulting@gmail.com

Dear Mr. Bennett:

MicroAir Consulting, LLC (MicroAir) was retained by Grand Rapids Public Schools (GRPS), to conduct an AHERA 3-year reinspection of Aberdeen Elementary School located at 928 Aberdeen Street NE in Grand Rapids, Michigan. The inspection was conducted according to the protocol described in the U.S. Environmental Protection Agency Asbestos Hazard Emergency Response Act of 1986 (40 CFR 763).

### CERTIFICATION

The building inspection was conducted on October 13<sup>th</sup>, 2019 by Mr. Ryan Emmons, a State of Michigan accredited Asbestos Building Inspector. Mr. Emmons's, Accreditation Number is A55220. **REGULATORY BACKGROUND** 

As a public and commercial building, Aberdeen is governed by 29 CFR 1910.1001, Occupational Health Standards for Asbestos in Construction/General Industry and the EPA's NESHAP for the normal course of business activities by GRPS employees and occupants.

There are three state agencies in Michigan that regulate asbestos in Michigan: the Michigan Department of Environmental Quality (DEQ), the Michigan Department of Licensing and Regulatory Affairs (DLARA) and the Michigan Department of State Police (MSP). The DEQ is concerned about the release of asbestos fibers to the outer air and proper waste disposal, while DLARA focuses on worker protection during renovation and demolition activities, contractor licensing, and worker training.

During construction or renovation activities, the persons performing those activities would be governed by 29 CFR 1926.1101, Occupational Health Standards for Asbestos in Construction. The Asbestos Hazard Emergency Response Act (AHERA), 40 CFR 763, (partial) and/or its associated requirements. However, there are some portions of AHERA that are used as guidelines for compliance with 29 CFR 1910.1001. In particular, 29 CFR 1910.1001(j)(1) requires owners of buildings constructed prior to 1980 to presume that certain types of building materials are asbestos-containing materials (ACM), unless the owner demonstrates that those materials are not ACM.

40 CFR Part 61, Subpart M (NESHAP) requires that a thorough inspection be conducted prior to all renovations and all demolitions. A thorough inspection for asbestos is required no matter the age of the facility because all uses of asbestos are not banned. The inspection must be completed before the commencement of a subject renovation and/or demolition activity.

### **BUILDING DESCRIPTION**

The Aberdeen Elementary School building was constructed in 1929. Some building renovations have occurred throughout over the years as well.

### **PREVIOUS INSPECTION**

The most recent inspection was conducted by GRPS. MicroAir reviewed this report and incorporated the findings of the previous inspection and historical information into the current reinspection data.

In the previous inspection report suspect ACM materials were given a unique identification number (homogeneous material number), MicroAir has changed numbering from previous reports. The reinspection did include the collection of bulk samples. Results of the sampling can be found in Appendix A along with locations of remaining ACM in the building.

### **REINSPECTION PROCEDURES**

With the assistance of GRPS maintenance staff, MicroAir re-inspected known and previously identified areas of the building including above suspended ceilings, pipe chases, and inside the tunnels.



It was beyond the scope of this reinspection to locate, identify, or quantify ACM in areas that were **Consulting**, LLC concealed and/or inaccessible areas, such as within walls, hard ceilings, or equipment.

## **2019 REINSPECTION FINDINGS**

The following suspect asbestos-containing materials were observed at Aberdeen Elementary School during the asbestos inspection and the bulk sampling. Materials in **bold** were found to be greater than 1% ACM.

- Block mortar
- Brick mortar
- Concrete
- Ceramic grout
- Smooth plaster
- Vinyl stair tread
- 1'x1' ceiling tiles
- Textured plaster
- Green cove base w/mastic
- Wood floor underlayment
- 2'x2' ceiling tile w/pins and fissures
- Fireplace brick mortar
- 2'x2' ceiling tile smooth white
- Blue/green cove base w/mastic
- Drywall, tape and mud
- Sink undercoating
- 12"x12" White/specs floor tile w/mastic
- Slate chalkboards
- 9"x9" Brown floor tile w/mastic
- Brown cove base w/mastic
- Vibration dampener
- 1'x1' ceiling tile w/glue pod
- Window glaze
- Exterior caulk
- Boiler gaskets
- Tall brown cove base w/mastic
- EIFS
- Decorative brick/block mortar
- Roofing
- Fire doors
- Foundation block mortar
- Hard plaster
- Tall green cove base w/mastic
- Textured drywall
- 2'x2' ceiling tile
- Block/stone exterior caulk
- Interior brick mortar
- 12"x12" w/squares floor tile w/mastic
- Green cove base w/mastic

Some of the materials listed above are assumed to contain asbestos until bulk samples can be collected and analyzed.

Appendix A of this report is a table that identifies the confirmed and suspect ACM homogeneous materials in Aberdeen, their corresponding identification number and locations, and the general condition of ACMs identified during the reinspection.

### CONCLUSIONS AND RECOMMENDATIONS

MicroAir was retained by Grand Rapids Public Schools to conduct a 3-year asbestos-containing material (ACM) reinspection of Aberdeen Elementary School located at 928 Aberdeen Street NE in Grand Rapids, Michigan. MicroAir completed the reinspection on October 13<sup>th</sup>, 2019. The inspection was conducted by a State of Michigan accredited Asbestos Building Inspector.



Any personnel entering a tunnel or chase area must be notified of ACM locations and explained the requirement to wear personal protective equipment.

If GRPS plans to conduct any renovation or demolition, the identified ACMs should be removed by a licensed asbestos abatement contractor, as required by current federal, state, and local laws and regulations, should perform any necessary removal and disposal of the identified ACM. MicroAir notes that if suspect ACM other than those identified during this reinspection are encountered during any renovation or demolition, such materials should be sampled and analyzed using PLM to verify presence of asbestos.

We also recommend that visual observations, verification of removal and cleanup, and air monitoring or clearance air monitoring for asbestos fibers be performed by a third party retained by GRPS to demonstrate compliance with applicable regulations, and to confirm the suitability or the area for re-entry. MicroAir can perform these services.

Warning labels should be affixed in all non-public areas where ACM or assumed ACM is present. After completion of repairs or removal of the ACM, fill out an O&M Activities Form and file it in the management plan.

As required by AHERA, GRPS should continue to send the annual notifications including information on planned response actions and reinspections. Copies of the notifications should be kept in the Management Plan.

### LIMITATIONS

The conclusions drawn from the observations and sample results are only valid for the time the observations occurred. In the process of gathering the field data included in this report, procedures were followed that represent reasonable and acceptable industrial hygiene practices and procedures in a manner consistent with the level of care and skill ordinarily exercised by other members of this profession currently practicing under similar conditions. However, the information and opinions provided in this report are not to be construed as a warranty of the conditions of this site in any way, implied or explicit. MicroAir accepts no responsibility for the use, interpretation, or reliance by other parties on the information contained herein, nor does this report represent an instrument of regulatory compliance or an asbestos abatement specification.

In conducting the reinspection there are a number of obstacles and limitations that can affect the final outcome of the report. These limitations include but are not limited to the following factors: access concerns, materials that cannot be intrusively sampled or damaged, materials that have been replaced by renovation activities, materials with conflicting laboratory results, and materials that are located in inaccessible and/or concealed areas which limits its quantification. Due to these limitations, the results of this investigation cannot be construed as a certification of the presence or absence of ACM, beyond the materials identified, but rather a diligent and prudent review of available data within an established work scope, and time and budgetary constraints.

If you have any questions or require additional information, please contact me at 616-302-0819 or microairconsulting@gmail.com.

Sincerely,

**MicroAir Consulting, LLC** 

isten T. Deeker

Christian T. Decker Accredited Building Inspector and Management Planner

# **APPENDIX A**

# TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS

## **APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS ABERDEEN ELEMENTARY SCHOOL INSPECTION DATE: OCTOBER 13th, 2019**



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
AES-1	Block mortar	Assumed	MM	NF-II	All cinderblock walls	Good
AES-2	Brick mortar	No	ММ		All brick walls	
AES-3	Concrete	Assumed	MM	NF-II	All concrete	Good
AES-4	Ceramic grout	Assumed	MM	NF-I	Ceramic tiled areas	Good
AES-5	Smooth plaster	No	SM		Hallways, classrooms and restrooms	
AES-6	Vinyl stair tread	No	MM		Stairway to 2 <sup>nd</sup> floor	
AES-7	1'x1' ceiling tile w/glue pod	No	MM		Hallways and classrooms	
AES-8	Textured plaster	No	SM		Walls and ceilings in hallways and classrooms	
AES-9	Green cove base w/mastic	Assumed	MM	NF-II	Hallways	Good
AES-10	Wood floor underlayment	Assumed	MM	NF-I	Some classrooms and gym	Good
AES-12	Fireplace brick mortar	Assumed	MM	NF-II	Façade of fireplace in kindergarten	Good
AES-13	2'x2' ceiling tile smooth white	Assumed	MM	NF-II	Kitchen	Good
AES-14	Blue/green cove base w/mastic	Assumed	MM	NF-II	Cafeteria	Good
AES-15	Drywall, tape and mud	No	SM		Cafeteria	
AES-16	Sink undercoating	Assumed	ММ	NF-II	Under metal sinks	Good
AES-17	12"x12" White/specs floor tile w/mastic	Assumed	ММ	NF-I	120 and other rooms	Good
AES-18	Slate chalkboards	Assumed	MM	NF-II	Classrooms	Good

#### FRIABILITY:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II MATERIAL TYPE: TSI: Thermal System Insulation

#### **CONDITION:**

SM: Surfacing Material MM: Miscellaneous Material

Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

SF: Square feet LF: Linear feet FT: Fittings NQ: Not Quantified

## APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS ABERDEEN ELEMENTARY SCHOOL INSPECTION DATE: OCTOBER 13<sup>th</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
AES-19	9"x9" Brown floor tile w/mastic	Assumed	ММ	NF-I	Stairway	Good
AES-20	Brown cove base w/mastic	Assumed	ММ	NF-II	Under lockers	Good
AES-21	Vibration dampener	Assumed	ММ	NF-II	Attic fan room	Good
AES-22	1'x1' ceiling tile w/glue pod	No	ММ		Storage	
AES-23	Window glaze	Yes	ММ	NF-II	Boiler room windows	Good
AES-24	Exterior caulk	Assumed	ММ	NF-II	Exterior around windows, doors and wall seams	Good
AES-25	Boiler gaskets	Assumed	ММ	NF-II	Boiler room	Good
AES-26	Tall brown cove base w/mastic	No	ММ		Back entrance	
AES-27	EIFS	No	ММ		Exterior around windows and doors	
AES-28	Decorative brick/block mortar	No	ММ		Entrance	
AES-29	Roofing	Assumed	ММ	NF-I	Exterior asphalt roofs	Good
AES-30	Fire doors	Yes	ММ	NF-II	All tagged fire doors	Good
AES-31	Foundation block mortar	No	MM		Exterior building foundation	
AES-31a	Hard plaster	No	SM		Boiler room	
AES-32	Tall green cove base w/mastic	No	ММ		Entrance	
AES-32a	Textured drywall	No	ММ		Main entrance wall	
AES-33	2'x2' ceiling tile	No	MM		Hallways, classrooms and offices	
AES-34	Block/stone exterior caulk	No	ММ		Around exterior of building	
AES-35	Interior brick mortar	No	ММ		Interior of entrance	

#### FRIABILITY:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II MATERIAL TYPE:

TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

### **CONDITION:**

Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

## APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS ABERDEEN ELEMENTARY SCHOOL INSPECTION DATE: OCTOBER 13<sup>th</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
AES-36	12"x12" w/squares floor tile w/mastic	No	ММ		Entrance	
AES-37	Green cove base w/mastic	No	MM		Office	

# FRIABILITY:

#### MATERIAL TYPE:

### CONDITION:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area This page has been left blank intentionally

November 6<sup>th</sup>, 2019 Project Number: MA-117-19

Mr. Marc Bennett Grand Rapids Public Schools 900 Union, NE Grand Rapids, MI 49503

Re: AHERA 3 Year Reinspection Report Grand Rapids Public Schools – Alger Middle School

Dear Mr. Bennett:



119 West Cass Street P.O. Box 908 Grand Rapids, MI 48838 Phone: 616-302-0819 Web: microairconsulting.com Email: microairconsulting@gmail.com

MicroAir Consulting, LLC (MicroAir) was retained by Grand Rapids Public Schools (GRPS), to conduct an AHERA 3-year reinspection of Alger Middle School located at 921 Alger Street SE in Grand Rapids, Michigan. The inspection was conducted according to the protocol described in the U.S. Environmental Protection Agency Asbestos Hazard Emergency Response Act of 1986 (40 CFR 763).

### CERTIFICATION

The building inspection was conducted on October 21<sup>st</sup>, 2019 by Mr. Ryan Emmons, a State of Michigan accredited Asbestos Building Inspector. Mr. Emmons's, Accreditation Number is A55220.

### **REGULATORY BACKGROUND**

As a public and commercial building, Alger is governed by 29 CFR 1910.1001, Occupational Health Standards for Asbestos in Construction/General Industry and the EPA's NESHAP for the normal course of business activities by GRPS employees and occupants.

There are three state agencies in Michigan that regulate asbestos in Michigan: the Michigan Department of Environmental Quality (DEQ), the Michigan Department of Licensing and Regulatory Affairs (DLARA) and the Michigan Department of State Police (MSP). The DEQ is concerned about the release of asbestos fibers to the outer air and proper waste disposal, while DLARA focuses on worker protection during renovation and demolition activities, contractor licensing, and worker training.

During construction or renovation activities, the persons performing those activities would be governed by 29 CFR 1926.1101, Occupational Health Standards for Asbestos in Construction. The Asbestos Hazard Emergency Response Act (AHERA), 40 CFR 763, (partial) and/or its associated requirements. However, there are some portions of AHERA that are used as guidelines for compliance with 29 CFR 1910.1001. In particular, 29 CFR 1910.1001(j)(1) requires owners of buildings constructed prior to 1980 to presume that certain types of building materials are asbestos-containing materials (ACM), unless the owner demonstrates that those materials are not ACM.

40 CFR Part 61, Subpart M (NESHAP) requires that a thorough inspection be conducted prior to all renovations and all demolitions. A thorough inspection for asbestos is required no matter the age of the facility because all uses of asbestos are not banned. The inspection must be completed before the commencement of a subject renovation and/or demolition activity.

### **BUILDING DESCRIPTION**

The Alger Middle School building was constructed in 2006.

### **PREVIOUS INSPECTION**

No previous inspection data.

### **REINSPECTION PROCEDURES**

With the assistance of GRPS maintenance staff, MicroAir re-inspected known and previously identified areas of the building including above suspended ceilings and pipe chases.

It was beyond the scope of this reinspection to locate, identify, or quantify ACM in areas that were concealed and/or inaccessible areas, such as within walls, hard ceilings, or equipment.



### **2019 REINSPECTION FINDINGS**

The following suspect asbestos-containing materials were observed at Alger Middle School during the asbestos inspection and the bulk sampling.

- Drywall, tape and mud
- Concrete
- Brick mortar
- Block mortar
- Exterior caulk

Some of the materials listed above are assumed to contain asbestos until bulk samples can be collected and analyzed.

Appendix A of this report is a table that identifies the confirmed and suspect ACM homogeneous materials in Alger Middle School, their corresponding identification number and locations, and the general condition of ACMs identified during the reinspection.

### CONCLUSIONS AND RECOMMENDATIONS

MicroAir was retained by Grand Rapids Public Schools to conduct a 3-year asbestos-containing material (ACM) reinspection of Alger Middle School located at 921 Alger Street SE in Grand Rapids, Michigan. MicroAir completed the reinspection on October 21<sup>st</sup>, 2019. The inspection was conducted by a State of Michigan accredited Asbestos Building Inspector.

During the reinspection, MicroAir identified and assessed 5 homogeneous materials remaining in Alger Middle School.

If GRPS plans to conduct any renovation or demolition, the identified ACMs should be removed by a licensed asbestos abatement contractor, as required by current federal, state, and local laws and regulations, should perform any necessary removal and disposal of the identified ACM. MicroAir notes that if suspect ACM other than those identified during this reinspection are encountered during any renovation or demolition, such materials should be sampled and analyzed using PLM to verify presence of asbestos.

We also recommend that visual observations, verification of removal and cleanup, and air monitoring or clearance air monitoring for asbestos fibers be performed by a third party retained by GRPS to demonstrate compliance with applicable regulations, and to confirm the suitability or the area for re-entry. MicroAir can perform these services.

Warning labels should be affixed in all non-public areas where ACM or assumed ACM is present. After completion of repairs or removal of the ACM, fill out an O&M Activities Form and file it in the management plan.

As required by AHERA, GRPS should continue to send the annual notifications including information on planned response actions and reinspections. Copies of the notifications should be kept in the Management Plan.

### LIMITATIONS

The conclusions drawn from the observations and sample results are only valid for the time the observations occurred. In the process of gathering the field data included in this report, procedures were followed that represent reasonable and acceptable industrial hygiene practices and procedures in a manner consistent with the level of care and skill ordinarily exercised by other members of this profession currently practicing under similar conditions. However, the information and opinions provided in this report are not to be construed as a warranty of the conditions of this site in any way, implied or explicit. MicroAir accepts no responsibility for the use, interpretation, or reliance by other parties on the information contained herein, nor does this report represent an instrument of regulatory compliance or an asbestos abatement specification.

In conducting the reinspection there are a number of obstacles and limitations that can affect the final outcome of the report. These limitations include but are not limited to the following factors: access concerns, materials that cannot be intrusively sampled or damaged, materials that have been replaced by renovation activities, materials with conflicting laboratory results, and materials that are located in inaccessible and/or concealed areas which limits its quantification. Due to these limitations, the results of this investigation cannot be construed as a certification of the presence or absence of ACM, beyond the materials identified, but rather a diligent and prudent review of available data within an established work scope, and time and budgetary constraints.

If you have any questions or require additional information, please contact me at 616-302-0819 or microairconsulting@gmail.com.

Sincerely,

**MicroAir Consulting, LLC** 

inten T. Deeker

Christian T. Decker Accredited Building Inspector and Management Planner



# **APPENDIX A**

# TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS

## APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS ALGER MIDDLE SCHOOL INSPECTION DATE: OCTOBER 21<sup>st</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
AMS-1	Drywall, tape and mud	No	SM		Interior drywall	
AMS-2	Concrete	No	ММ		All concrete	
AMS-3	Brick mortar	Assumed	MM	NF-II	All brick walls	Good
AMS-4	Block mortar	Assumed	MM	NF-II	All cinderblock walls	Good
AMS-5	Exterior caulk	Assumed	MM	NF-II	Around windows, doors and wall seams	Good

#### FRIABILITY:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II MATERIAL TYPE:

TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

### **CONDITION:**

Good: Little or no damage

Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

SF: Square feet LF: Linear feet FT: Fittings NQ: Not Quantified

This page has been left blank intentionally

October 25<sup>th</sup>, 2019 Project Number: MA-117-19

Mr. Marc Bennett Grand Rapids Public Schools 900 Union, NE Grand Rapids, MI 49503

Re: AHERA 3 Year Reinspection Report Grand Rapids Public Schools – **Burton Elementary/Middle School** 

Dear Mr. Bennett:

Consulting, LLC 119 West Cass Street P.O. Box 908 Greenville, MI 48838 Phone: 616-302-0819 Web: microairconsulting.com Email: microairconsulting@gmail.com

MicroAir Consulting, LLC (MicroAir) was retained by Grand Rapids Public Schools (GRPS), to conduct an AHERA 3-year reinspection of Burton Elementary/Middle School located at 2133 Buchanan Avenue SW in Grand Rapids, Michigan. The inspection was conducted according to the protocol described in the U.S. Environmental Protection Agency Asbestos Hazard Emergency Response Act of 1986 (40 CFR 763).

### CERTIFICATION

The building inspection was conducted on October 23<sup>rd</sup>, 2019 by Mr. Ryan Emmons, a State of Michigan accredited Asbestos Building Inspector. Mr. Emmons's, Accreditation Number is A55220.

### **REGULATORY BACKGROUND**

As a public and commercial building, Burton is governed by 29 CFR 1910.1001, Occupational Health Standards for Asbestos in Construction/General Industry and the EPA's NESHAP for the normal course of business activities by GRPS employees and occupants.

There are three state agencies in Michigan that regulate asbestos in Michigan: the Michigan Department of Environmental Quality (DEQ), the Michigan Department of Licensing and Regulatory Affairs (DLARA) and the Michigan Department of State Police (MSP). The DEQ is concerned about the release of asbestos fibers to the outer air and proper waste disposal, while DLARA focuses on worker protection during renovation and demolition activities, contractor licensing, and worker training.

During construction or renovation activities, the persons performing those activities would be governed by 29 CFR 1926.1101, Occupational Health Standards for Asbestos in Construction. The Asbestos Hazard Emergency Response Act (AHERA), 40 CFR 763, (partial) and/or its associated requirements. However, there are some portions of AHERA that are used as guidelines for compliance with 29 CFR 1910.1001. In particular, 29 CFR 1910.1001(j)(1) requires owners of buildings constructed prior to 1980 to presume that certain types of building materials are asbestos-containing materials (ACM), unless the owner demonstrates that those materials are not ACM.

40 CFR Part 61, Subpart M (NESHAP) requires that a thorough inspection be conducted prior to all renovations and all demolitions. A thorough inspection for asbestos is required no matter the age of the facility because all uses of asbestos are not banned. The inspection must be completed before the commencement of a subject renovation and/or demolition activity.

### **BUILDING DESCRIPTION**

The Burton Elementary/Middle School building was constructed in 1926 with an addition in 2007. Some building renovations have occurred throughout over the years as well.

### **PREVIOUS INSPECTION**

The most recent inspection was conducted by GRPS. MicroAir reviewed this report and incorporated the findings of the previous inspection and historical information into the current reinspection data.

In the previous inspection report suspect ACM materials were given a unique identification number (homogeneous material number), MicroAir has changed numbering from previous reports. The reinspection did

include the collection of bulk samples. Results of the sampling can be found in Appendix A along with locations of remaining ACM in the building.



### **REINSPECTION PROCEDURES**

With the assistance of GRPS maintenance staff, MicroAir re-inspected known and previously identified areas of the building including above suspended ceilings, pipe chases, and inside the tunnels.

It was beyond the scope of this reinspection to locate, identify, or quantify ACM in areas that were concealed and/or inaccessible areas, such as within walls, hard ceilings, or equipment.

### **2019 REINSPECTION FINDINGS**

The following suspect asbestos-containing materials were observed at Burton Elementary/Middle School during the asbestos inspection and the bulk sampling. Materials in **bold** were found to be greater than 1% ACM.

- Brick mortar
- Cinderblock mortar
- Decorative block mortar
- Concrete
- Roofing
- Fire doors and frames
- Duct putty
- Vibration dampener
- 2'x4' drop ceiling tile pins and fissures
- Drywall, tape and mud
- Ceramic grout
- Tall black cove base w/mastic
- Gray textured drywall
- Older plaster
- Short black cove base w/mastic
- Purple drywall, tape and mud
- 2'x2' drop ceiling tile w/holes
- Spray-on insulation
- Wall tile w/glue pod
- Rolled vinyl flooring w/mastic
- Decorative brick mortar
- Sink undercoating
- Vinyl stair tread w/mastic
- Ceiling plaster
- Stage curtain
- Wood floor underlayment
- Textured plaster
- 12"x12" Red floor tile w/mastic
- 12"x12" White floor tile w/mastic

Some of the materials listed above are assumed to contain asbestos until bulk samples can be collected and analyzed.

Appendix A of this report is a table that identifies the confirmed and suspect ACM homogeneous materials in Burton Elementary/Middle School, their corresponding identification number and locations, and the general condition of ACMs identified during the reinspection.

# CONCLUSIONS AND RECOMMENDATIONS

MicroAir was retained by Grand Rapids Public Schools to conduct a 3-year asbestos-containing material (ACM) reinspection of Burton Elementary/Middle School located at 2133 Buchanan Avenue SW in Grand Rapids, Michigan. MicroAir completed the reinspection on October 23<sup>rd</sup>, 2019. The inspection was conducted by a State of Michigan accredited Asbestos Building Inspector.

During the reinspection, MicroAir identified and assessed 29 homogeneous materials remaining in Burton Elementary/Middle School. Any personnel entering a tunnel or chase areas must be notified of ACM locations and explained the requirement to wear personal protective equipment.



If GRPS plans to conduct any renovation or demolition, the identified ACMs should be removed by a licensed asbestos abatement contractor, as required by current federal, state, and local laws and regulations, should perform any necessary removal and disposal of the identified ACM. MicroAir notes that if suspect ACM other than those identified during this reinspection are encountered during any renovation or demolition, such materials should be sampled and analyzed using PLM to verify presence of asbestos.

We also recommend that visual observations, verification of removal and cleanup, and air monitoring or clearance air monitoring for asbestos fibers be performed by a third party retained by GRPS to demonstrate compliance with applicable regulations, and to confirm the suitability or the area for re-entry. MicroAir can perform these services.

Warning labels should be affixed in all non-public areas where ACM or assumed ACM is present. After completion of repairs or removal of the ACM, fill out an O&M Activities Form and file it in the management plan.

As required by AHERA, GRPS should continue to send the annual notifications including information on planned response actions and reinspections. Copies of the notifications should be kept in the Management Plan.

### LIMITATIONS

The conclusions drawn from the observations and sample results are only valid for the time the observations occurred. In the process of gathering the field data included in this report, procedures were followed that represent reasonable and acceptable industrial hygiene practices and procedures in a manner consistent with the level of care and skill ordinarily exercised by other members of this profession currently practicing under similar conditions. However, the information and opinions provided in this report are not to be construed as a warranty of the conditions of this site in any way, implied or explicit. MicroAir accepts no responsibility for the use, interpretation, or reliance by other parties on the information contained herein, nor does this report represent an instrument of regulatory compliance or an asbestos abatement specification.

In conducting the reinspection there are a number of obstacles and limitations that can affect the final outcome of the report. These limitations include but are not limited to the following factors: access concerns, materials that cannot be intrusively sampled or damaged, materials that have been replaced by renovation activities, materials with conflicting laboratory results, and materials that are located in inaccessible and/or concealed areas which limits its quantification. Due to these limitations, the results of this investigation cannot be construed as a certification of the presence or absence of ACM, beyond the materials identified, but rather a diligent and prudent review of available data within an established work scope, and time and budgetary constraints.

If you have any questions or require additional information, please contact me at 616-302-0819 or microairconsulting@gmail.com. Thank you.

Sincerely,

**MicroAir Consulting, LLC** 

inten T. Deeker

Christian T. Decker Accredited Building Inspector and Management Planner

# **APPENDIX A**

# TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS

# APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS BURTON ELEMENTARY SCHOOL INSPECTION DATE: OCTOBER 23<sup>rd</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
BES-1	Brick mortar	Assumed	MM	NF-II	Brick walls	Good
BES-2	Cinderblock mortar	Assumed	MM	NF-II	Cinderblock walls	Good
BES-3	Decorative block mortar	Assumed	MM	NF-II	Exterior decorative block	Good
BES-4	Concrete	Assumed	MM	NF-II	All concrete	Good
BES-5	Roofing	Assumed	MM	NF-I	Exterior asphalt roofing	Good
BES-6	Fire doors and frames	Yes	MM	NF-II	All tagged fire doors	Good
BES-7	Duct putty	Assumed	MM	NF-II	HVAC duct work	Good
BES-8	Vibration dampener	Assumed	MM	NF-II	HVAC duct work	Good
BES-9	2'x4' drop ceiling tile pins and fissures	Assumed	MM	NF-II	Outside boiler room	Good
BES-10	Drywall, tape and mud	No	SM		Interior walls	
BES-11	Ceramic grout	Assumed	MM	NF-I	Bathrooms, kitchen and smart room	Good
BES-12	Tall black cove base w/mastic	Assumed	MM	NF-II	Hallways	Good
BES-13	Gray textured drywall	No	SM		Elevator area	
BES-14	Older plaster	Yes	SM	F	198G area, 290D all stairways	Good
BES-15	Short black cove base w/mastic	Assumed	MM	NF-II	198G area	Good
BES-16	Purple drywall, tape and mud	No	SM		198G area	

#### FRIABILITY:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II

#### MATERIAL TYPE:

TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

#### CONDITION:

Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

SF: Square feet LF: Linear feet FT: Fittings NQ: Not Quantified



## APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS BURTON ELEMENTARY SCHOOL INSPECTION DATE: OCTOBER 23<sup>rd</sup>, 2019

HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
BES-17	2'x2' drop ceiling tile w/holes	Assumed	MM	NF-II	Hallways	Good
BES-18	Spray-on insulation	No	SM		2 <sup>nd</sup> floor HVAC room	
BES-19	Wall tile w/glue pod	Both- No	MM		2 <sup>nd</sup> floor HVAC room	
BES-20	Rolled vinyl flooring w/mastic	Assumed	MM	NF-I	Entrance, classrooms, cafeteria and storage	Good
BES-21	Decorative brick mortar	Assumed	MM	NF-II	2 <sup>nd</sup> floor drinking fountain	Good
BES-22	Sink undercoating	Assumed	MM	NF-II	Under metal sinks	Good
BES-23	Vinyl stair tread w/mastic	Assumed	MM	NF-I	Stairways	Good
BES-24	Ceiling plaster	No	SM		Top floor HVAC room	
BES-25	Stage curtain	Assumed	MM	NF-II	Auditorium	Good
BES-26	Wood floor underlayment	Assumed	MM	NF-I	Under wood floors	Good
BES-27	Textured plaster	No	SM		Auditorium and entrance ceilings	
BES-28	12"x12" Red floor tile w/mastic	Assumed	MM	NF-I	Bathrooms and fountains	Good
BES-29	12"x12" White floor tile w/mastic	Assumed	MM	NF-I	Kitchen	Good

#### FRIABILITY: F: Friable

NF-I: Non-friable Category I

NF-II: Non-friable Category II

## MATERIAL TYPE:

TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

### CONDITION:

Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

SF: Square feet LF: Linear feet FT: Fittings NQ: Not Quantified

MicroAir Project No. MA-117-19

This page has been left blank intentionally

January 23<sup>rd</sup>, 2019 Project Number: MA-158-18

Mr. Marc Bennett Grand Rapids Public Schools 900 Union, NE Grand Rapids, MI 49503

Re: AHERA 3 Year Reinspection Report Grand Rapids Public Schools – **Campus Elementary School**  119 West Cass Street P.O. Box 908 Grand Rapids, MI 48838 Phone: 616-302-0819 Web: microairconsulting.com Email: microairconsulting@gmail.com

Consulting LLC

Dear Mr. Bennett:

MicroAir Consulting, LLC (MicroAir) was retained by Grand Rapids Public Schools (GRPS), to conduct an AHERA 3-year reinspection of Campus Elementary School (C) located at 710 Benjamin Avenue SE in Grand Rapids, Michigan. The inspection was conducted according to the protocol described in the U.S. Environmental Protection Agency Asbestos Hazard Emergency Response Act of 1986 (40 CFR 763).

### CERTIFICATION

The building inspection was conducted on January 4<sup>th</sup>, 2019 by Mr. Grant Edgerly, a State of Michigan accredited Asbestos Building Inspector. Mr. Edgerly's, Accreditation Number is A41792.

### **REGULATORY BACKGROUND**

As a public and commercial building, Campus is governed by 29 CFR 1910.1001, Occupational Health Standards for Asbestos in Construction/General Industry and the EPA's NESHAP for the normal course of business activities by GRPS employees and occupants.

There are three state agencies in Michigan that regulate asbestos in Michigan: the Michigan Department of Environmental Quality (DEQ), the Michigan Department of Licensing and Regulatory Affairs (DLARA) and the Michigan Department of State Police (MSP). The DEQ is concerned about the release of asbestos fibers to the outer air and proper waste disposal, while DLARA focuses on worker protection during renovation and demolition activities, contractor licensing, and worker training.

During construction or renovation activities, the persons performing those activities would be governed by 29 CFR 1926.1101, Occupational Health Standards for Asbestos in Construction. The Asbestos Hazard Emergency Response Act (AHERA), 40 CFR 763, (partial) and/or its associated requirements. However, there are some portions of AHERA that are used as guidelines for compliance with 29 CFR 1910.1001. In particular, 29 CFR 1910.1001(j)(1) requires owners of buildings constructed prior to 1980 to presume that certain types of building materials are asbestos-containing materials (ACM), unless the owner demonstrates that those materials are not ACM.

40 CFR Part 61, Subpart M (NESHAP) requires that a thorough inspection be conducted prior to all renovations and all demolitions. A thorough inspection for asbestos is required no matter the age of the facility because all uses of asbestos are not banned. The inspection must be completed before the commencement of a subject renovation and/or demolition activity.

### **BUILDING DESCRIPTION**

The Campus Elementary School building was constructed in 1950 with an addition in 1994. Some building renovations have occurred throughout over the years as well.

### **PREVIOUS INSPECTION**

The most recent inspection was conducted by GRPS in 2018. MicroAir reviewed this report and incorporated the findings of the previous inspection and historical information into the current reinspection data.

In the previous inspection report suspect ACM materials were given a unique identification number (homogeneous material number), MicroAir has changed numbering from previous reports. The reinspection

did include the collection of bulk samples. Results of the sampling can be found in Appendix A along with locations of remaining ACM in the building.



### **REINSPECTION PROCEDURES**

With the assistance of GRPS maintenance staff, MicroAir re-inspected known and previously identified areas of the building including above suspended ceilings, pipe chases, and inside the tunnels.

It was beyond the scope of this reinspection to locate, identify, or quantify ACM in areas that were concealed and/or inaccessible areas, such as within walls, hard ceilings, or equipment.

### **2019 REINSPECTION FINDINGS**

The following suspect asbestos-containing materials were observed at Campus Elementary School during the asbestos inspection and the bulk sampling. Materials in **bold** were found to be greater than 1% ACM.

- Drywall, tape, and mud
- Plaster
- Sink undercoating
- Cream w/color spots 12"x12" Floor tile w/mastic
- 2'x2' Ceiling tile
- Cream cove base w/mastic
- Gray cove base w/mastic
- Black duct putty
- Caulks and sealants
- Mortars
- Ceramic grout
- Fire doors
- Concrete
- Roofing
- Mudded fittings and drains
- Black window sills
- Divider walls

Some of the materials listed above are assumed to contain asbestos until bulk samples can be collected and analyzed.

Appendix A of this report is a table that identifies the confirmed and suspect ACM homogeneous materials in Campus, their corresponding identification number and locations, and the general condition of ACMs identified during the reinspection.

### CONCLUSIONS AND RECOMMENDATIONS

MicroAir was retained by Grand Rapids Public Schools to conduct a 3-year asbestos-containing material (ACM) reinspection of Campus Elementary School located at 710 Benjamin Avenue SE in Grand Rapids, Michigan. MicroAir completed the reinspection on January 4<sup>th</sup>, 2019. The inspection was conducted by a State of Michigan accredited Asbestos Building Inspector.

During the reinspection, MicroAir identified and assessed 17 homogeneous materials remaining in Campus Elementary School.

Any personnel entering a tunnel or chase area must be notified of ACM locations and explained the requirement to wear personal protective equipment.

If GRPS plans to conduct any renovation or demolition, the identified ACMs should be removed by a licensed asbestos abatement contractor, as required by current federal, state, and local laws and regulations, should perform any necessary removal and disposal of the identified ACM. MicroAir notes that if suspect ACM other than those identified during this reinspection are encountered during any renovation or demolition, such materials should be sampled and analyzed using PLM to verify presence of asbestos.

We also recommend that visual observations, verification of removal and cleanup, and air monitoring or clearance air monitoring for asbestos fibers be performed by a third party retained by GRPS to demonstrate
compliance with applicable regulations, and to confirm the suitability or the area for re-entry. MicroAir can perform these services.



Warning labels should be affixed in all non-public areas where ACM or assumed ACM is present. After completion of repairs or removal of the ACM, fill out an O&M Activities Form and file it in the management plan.

As required by AHERA, GRPS should continue to send the annual notifications including information on planned response actions and reinspections. Copies of the notifications should be kept in the Management Plan.

# LIMITATIONS

The conclusions drawn from the observations and sample results are only valid for the time the observations occurred. In the process of gathering the field data included in this report, procedures were followed that represent reasonable and acceptable industrial hygiene practices and procedures in a manner consistent with the level of care and skill ordinarily exercised by other members of this profession currently practicing under similar conditions. However, the information and opinions provided in this report are not to be construed as a warranty of the conditions of this site in any way, implied or explicit. MicroAir accepts no responsibility for the use, interpretation, or reliance by other parties on the information contained herein, nor does this report represent an instrument of regulatory compliance or an asbestos abatement specification.

In conducting the reinspection there are a number of obstacles and limitations that can affect the final outcome of the report. These limitations include but are not limited to the following factors: access concerns, materials that can not be intrusively sampled or damaged, materials that have been replaced by renovation activities, materials with conflicting laboratory results, and materials that are located in inaccessible and/or concealed areas which limits its quantification. Due to these limitations, the results of this investigation cannot be construed as a certification of the presence or absence of ACM, beyond the materials identified, but rather a diligent and prudent review of available data within an established work scope, and time and budgetary constraints.

If you have any questions or require additional information, please contact me at 616-302-0819 or microairconsulting@gmail.com. Thank you.

Sincerely,

**MicroAir Consulting, LLC** 

isten T. Deeker

Christian T. Decker Accredited Building Inspector and Management Planner

# **APPENDIX A**

# TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS

# **APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS CAMPUS ELEMENTARY SCHOOL INSPECTION DATE: JANUARY 4th**, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
C-1	Drywall, tape, and mud	No	SM		Walls and ceilings	
C-2	Plaster	No	SM		Walls and ceilings	
C-3	Sink undercoating	Assumed	MM	NF-II	Metal sinks	Good
C-4	Cream w/color spots 12"x12" Floor tile w/mastic	Assumed	MM	NF-I	Interior flooring	Good
C-5	2'x2' Ceiling tile	Assumed	MM	NF-II	Ceilings on grid	Good
C-6	Cream cove base w/mastic	Assumed	MM	NF-II	Interior walls	Good
C-7	Gray cove base w/mastic	Assumed	MM	NF-II	Interior walls	Good
C-8	Black duct putty	Assumed	MM	NF-II	HVAC ductwork	Good
C-9	Caulks and sealants	Assumed	MM	NF-II	All original caulks and sealants	Good
C-10	Mortars	Assumed	MM	NF-II	All block and brick walls	Good
C-11	Ceramic grout	Assumed	MM	NF-I	Ceramic tiled areas	Good
C-12	Fire doors	Assumed	MM	NF-II	Boiler room and other tagged fire doors	Good
C-13	Concrete	Assumed	MM	NF-II	All concrete	Good
C-14	Roofing	Assumed	MM	NF-I	Exterior roof (roof caulk 15%)	Good
C-15	Mudded fittings and roof drains	Yes	TSI	F	Above ceilings and in walls	Good

### FRIABILITY:

MATERIAL TYPE:

#### F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II

#### TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

# **CONDITION:**

Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

# APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS CAMPUS ELEMENTARY SCHOOL INSPECTION DATE: JANUARY 4<sup>th</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
C-16	Black window sills	Assumed	MM	NF-I	Interior window sills	Good
C-17	Divider walls	Assumed	MM	NF-II	Rooms with divider walls	Good

# FRIABILITY:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II

#### MATERIAL TYPE:

TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

#### **CONDITION:**

Good: Little or no damage

Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

This page has been left blank intentionally

January 23<sup>rd</sup>, 2019 Project Number: MA-158-18

Mr. Marc Bennett Grand Rapids Public Schools 900 Union, NE Grand Rapids, MI 49503

Re: AHERA 3 Year Reinspection Report Grand Rapids Public Schools – Campus Elementary School 119 West Cass Street P.O. Box 908 Grand Rapids, MI 48838 Phone: 616-302-0819 Web: microairconsulting.com Email: microairconsulting@gmail.com

Consulting, LLC

Dear Mr. Bennett:

MicroAir Consulting, LLC (MicroAir) was retained by Grand Rapids Public Schools (GRPS), to conduct an AHERA 3-year reinspection of Campus Elementary School (C) located at 710 Benjamin Avenue SE in Grand Rapids, Michigan. The inspection was conducted according to the protocol described in the U.S. Environmental Protection Agency Asbestos Hazard Emergency Response Act of 1986 (40 CFR 763).

### CERTIFICATION

The building inspection was conducted on January 4<sup>th</sup>, 2019 by Mr. Grant Edgerly, a State of Michigan accredited Asbestos Building Inspector. Mr. Edgerly's, Accreditation Number is A41792.

### **REGULATORY BACKGROUND**

As a public and commercial building, Campus is governed by 29 CFR 1910.1001, Occupational Health Standards for Asbestos in Construction/General Industry and the EPA's NESHAP for the normal course of business activities by GRPS employees and occupants.

There are three state agencies in Michigan that regulate asbestos in Michigan: the Michigan Department of Environmental Quality (DEQ), the Michigan Department of Licensing and Regulatory Affairs (DLARA) and the Michigan Department of State Police (MSP). The DEQ is concerned about the release of asbestos fibers to the outer air and proper waste disposal, while DLARA focuses on worker protection during renovation and demolition activities, contractor licensing, and worker training.

During construction or renovation activities, the persons performing those activities would be governed by 29 CFR 1926.1101, Occupational Health Standards for Asbestos in Construction. The Asbestos Hazard Emergency Response Act (AHERA), 40 CFR 763, (partial) and/or its associated requirements. However, there are some portions of AHERA that are used as guidelines for compliance with 29 CFR 1910.1001. In particular, 29 CFR 1910.1001(j)(1) requires owners of buildings constructed prior to 1980 to presume that certain types of building materials are asbestos-containing materials (ACM), unless the owner demonstrates that those materials are not ACM.

40 CFR Part 61, Subpart M (NESHAP) requires that a thorough inspection be conducted prior to all renovations and all demolitions. A thorough inspection for asbestos is required no matter the age of the facility because all uses of asbestos are not banned. The inspection must be completed before the commencement of a subject renovation and/or demolition activity.

### BUILDING DESCRIPTION

The Campus Elementary School building was constructed in 1970's. Some building renovations have occurred throughout over the years as well.

## PREVIOUS INSPECTION

The most recent inspection was conducted by GRPS in 2018. MicroAir reviewed this report and incorporated the findings of the previous inspection and historical information into the current reinspection data.

In the previous inspection report suspect ACM materials were given a unique identification number (homogeneous material number), MicroAir has changed numbering from previous reports. The reinspection

did include the collection of bulk samples. Results of the sampling can be found in Appendix A along with locations of remaining ACM in the building.



# **REINSPECTION PROCEDURES**

With the assistance of GRPS maintenance staff, MicroAir re-inspected known and previously identified areas of the building including above suspended ceilings, pipe chases, and inside the tunnels.

It was beyond the scope of this reinspection to locate, identify, or quantify ACM in areas that were concealed and/or inaccessible areas, such as within walls, hard ceilings, or equipment.

## 2019 REINSPECTION FINDINGS

The following suspect asbestos-containing materials were observed at Campus Elementary School during the asbestos inspection and the bulk sampling. Materials in **bold** were found to be greater than 1% ACM.

- Drywall, tape, and mud
- Plaster
- Sink undercoating
- Cream w/color spots 12"x12" Floor tile w/mastic
- 2'x2' Ceiling tile
- Cream cove base w/mastic
- Gray cove base w/mastic
- Black duct putty
- Caulks and sealants
- Mortars
- Ceramic grout
- Fire doors
- Concrete
- Roofing
- Mudded fittings and drains
- Black window sills
- Divider walls

Some of the materials listed above are assumed to contain asbestos until bulk samples can be collected and analyzed.

Appendix A of this report is a table that identifies the confirmed and suspect ACM homogeneous materials in Campus, their corresponding identification number and locations, and the general condition of ACMs identified during the reinspection.

## CONCLUSIONS AND RECOMMENDATIONS

MicroAir was retained by Grand Rapids Public Schools to conduct a 3-year asbestos-containing material (ACM) reinspection of Campus Elementary School located at 710 Benjamin Avenue SE in Grand Rapids, Michigan. MicroAir completed the reinspection on January 4<sup>th</sup>, 2019. The inspection was conducted by a State of Michigan accredited Asbestos Building Inspector.

During the reinspection, MicroAir identified and assessed 17 homogeneous materials remaining in Campus Elementary School.

Any personnel entering a tunnel or chase area must be notified of ACM locations and explained the requirement to wear personal protective equipment.

If GRPS plans to conduct any renovation or demolition, the identified ACMs should be removed by a licensed asbestos abatement contractor, as required by current federal, state, and local laws and regulations, should perform any necessary removal and disposal of the identified ACM. MicroAir notes that if suspect ACM other than those identified during this reinspection are encountered during any renovation or demolition, such materials should be sampled and analyzed using PLM to verify presence of asbestos.

We also recommend that visual observations, verification of removal and cleanup, and air monitoring or clearance air monitoring for asbestos fibers be performed by a third party retained by GRPS to demonstrate

compliance with applicable regulations, and to confirm the suitability or the area for re-entry. MicroAir can perform these services.



Warning labels should be affixed in all non-public areas where ACM or assumed ACM is present. After completion of repairs or removal of the ACM, fill out an O&M Activities Form and file it in the management plan.

As required by AHERA, GRPS should continue to send the annual notifications including information on planned response actions and reinspections. Copies of the notifications should be kept in the Management Plan.

# LIMITATIONS

The conclusions drawn from the observations and sample results are only valid for the time the observations occurred. In the process of gathering the field data included in this report, procedures were followed that represent reasonable and acceptable industrial hygiene practices and procedures in a manner consistent with the level of care and skill ordinarily exercised by other members of this profession currently practicing under similar conditions. However, the information and opinions provided in this report are not to be construed as a warranty of the conditions of this site in any way, implied or explicit. MicroAir accepts no responsibility for the use, interpretation, or reliance by other parties on the information contained herein, nor does this report represent an instrument of regulatory compliance or an asbestos abatement specification.

In conducting the reinspection there are a number of obstacles and limitations that can affect the final outcome of the report. These limitations include but are not limited to the following factors: access concerns, materials that can not be intrusively sampled or damaged, materials that have been replaced by renovation activities, materials with conflicting laboratory results, and materials that are located in inaccessible and/or concealed areas which limits its quantification. Due to these limitations, the results of this investigation cannot be construed as a certification of the presence or absence of ACM, beyond the materials identified, but rather a diligent and prudent review of available data within an established work scope, and time and budgetary constraints.

If you have any questions or require additional information, please contact me at 616-302-0819 or microairconsulting@gmail.com. Thank you.

Sincerely,

MicroAir Consulting, LLC

isten T. Decker

Christian T. Decker Accredited Building Inspector and Management Planner

# **APPENDIX A**

# TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS

# **APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS** CAMPUS ELEMENTARY SCHOOL **INSPECTION DATE: JANUARY 4th, 2019**



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
C-1	Drywall, tape, and mud	No	SM		Walls and ceilings	
C-2	Plaster	No	SM		Walls and ceilings	
C-3	Sink undercoating	Assumed	MM	NF-II	Metal sinks	Good
C-4	Cream w/color spots 12"x12" Floor tile w/mastic	Assumed	MM	NF-I	Interior flooring	Good
C-5	2'x2' Ceiling tile	Assumed	MM	NF-II	Ceilings on grid	Good
C-6	Cream cove base w/mastic	Assumed	MM	NF-II	Interior walls	Good
C-7	Gray cove base w/mastic	Assumed	MM	NF-II	Interior walls	Good
C-8	Black duct putty	Assumed	MM	NF-II	HVAC ductwork	Good
C-9	Caulks and sealants	Assumed	MM	NF-II	All original caulks and sealants	Good
C-10	Mortars	Assumed	MM	NF-II	All block and brick walls	Good
C-11	Ceramic grout	Assumed	MM	NF-I	Ceramic tiled areas	Good
C-12	Fire doors	Assumed	MM	NF-II	Boiler room and other tagged fire doors	Good
C-13	Concrete	Assumed	MM	NF-II	All concrete	Good
C-14	Roofing	Assumed	MM	NF-I	Exterior roof (roof caulk 15%)	Good
C-15	Mudded fittings and roof drains	Yes	TSI	F	Above ceilings and in walls	Good

#### FRIABILITY: F: Friable

MATERIAL TYPE:

#### TSI: Thermal System Insulation NF-I: Non-friable Category I SM: Surfacing Material NF-II: Non-friable Category II MM: Miscellaneous Material

## CONDITION:

Good: Little or no damage

Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

# APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS CAMPUS ELEMENTARY SCHOOL INSPECTION DATE: JANUARY 4<sup>th</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
C-16	Black window sills	Assumed	MM	NF-I	Interior window sills	Good
C-17	Divider walls	Assumed	MM	NF-II	Rooms with divider walls	Good

# FRIABILITY:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II

#### MATERIAL TYPE:

TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

#### CONDITION:

Good: Little or no damage

Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

This page has been left blank intentionally

October 25<sup>th</sup>, 2019 Project Number: MA-117-19

Mr. Marc Bennett Grand Rapids Public Schools 900 Union, NE Grand Rapids, MI 49503

Re: AHERA 3-Year Reinspection Report Grand Rapids Public Schools – **City High Middle School** 

Dear Mr. Bennett:



119 West Cass Street P.O. Box 908 Grand Rapids, MI 48838 Phone: 616-302-0819 Web: microairconsulting.com Email: microairconsulting@gmail.com

MicroAir Consulting, LLC (MicroAir) was retained by Grand Rapids Public Schools (GRPS), to conduct an AHERA 3-year reinspection of City High Middle School (CHMS) located at 1720 Plainfield Ave NE in Grand Rapids, Michigan. The inspection was conducted according to the protocol described in the U.S. Environmental Protection Agency Asbestos Hazard Emergency Response Act of 1986 (40 CFR 763).

# CERTIFICATION

The building inspection was conducted on October 25<sup>th</sup>, 2019 by Mr. Chris Decker, a State of Michigan accredited Asbestos Building Inspector. Mr. Decker's, Accreditation Number is A26683.

## **REGULATORY BACKGROUND**

As a public and commercial building, the CHMS is governed by 29 CFR 1910.1001, Occupational Health Standards for Asbestos in Construction/General Industry and the EPA's NESHAP for the normal course of business activities by GRPS employees.

There are three state agencies in Michigan that regulate asbestos: the Michigan Department of Environmental Quality (DEQ), the Michigan Department of Licensing and Regulatory Affairs (DLARA) and the Michigan Department of State Police (MSP). The DEQ is concerned about the release of asbestos fibers to the outer air and proper waste disposal, while DLARA focuses on worker protection during renovation and demolition activities, contractor licensing, and worker training.

During construction or renovation activities, the persons performing those activities would be governed by 29 CFR 1926.1101, Occupational Health Standards for Asbestos in Construction. The Asbestos Hazard Emergency Response Act (AHERA), 40 CFR 763, (partial) and/or its associated requirements. However, there are some portions of AHERA that are used as guidelines for compliance with 29 CFR 1910.1001. In particular, 29 CFR 1910.1001(j)(1) requires owners of buildings constructed prior to 1980 to presume that certain types of building materials are asbestos-containing materials (ACM), unless the owner demonstrates that those materials are not ACM.

40 CFR Part 61, Subpart M (NESHAP) requires that a thorough inspection be conducted prior to all renovations and all demolitions. A thorough inspection for asbestos is required no matter the age of the facility because all uses of asbestos are not banned. The inspection must be completed before the commencement of a subject renovation and/or demolition activity.

## **BUILDING DESCRIPTION**

The City High Middle School building was constructed in 1923 with additions in 1928 and 1980. It is a 3-story building with a large attic space. The building is approximately 200,000 square feet in size. Since its construction, the building has undergone various renovations.

## **PREVIOUS INSPECTION**

The most recent inspection was conducted by GRPS in 2019. MicroAir reviewed this report and incorporated the findings of the previous inspection and historical information into the current reinspection data.

In the previous inspection report suspect ACM materials were given a unique identification number (homogeneous material number), MicroAir has changed numbering from previous reports. The reinspection did

include the collection of bulk samples. Results of the sampling can be found in Appendix A along with locations of remaining ACM in the building.



# **REINSPECTION PROCEDURES**

With the assistance of GRPS maintenance staff, MicroAir re-inspected known and previously identified areas of the building including above suspended ceilings, pipe chases, and inside the tunnels.

It was beyond the scope of this reinspection to locate, identify, or quantify ACM in areas that were concealed and/or inaccessible areas, such as within walls, hard ceilings, or equipment.

# **2019 REINSPECTION FINDINGS**

The following suspect asbestos-containing materials were observed at City High Middle School during the asbestos inspection and the bulk sampling. Materials in **bold** were found to be greater than 1% ACM.

- Wall and ceiling plaster
- Skim coated concrete
- 4th floor ceiling plaster
- 2nd floor mechanical ceiling plaster
- Drywall, tape and mud
- Decorative plaster
- Firebrick
- Firebrick mortar
- Exterior masonry caulk
- 1936 window glazing
- Grey sink undercoating
- Green 9"x9" floor tile w/mastic
- White w/grey streaks 12"x12" floor tile w/mastic
- Blue vinyl stair tread w/mastic
- Tan w/brown streaks 12"x12" floor tile w/mastic
- Blue 12"x12" floor tile w/mastic
- 1'x1' ceiling tile w/glue pod
- Pipe insulation fittings
- Stage rope
- Stage light bar wiring
- 2'x4' drop in ceiling tile
- Spray-on insulation
- Fume hood and vent pipes
- Wood floor underlayment
- Black lab top tables
- Transite panels
- Cove base w/mastic
- Boiler materials
- Tagged fire doors and frames
- Roofing materials
- Brown wall mastic
- Black mastic
- Beige 9"x9" floor tile w/mastic
- Steam water tank insulation
- Incinerator fire brick
- Pink boiler door material
- Boiler cone
- Boiler floor debris
- Heat shield inside radiator
- Ceramic grout
- Fire brick

Many of the ACM materials listed above were removed as part of the 2018-2019 building renovations.

Appendix A of this report is a table that identifies the confirmed and suspect ACM homogeneous materials in CHMS, their corresponding identification number and locations, and the general condition of ACMs identified during the reinspection.



# CONCLUSIONS AND RECOMMENDATIONS

MicroAir was retained by Grand Rapids Public Schools to conduct a 3-year asbestos-containing material (ACM) reinspection of City High Middle School located at 1720 Plainfield Ave NE in Grand Rapids, Michigan. MicroAir completed the reinspection on October 25<sup>th</sup>, 2019. The inspection was conducted by a State of Michigan accredited Asbestos Building Inspector.

During the reinspection, MicroAir identified and assessed 41 homogeneous materials remaining in City High Middle School.

Any personnel entering a tunnel or chase area must be notified of ACM locations and explained the requirement to wear personal protective equipment.

If GRPS plans to conduct any renovation or demolition, the identified ACMs should be removed by a licensed asbestos abatement contractor, as required by current federal, state, and local laws and regulations, should perform any necessary removal and disposal of the identified ACM. MicroAir notes that if suspect ACM other than those identified during this reinspection are encountered during any renovation or demolition, such materials should be sampled and analyzed using PLM to verify presence of asbestos.

We also recommend that visual observations, verification of removal and cleanup, and air monitoring or clearance air monitoring for asbestos fibers be performed by a third party retained by GRPS to demonstrate compliance with applicable regulations, and to confirm the suitability or the area for re-entry. MicroAir can perform these services.

Warning labels should be affixed in all non-public areas where ACM or assumed ACM is present. After completion of repairs or removal of the ACM, fill out an O&M Activities Form and file it in the management plan.

As required by AHERA, GRPS should continue to send the annual notifications including information on planned response actions and reinspections. Copies of the notifications should be kept in the Management Plan.

# LIMITATIONS



The conclusions drawn from the observations and sample results are only valid for the time the observations occurred. In the process of gathering the field data included in this report, procedures were followed that represent reasonable and acceptable industrial hygiene practices and procedures in a manner consistent with the level of care and skill ordinarily exercised by other members of this profession currently practicing under similar conditions. However, the information and opinions provided in this report are not to be construed as a warranty of the conditions of this site in any way, implied or explicit. MicroAir accepts no responsibility for the use, interpretation, or reliance by other parties on the information contained herein, nor does this report represent an instrument of regulatory compliance or an asbestos abatement specification.

In conducting the reinspection there are a number of obstacles and limitations that can affect the final outcome of the report. These limitations include but are not limited to the following factors: access concerns, materials that cannot be intrusively sampled or damaged, materials that have been replaced by renovation activities, materials with conflicting laboratory results, and materials that are located in inaccessible and/or concealed areas which limits its quantification. Due to these limitations, the results of this investigation cannot be construed as a certification of the presence or absence of ACM, beyond the materials identified, but rather a diligent and prudent review of available data within an established work scope, and time and budgetary constraints.

If you have any questions or require additional information, please contact me at 616-302-0819 or microairconsulting@gmail.com. Thank you.

Sincerely,

**MicroAir Consulting, LLC** 

nisten T. Decker

Christian T. Decker Accredited Building Inspector and Management Planner

# **APPENDIX A**

# TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS

# **APPENDIX A – 3-YEAR REINSPECTIONS TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS CITY HIGH MIDDLE SCHOOL INSPECTION DATE: OCTOBER 25th**, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERI AL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
CH-1	Wall and ceiling plaster	No	SM		All 3 floors	
CH-2	Skim coated concrete	No	SM		Stairway walls to 4 <sup>th</sup> floor	
CH-3	4 <sup>th</sup> floor ceiling plaster	No	SM		Fan room ceiling on 4 <sup>th</sup> floor	
CH-4	2 <sup>nd</sup> floor ceiling plaster	No	SM		Mechanical room ceiling on 2 <sup>nd</sup> floor	
CH-5	Drywall, tape and mud	No	SM		Closets on floors 1-3	
CH-6	Decorative plaster	No	SM		Library	
CH-7	Firebrick	No	TSI		Boiler rooms	
CH-8	Firebrick mortar	No	TSI		Boiler rooms	
CH-9	Exterior masonry caulk	Yes	ММ	NF-II	Exterior decorative masonry caps	Good
CH-10	1936 window glazing	No	MM		Art rooms (7), Greenhouse area (5), 2 <sup>nd</sup> floor science area (3), 4 <sup>th</sup> floor (4), (4)	
CH-11	Sink undercoating	Yes	MM	NF-II	REMOVED FROM FLOORS 1-3	
CH-12	Green 9"x9" floor tile w/mastic	Tile- Yes Mastic- No	MM	NF-I	REMOVED FROM FLOORS 1-3	
CH-13	White w/grey streaks 12"x12" floor tile w/mastic	Tile- No Mastic- No	MM		Stairways	
CH-14	Blue vinyl stair tread w/mastic	No	ММ		Stairways	
CH-15	Tan w/brown streaks 12"x12" floor tile w/mastic	Tile- No Mastic- Yes	MM	NF-I	Room 319 (1,400 SF)	Good

#### FRIABILITY: F: Friable

#### MATERIAL TYPE:

# TSI: Thermal System Insulation SM: Surfacing Material

### **CONDITION:**

NF-I: Non-friable Category I NF-II: Non-friable Category II MM: Miscellaneous Material Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

# APPENDIX A – 3-YEAR REINSPECTIONS TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS CITY HIGH MIDDLE SCHOOL INSPECTION DATE: OCTOBER 25<sup>th</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
CH-16	Blue 12"x12" floor tile w/mastic	Tile- No Mastic- No	MM		Classrooms and Storage	
CH-17	1'x1' ceiling tile w/ glue pods	Tile- No Gluepod- No	MM		Floors 1-3	
CH-18	Pipe insulation fittings	Yes	MM	NF-II	REMOVED IN 2018. HIDDEN PIPE INSULATION COULD BE IN WALLS AND CEILINGS	Good
CH-19	Stage rope	Yes	TSI	F	Front stage in Auditorium	Good
CH-20	Stage light bar wiring	Yes	SM	F	Auditorium Room 138	Good
CH-21	2'x4' drop in ceiling tile	No	MM		Ceiling grids on floors 1-3	
CH-22	Spray-on insulation	No	ММ		Kitchen	
CH-23	Fume hood and vent pipes	Yes	TSI	F	REMOVED	
CH-24	Wood floor underlayment	No	TSI	F	All wood floors	Good
CH-25	Black lab top tables	Yes	MM	NF-II	REMOVED	
CH-26	Transite panels	Yes	MM	NF-II	REMOVED	
CH-27	Cove base w/mastic	No	MM		Floors 1-3	
CH-28	Boiler materials	No	TSI		REMOVED	

#### FRIABILITY:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II MATERIAL TYPE: TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

### CONDITION:

Good: Little or no damage

Damaged: Less than  $10^{-6}$  damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

# APPENDIX A – 3-YEAR REINSPECTIONS TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS CITY HIGH MIDDLE SCHOOL INSPECTION DATE: OCTOBER 25<sup>th</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
CH-29	Tagged Fire doors and frames	Yes	ММ	NF-II	Rooms 322 N. door, 346 W. end, 329, 206A (2), 210, 227 (2), 100 N. door, 104 S. hall, 144, 144A, Stage hall, Industrial Arts Rooms 251, 252 N. hall, 254, 256 E. hall, 258 hall, 261 hall.	Good
CH-30	Roofing materials	No	ММ		Exterior roof	
CH-31	Brown wall mastic	No	MM		Holding up boards on 2 <sup>nd</sup> floor	
CH-32	Black mastic	No	MM		Hallway 2 <sup>nd</sup> floor	
CH-33	Beige 9"x9" floor tile w/mastic	Tile- No Mastic- No	ММ		Under cabinets and some lockers	
CH-34	Steam water tank insulation	No	TSI		Corner of boiler room	
CH-35	Incinerator fire brick	No	TSI		Boiler room	
CH-36	Pink boiler door material	No	TSI		Inside boiler	
CH-37	Boiler cone	No	TSI		Inside boiler	
CH-38	Boiler floor debris	No			Boiler room floor	
CH-39	Heat shield inside radiator	Yes	MM	NF-II	REMOVED FROM FLOOR 1 IN 2018. HEAT SHIELDS MAY BE PRESENT IN OTHER AREAS OF THE BUILDING	Good
CH-40	Ceramic grout	No	ММ		Near entryways	-
CH-41	Fire brick	No	MM		Near main entrance	

### FRIABILITY:

MATERIAL TYPE:

### CONDITION:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

# TESTED SUSPECT LEAD-BASED and CAD/CHROM VI PAINT MATERIALS CITY HIGH MIDDLE SCHOOL GRAND RAPIDS, MICHIGAN



SAMPLE NO.	SAMPLE LOCATION	COMPONENT	COLOR	CADMIUM REPORTING LIMIT	CAD (%)	CHROMIUM REPORTING LIMIT	CHROMIUM (VI) (%)	LEAD REPORTING LIMIT	LEAD (%)
CHM-1	Boiler Room	Wall	Gold	0.00075 %	<rl< td=""><td>0.0013 %</td><td>0.056</td><td>0.0025 %</td><td>0.44</td></rl<>	0.0013 %	0.056	0.0025 %	0.44
CHM-2	Boiler Room	Boiler	Silver	0.00075 %	<rl< td=""><td>0.0013 %</td><td>0.029</td><td>0.0025 %</td><td>0.24</td></rl<>	0.0013 %	0.029	0.0025 %	0.24
CHM-3	Boiler Room	Floor	Grey/Red	0.0023 %	<rl< td=""><td>0.0038 %</td><td>0.11</td><td>0.0076 %</td><td>0.80</td></rl<>	0.0038 %	0.11	0.0076 %	0.80
CHM-4	1 <sup>st</sup> floor Hallway	Trim	Blue	0.0048 %	<rl< td=""><td>0.0080 %</td><td><rl< td=""><td>0.016 %</td><td>0.025</td></rl<></td></rl<>	0.0080 %	<rl< td=""><td>0.016 %</td><td>0.025</td></rl<>	0.016 %	0.025
CHM-5	Room 120	Brick	Green/White	0.00075 %	<rl< td=""><td>0.0013 %</td><td>0.012</td><td>0.0025 %</td><td>0.11</td></rl<>	0.0013 %	0.012	0.0025 %	0.11
CHM-6	Room 224	Floor	Clear	0.0031 %	<rl< td=""><td>0.0052 %</td><td><rl< td=""><td>0.010 %</td><td>0.013</td></rl<></td></rl<>	0.0052 %	<rl< td=""><td>0.010 %</td><td>0.013</td></rl<>	0.010 %	0.013
CHM-7	Room 222	Wall	Green/Beige	0.00075 %	<rl< td=""><td>0.0013 %</td><td>0.046</td><td>0.0025 %</td><td>0.35</td></rl<>	0.0013 %	0.046	0.0025 %	0.35
CHM-8	2 <sup>nd</sup> floor Hallway	Wall	Yellow	0.0033 %	<rl< td=""><td>0.0055 %</td><td><rl< td=""><td>0.011 %</td><td><rl< td=""></rl<></td></rl<></td></rl<>	0.0055 %	<rl< td=""><td>0.011 %</td><td><rl< td=""></rl<></td></rl<>	0.011 %	<rl< td=""></rl<>
CHM-9	3 <sup>rd</sup> Floor	Handrail	Blue	0.0087 %	<rl< td=""><td>0.014 %</td><td>2.2</td><td>0.029 %</td><td><rl< td=""></rl<></td></rl<>	0.014 %	2.2	0.029 %	<rl< td=""></rl<>
CHM-10	3 <sup>rd</sup> Floor	Wall	Bright Yellow	0.0099 %	<rl< td=""><td>0.016 %</td><td><rl< td=""><td>0.033 %</td><td><rl< td=""></rl<></td></rl<></td></rl<>	0.016 %	<rl< td=""><td>0.033 %</td><td><rl< td=""></rl<></td></rl<>	0.033 %	<rl< td=""></rl<>
CHM-11	3 <sup>rd</sup> Floor	Wall (Brick)	Yellow	0.0016 %	<rl< td=""><td>0.0027 %</td><td><rl< td=""><td>0.0054 %</td><td><rl< td=""></rl<></td></rl<></td></rl<>	0.0027 %	<rl< td=""><td>0.0054 %</td><td><rl< td=""></rl<></td></rl<>	0.0054 %	<rl< td=""></rl<>
CHM-12	Attic	Stairway Wall	Grey	0.0011 %	<rl< td=""><td>0.0019 %</td><td><rl< td=""><td>0.0038 %</td><td><rl< td=""></rl<></td></rl<></td></rl<>	0.0019 %	<rl< td=""><td>0.0038 %</td><td><rl< td=""></rl<></td></rl<>	0.0038 %	<rl< td=""></rl<>
CHM-13	Attic	Stairs	Green/Grey	0.0086 %	<rl< td=""><td>0.014 %</td><td>0.25</td><td>0.029 %</td><td>1.2</td></rl<>	0.014 %	0.25	0.029 %	1.2
CHM-14	Boiler room	Ceiling	Tan					0.0025 %	0.20

This page has been left blank intentionally

October 24<sup>th</sup>, 2019 Project Number: MA-117-19

Mr. Marc Bennett Grand Rapids Public Schools 900 Union, NE Grand Rapids, MI 49503

Re: AHERA 3 Year Reinspection Report Grand Rapids Public Schools – **Coit Arts Academy** 

Dear Mr. Bennett:

MicroAir Consulting, LLC (MicroAir) was retained by Grand Rapids Public Schools (GRPS), to conduct an AHERA 3-year reinspection of Coit Arts Academy located at 617 Coit Avenue NE in Grand Rapids, Michigan. The inspection was conducted according to the protocol described in the U.S. Environmental Protection Agency Asbestos Hazard Emergency Response Act of 1986 (40 CFR 763).

# CERTIFICATION

The building inspection was conducted on October 18<sup>th</sup>, 2019 by Mr. Ryan Emmons, a State of Michigan accredited Asbestos Building Inspector. Mr. Emmons's, Accreditation Number is A55220.

## **REGULATORY BACKGROUND**

As a public and commercial building, Coit is governed by 29 CFR 1910.1001, Occupational Health Standards for Asbestos in Construction/General Industry and the EPA's NESHAP for the normal course of business activities by GRPS employees and occupants.

There are three state agencies in Michigan that regulate asbestos in Michigan: the Michigan Department of Environmental Quality (DEQ), the Michigan Department of Licensing and Regulatory Affairs (DLARA) and the Michigan Department of State Police (MSP). The DEQ is concerned about the release of asbestos fibers to the outer air and proper waste disposal, while DLARA focuses on worker protection during renovation and demolition activities, contractor licensing, and worker training.

During construction or renovation activities, the persons performing those activities would be governed by 29 CFR 1926.1101, Occupational Health Standards for Asbestos in Construction. The Asbestos Hazard Emergency Response Act (AHERA), 40 CFR 763, (partial) and/or its associated requirements. However, there are some portions of AHERA that are used as guidelines for compliance with 29 CFR 1910.1001. In particular, 29 CFR 1910.1001(j)(1) requires owners of buildings constructed prior to 1980 to presume that certain types of building materials are asbestos-containing materials (ACM), unless the owner demonstrates that those materials are not ACM.

40 CFR Part 61, Subpart M (NESHAP) requires that a thorough inspection be conducted prior to all renovations and all demolitions. A thorough inspection for asbestos is required no matter the age of the facility because all uses of asbestos are not banned. The inspection must be completed before the commencement of a subject renovation and/or demolition activity.

## **BUILDING DESCRIPTION**

The Coit Arts Academy building was constructed in 1880 with additions in 1908, 1922 and 2002. Some building renovations have occurred throughout over the years as well.

## **PREVIOUS INSPECTION**

The most recent inspection was conducted by GRPS. MicroAir reviewed this report and incorporated the findings of the previous inspection and historical information into the current reinspection data.

In the previous inspection report suspect ACM materials were given a unique identification number (homogeneous material number), MicroAir has changed numbering from previous reports. The reinspection did



119 West Cass Street P.O. Box 908 Greenville, MI 48838 Phone: 616-302-0819 Web: microairconsulting.com Email: microairconsulting@gmail.com include the collection of bulk samples. Results of the sampling can be found in Appendix A along with locations of remaining ACM in the building.



# **REINSPECTION PROCEDURES**

With the assistance of GRPS maintenance staff, MicroAir re-inspected known and previously identified areas of the building including above suspended ceilings, pipe chases, and inside the tunnels.

It was beyond the scope of this reinspection to locate, identify, or quantify ACM in areas that were concealed and/or inaccessible areas, such as within walls, hard ceilings, or equipment.

## **2019 REINSPECTION FINDINGS**

The following suspect asbestos-containing materials were observed at Coit Arts Academy School during the asbestos inspection and the bulk sampling. Materials in **bold** were found to be greater than 1% ACM.

- Brick mortar
- Cinderblock mortar
- Concrete
- Roofing
- Fire doors and frames
- Decorative block mortar
- Glass block mortar
- Blue cove base w/mastic
- Cream 12"x12" Floor tile w/mastic
- Wood floor underlayment
- Cream cove base w/mastic
- Ceramic grout
- 2'x4' drop ceiling tile smooth
- 2'x2' drop ceiling tile w/holes
- Wall plaster
- Textured drywall
- Ceiling plaster
- Drywall, tape and mud
- Black cove base w/mastic
- Smooth wall plaster
- Sink undercoating
- Divider wall
- Gray 12"x12" Floor tile w/mastic
- Drywall, tape and mud- downstairs
- Drywall, tape and mud- main floor

Some of the materials listed above are assumed to contain asbestos until bulk samples can be collected and analyzed.

Appendix A of this report is a table that identifies the confirmed and suspect ACM homogeneous materials in Coit Arts Academy, their corresponding identification number and locations, and the general condition of ACMs identified during the reinspection.

# CONCLUSIONS AND RECOMMENDATIONS

MicroAir was retained by Grand Rapids Public Schools to conduct a 3-year asbestos-containing material (ACM) reinspection of Coit Arts Academy located at 617 Coit Avenue NE in Grand Rapids, Michigan. MicroAir completed the reinspection on October 18<sup>th</sup>, 2019. The inspection was conducted by a State of Michigan accredited Asbestos Building Inspector.

During the reinspection, MicroAir identified and assessed 25 homogeneous materials remaining in Coit Arts Academy. Any personnel entering a tunnel or chase areas must be notified of ACM locations and explained



the requirement to wear personal protective equipment.

If GRPS plans to conduct any renovation or demolition, the identified ACMs should be removed by a licensed asbestos abatement contractor, as required by current federal, state, and local laws and regulations, should perform any necessary removal and disposal of the identified ACM. MicroAir notes that if suspect ACM other than those identified during this reinspection are encountered during any renovation or demolition, such materials should be sampled and analyzed using PLM to verify presence of asbestos.

We also recommend that visual observations, verification of removal and cleanup, and air monitoring or clearance air monitoring for asbestos fibers be performed by a third party retained by GRPS to demonstrate compliance with applicable regulations, and to confirm the suitability or the area for re-entry. MicroAir can perform these services.

Warning labels should be affixed in all non-public areas where ACM or assumed ACM is present. After completion of repairs or removal of the ACM, fill out an O&M Activities Form and file it in the management plan.

As required by AHERA, GRPS should continue to send the annual notifications including information on planned response actions and reinspections. Copies of the notifications should be kept in the Management Plan.

# LIMITATIONS

The conclusions drawn from the observations and sample results are only valid for the time the observations occurred. In the process of gathering the field data included in this report, procedures were followed that represent reasonable and acceptable industrial hygiene practices and procedures in a manner consistent with the level of care and skill ordinarily exercised by other members of this profession currently practicing under similar conditions. However, the information and opinions provided in this report are not to be construed as a warranty of the conditions of this site in any way, implied or explicit. MicroAir accepts no responsibility for the use, interpretation, or reliance by other parties on the information contained herein, nor does this report represent an instrument of regulatory compliance or an asbestos abatement specification.

In conducting the reinspection there are a number of obstacles and limitations that can affect the final outcome of the report. These limitations include but are not limited to the following factors: access concerns, materials that cannot be intrusively sampled or damaged, materials that have been replaced by renovation activities, materials with conflicting laboratory results, and materials that are located in inaccessible and/or concealed areas which limits its quantification. Due to these limitations, the results of this investigation cannot be construed as a certification of the presence or absence of ACM, beyond the materials identified, but rather a diligent and prudent review of available data within an established work scope, and time and budgetary constraints.

If you have any questions or require additional information, please contact me at 616-302-0819 or microairconsulting@gmail.com. Thank you.

Sincerely,

**MicroAir Consulting, LLC** 

isten T. Decker

Christian T. Decker Accredited Building Inspector and Management Planner

# **APPENDIX A**

# TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS

# APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS COIT ARTS ACADEMY INSPECTION DATE: OCTOBER 18th, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
Coit-1	Brick mortar	Assumed	MM	NF-II	Brick walls	Good
Coit-2	Cinderblock mortar	Assumed	MM	NF-II	Cinderblock walls	Good
Coit-3	Concrete	Assumed	MM	NF-II	All concrete	Good
Coit-4	Roofing	Assumed	MM	NF-I	Exterior asphalt roof	Good
Coit-5	Fire doors and frames	Yes	MM	NF-II	Boiler room and other tagged fire doors	Good
Coit-6	Decorative block mortar	Assumed	MM	NF-II	Exterior decorative block	Good
Coit-7	Glass block mortar	Assumed	MM	NF-II	Glass block areas	Good
Coit-8	Blue cove base w/mastic	Assumed	MM	NF-II	Hallways and stairways	Good
Coit-9	Cream 12"x12" Floor tile w/mastic	Assumed	MM	NF-I	Hallways and stairways	Good
Coit-10	Wood floor underlayment	Assumed	MM	NF-I	Under wood floors- Gym	Good
Coit-11	Cream cove base w/mastic	Assumed	MM	NF-II	Gym storage, receiving, storage and mechanical	Good
Coit-12	Ceramic grout	Assumed	MM	NF-I	Bathrooms and Locker rooms	Good
Coit-13	2'x4' drop ceiling tile smooth	Assumed	MM	NF-II	Locker rooms	Good
Coit-14	2'x2' drop ceiling tile w/holes	Assumed	MM	NF-II	Classrooms, hallways and kitchen	Good
Coit-15	Wall plaster	No	SM	F	Boiler room	Good
Coit-16	Textured drywall	No	SM	F	Boiler room	Good

### FRIABILITY:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II

#### MATERIAL TYPE:

TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

### CONDITION:

Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area



# **APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS COIT ARTS ACADEMY INSPECTION DATE: OCTOBER 18th, 2019**

HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
Coit-17	Ceiling plaster	No	SM	F	Boiler room	Good
Coit-18	Drywall, tape and mud	No	SM	F	Interior walls and tunnels	Good
Coit-19	Black cove base w/mastic	Assumed	MM	NF-II	Stairways	Good
Coit-20	Smooth wall plaster	No	SM	F	Interior walls main floor	Good
Coit-21	Sink undercoating	Assumed	MM	NF-II	Tunnels	Good
Coit-22	Divider wall	Assumed	MM	NF-II	Top floor and gym stage	Good
Coit-23	Gray 12"x12" Floor tile w/mastic	Assumed	MM	NF-I	Kitchen and office area	Good
Coit-24	Drywall, tape and mud	No	SM	F	Downstairs kitchen	Good
Coit-25	Drywall, tape and mud	No	SM	F	Main floor	Good

### FRIABILITY:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II

#### MATERIAL TYPE:

TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

#### CONDITION:

Good: Little or no damage

Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

This page has been left blank intentionally

November 12<sup>th</sup>, 2019 Project Number: MA-117-19

Mr. Marc Bennett Grand Rapids Public Schools 900 Union, NE Grand Rapids, MI 49503

Re: AHERA 3 Year Reinspection Report Grand Rapids Public Schools – Ottawa Hills High School

Dear Mr. Bennett:



119 West Cass Street P.O. Box 908 Greenville, MI 48838 Phone: 616-302-0819 Email: microairconsulting@gmail.com

MicroAir Consulting, LLC (MicroAir) was retained by Grand Rapids Public Schools (GRPS), to conduct an AHERA 3-year reinspection of Ottawa Hills High School (OHHS) located at 2055 Rosewood SE in Grand Rapids, Michigan. The inspection was conducted according to the protocol described in the U.S. Environmental Protection Agency Asbestos Hazard Emergency Response Act of 1986 (40 CFR 763).

## CERTIFICATION

The building inspection was conducted on November 29<sup>th</sup>, 2019 by Mr. Grant Edgerly, a State of Michigan accredited Asbestos Building Inspector. Mr. Edgerly's, Accreditation Number is A41792.

## **REGULATORY BACKGROUND**

As a public school and/or a commercial building, Ottawa Hills is governed by 29 CFR 1910.1001, Occupational Health Standards for Asbestos in Construction/General Industry and the EPA's NESHAP and AHERA for the normal course of business activities by GRPS employees.

There are three state agencies in Michigan that regulate asbestos: the Michigan Department of Environmental Quality (DEQ), the Michigan Department of Licensing and Regulatory Affairs (DLARA) and the Michigan Department of State Police (MSP). The DEQ is concerned about the release of asbestos fibers to the outer air and proper waste disposal, while DLARA focuses on worker protection during renovation and demolition activities, contractor licensing, and worker training.

During construction or renovation activities, the persons performing those activities would be governed by 29 CFR 1926.1101, Occupational Health Standards for Asbestos in Construction. The Asbestos Hazard Emergency Response Act (AHERA), 40 CFR 763, (partial) and/or its associated requirements. However, there are some portions of AHERA that are used as guidelines for compliance with 29 CFR 1910.1001. In particular, 29 CFR 1910.1001(j)(1) requires owners of buildings constructed prior to 1980 to presume that certain types of building materials are asbestos-containing materials (ACM), unless the owner demonstrates that those materials are not ACM.

40 CFR Part 61, Subpart M (NESHAP) requires that a thorough inspection be conducted prior to all renovations and all demolitions. A thorough inspection for asbestos is required no matter the age of the facility because all uses of asbestos are not banned. The inspection must be completed before the commencement of a subject renovation and/or demolition activity.

## **BUILDING DESCRIPTION**

The Ottawa Hills High School building was constructed in 1960 with an addition added to the school in 1972. Some building renovations have occurred throughout OHHS over the years.

## **PREVIOUS INSPECTION**

The most recent inspection was conducted by MicroAir in 2018. MicroAir reviewed this report and incorporated the findings of the previous inspection and historical information into the current reinspection data.

In the previous inspection report suspect ACM materials were given a unique identification number (homogeneous material number), MicroAir has changed numbering from previous reports. The reinspection did include the collection of bulk samples. Results of the sampling can be found in Appendix A along with locations and estimated quantities of remaining ACM in the building.

# **REINSPECTION PROCEDURES**



With the assistance of GRPS maintenance staff, MicroAir re-inspected known and previously identified areas of the building including above suspended ceilings, pipe chases, and inside the tunnels.

The reinspection was performed based on the requirements outlined in AHERA, NESHAP, and the Occupational Safety and Administration (OSHA) Asbestos in Construction Standard 29 CFR 1926.1101.

The reinspection was conducted in a room-by-room fashion. Homogeneous material/areas (HSA) numbers were arbitrarily selected depending on when they were first identified. The number of samples collected from each homogeneous material was determined depending on the type of material. Samples were collected from discrete locations.

It should be noted that it was beyond the scope of this inspection to locate, identify, or quantify suspect ACM in concealed and/or inaccessible areas, such as within walls, ceilings, or equipment (e.g., boiler, motors, etc.). However, areas above most suspended ceilings were observed where access was feasible. MicroAir did not test roofing materials due to the destructive nature of testing. MicroAir will sample the roofing materials at the request of GRPS.

Samples collected by MicroAir were taken in locations randomly selected by the inspector at the time of the inspection. All layers of the submitted sample were analyzed, and the lab was not instructed to discontinue analyzing the homogeneous material when asbestos was found in a sample.

Bulk samples were analyzed by Polarized Light Microscopy (PLM) using EPA Method 600/R-93/116 with gravimetric reduction (if required).

# **2019 REINSPECTION FINDINGS**

At the time of the ACM reinspection, MicroAir identified the following 32 known or suspect ACM homogeneous materials remaining in Ottawa Hills High School. Materials in **bold** were found to be greater than 1% ACM.

- Tan 12"x12" floor tile with associated mastic
- 9"x9" floor tile and associated mastic
- Smooth Ceiling Plaster
- Ceiling decorative plaster (fireproofing)
- Mudded fittings on fiberglass pipe insulation including roof drains
- Aircell pipe insulation
- Textured ceiling plaster
- Wall boards and glue pods
- Wood floor underlayment and mastic
- Stucco panels
- Vinyl stair treads
- White suspended ceiling tile
- Vinyl cove base
- Sink undercoating
- Rolled-on flooring
- Transite
- Stage curtains/ropes
- Window glazing
- Vibration dampener
- Duct insulation
- Drywall, tape and mud
- Fire doors and frames
- Boiler room ceiling
- 1"x1" Splined-on ceiling tile pins and fissures
- 2'x2' Ceiling tile
- Flooring under carpet
- 12"x12" Olive floor tile w/mastic
- Brick mortar
- Ceramic grout
- Block mortar
- 2'x4' Ceiling tile
- Pipe gasket

Some of the materials listed above are assumed to contain asbestos until bulk samples can be collected and analyzed.



The AHERA Priority Assessment ranking is Category 1 (damaged or significantly damaged thermal systems insulation or TSI) for the Aircell pipe insulation in rooms 274. The AHERA Priority Assessment ranking for the mudded pipe fittings in rooms 274B, 269E and 266 are a Category 1 (damaged or significantly damaged thermal systems insulation or TSI). It should be a priority to cleanup and patch these areas.

Appendix A of this report is a table that identifies the confirmed and suspect ACM homogeneous materials in OHHS, their corresponding identification number, estimated quantities and locations, and the general condition of ACMs identified during the reinspection.

# CONCLUSIONS AND RECOMMENDATIONS

MicroAir was retained by Grand Rapids Public Schools to conduct a 3-year asbestos-containing material (ACM) reinspection of Ottawa Hills High School located at 2055 Rosewood SE in Grand Rapids, Michigan. MicroAir completed the reinspection on November 29<sup>th</sup>, 2019. The inspection was conducted by a State of Michigan accredited Asbestos Building Inspector.

During the reinspection, MicroAir identified and assessed 32 homogeneous materials remaining in Ottawa Hills High School. Various areas of damaged ACM were noted during the reinspection.

These areas where ACM should be cleaned, repaired or removed include:

- Aircell pipe insulation in Room 274
- Mudded pipe fittings on fiberglass pipe insulation in 274B (5), 269E (20) and 266 (20)

The AHERA Priority Assessment ranking is category 1 (damaged or significantly damaged thermal systems insulation or TSI) for the Aircell pipe insulation in rooms 274. The AHERA Priority Assessment ranking for the Mudded pipe fittings in rooms 274B, 269E and 266 are a category 1 (damaged or significantly damaged thermal systems insulation or TSI). It should be a priority to cleanup and patch these areas.

Any personnel entering the tunnel or chase areas must be notified of ACM locations and explained the requirement to wear personal protective equipment.

If GRPS plans to conduct any renovation or demolition, the identified ACMs should be removed by a licensed asbestos abatement contractor, as required by current federal, state, and local laws and regulations, should perform any necessary removal and disposal of the identified ACM. MicroAir notes that if suspect ACM other than those identified during this reinspection are encountered during any renovation or demolition, such materials should be sampled and analyzed using PLM to verify presence of asbestos.

We also recommend that visual observations, verification of removal and cleanup, and air monitoring or clearance air monitoring for asbestos fibers be performed by a third party retained by GRPS to demonstrate compliance with applicable regulations, and to confirm the suitability or the area for re-entry. MicroAir can perform these services.

Warning labels should be affixed in all non-public areas where ACM or assumed ACM is present. After completion of repairs or removal of the ACM, fill out an O&M Activities Form and file it in the management plan.

As required by AHERA, GRPS should continue to send the annual notifications including information on planned response actions and reinspections. Copies of the notifications should be kept in the Management Plan.

# LIMITATIONS



In conducting the reinspection there are a number of obstacles and limitations that can affect the final outcome of the report. These limitations include but are not limited to the following factors: access concerns, materials that cannot be intrusively sampled or damaged, materials that have been replaced by renovation activities, materials with conflicting laboratory results, and materials that are located in inaccessible and/or concealed areas which limits its quantification. Due to these limitations, the results of this investigation cannot be construed as a certification of the presence or absence of ACM, beyond the materials identified, but rather a diligent and prudent review of available data within an established work scope, and time and budgetary constraints.

If you have any questions or require additional information, please contact me at 616-302-0819 or microairconsulting@gmail.com.

Sincerely,

**MicroAir Consulting, LLC** 

ister T. Decker

Christian T. Decker Accredited Building Inspector and Management Planner

Enclosures



# **APPENDIX A**

# TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS

# APPENDIX A TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS OTTAWA HILLS HIGH SCHOOL INSPECTION DATE: NOVEMBER 29<sup>th</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA / (ESTIMATED QUANTITY)	CONDITION
OHHS-1	Tan 12"x12" floor tile with associated mastic	Tile – No Mastic –No	ММ		Cafeteria, 274, 268, 257, 251, 238, 237, 237A, 237B, 244, Skywalk to south house, 167, 169J, 164, 137, 202, 201A, Auditorium orchestra pit, stage stairway to music room, 203, 233, 236, North House - 110 <b>(&gt;10K square feet)</b>	
OHHS-2	9"x9" floor tile and associated mastic	Tile – <b>Yes</b> Mastic – No	ММ	NF-I	141 (40 square feet), Stage stairway to music room (25 square feet), Pool Balcony Landing (150 square feet), Skywalk (120 square feet)	Good
OHHS-3	Smooth Ceiling Plaster	Skim Coat – No Base Coat – No	SM		276, 276A, 275, 273, 262, 270, Boiler room adjacent to 274, 146A, 268, Girls and Boys bath near 256, 258, 259B-D, 251, 238, 239, 240, 244, Small gym upper fan room, 157, 154, Tunnel under Pool, 159, Boys and Girls locker room, 164, 143, 137, Weight room stairway, 202, 200, Auditorium, Stage, 208, 233, 234 (>10K square feet)	
OHHS-4	Ceiling decorative plaster (fireproofing)	No	SM		273, Café serving, 269E, 260, 257, 259A, Hallway near 251 <b>(6K square feet)</b>	
OHHS-5	Mudded fittings on fiberglass pipe insulation including roof drains	Yes	TSI	F	274B <b>(5)</b> , 269 <b>F</b> , <b>(20)</b> , 266 <b>(20)</b> , 269 (34), 256 (4), 260 (20), Girls and Boys bath near 256 (30), 257, (10), 269B (15), 258 (5), 259A (30), Hallway near 251 (200), 249G (20), 238 (15), 299o near office (12), 240 (10), 237 (16), 242 (10), 245 (15), 248 (25), 246 (10), 244 (10), 253 (6), 255 (40), Skywalk (10), Gym boiler/fan room (100), 157 (10), Tunnel under pool (45), Pool heater room (21), 159 (20), 167 (10), 160 (20), Lower gym (12), 164 (gym) (28), 147 (small gym) (12), Boys and Girls locker room (40), Tunnel under athletic areas (20), 164 A-B (20), 137 (30), 134 (13), 136 (20), 133 (5), 137 (10), Auditorium loft (74), 203 (20), 208 (125), 233 (30), 236 (15), 236A (10), 234 (20), Tunnel around North and South Houses, South and North House 3 <sup>rd</sup> Floor above ceilings	Damage- Tunnel
OHHS-6	Aircell pipe insulation	Yes	TSI	F	274 (12), 27B (15), Boiler Room adjacent to 274 (100), 146A (15), 266 (20), Boys and Girls bathrooms near 256 (40), 258 (25), 239 (350), 240 (50), Small gym upper fan room (120), Tunnel under athletic areas (100), Tunnel under boiler room 144 (200), 137 (50)	Damage in 274, 258

#### FRIABILITY: F: Friable

MATERIAL TYPE:

TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

#### **CONDITION:**

Good: Little or no damage

Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

SF: Square feet LF: Linear feet

FT: Fittings NQ: Not Quantified

MicroAir Project No. MA-117-19

NF-I: Non-friable Category I

NF-II: Non-friable Category II

# APPENDIX A TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS OTTAWA HILLS HIGH SCHOOL INSPECTION DATE: NOVEMBER 29<sup>th</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA / (ESTIMATED QUANTITY)	CONDITION
OHHS-7	Textured ceiling plaster	No	SM		Auditorium (9,000 SF)	
OHHS-8	Glue pods associated with wall boards	Yes	MM	NF-II	Classrooms, offices, hallways and associated rooms (25)	Good
OHHS-9	Wood floor underlayment and mastic	No	MM		209A-C (2K SF), Auditorium stage (2K SF), Under Gym floor (13,000 SF)	
OHHS-10	Stucco panels	No	SM	-	Auditorium walls (>10K SF)	
OHHS-11	Vinyl stair treads	No	MM		Large gym <b>(400 SF)</b> , 201A <b>(10 SF)</b>	
OHHS-12	White suspended ceiling tile	No	MM		273, 269A-E, 256, 266, 265, 260, 257, 259A, 249A-G, 238, 242, 248, 253 and 154 (pool area). <b>(&gt;10K SF)</b>	
OHHS-13	Vinyl cove base	No	ММ		269A-E, 266, 265, 269, 256, 260, 257, 269B, 252A, 259A, 251, 249A-E, 238, 237A-B, 242, 244, 254, 159, 160, 167, locker rooms, 164A-B, 141, 137, 202, 201A, 203, 233, 236 and 234. (>2K LF)	
OHHS-14	Sink undercoating	Yes	ММ	NF-II	269, 269D, 269E, 260, 257, 249G, 248, 164 and 164B. (9 total)	Good
OHHS-15	Rolled-on flooring	Yes	MM	NF-II	234 Bookstore (removed in 2019)	
OHHS-16	Transite	Yes	MM	NF-I	249A-E, 203 and 233. (1000 SF)	Good
OHHS-17	Stage curtains/ropes	No	MM		Auditorium (>1000 LF)	
OHHS-18	Window glazing	Yes	MM	NF-II	237А-В.	Good
OHHS-19	Vibration dampener	No	MM		274, 239, 147 upper room and 208. (200 LF)	

### FRIABILITY:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II MATERIAL TYPE: TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

### **CONDITION:**

Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area
## APPENDIX A TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS OTTAWA HILLS HIGH SCHOOL INSPECTION DATE: NOVEMBER 29<sup>th</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA / (ESTIMATED QUANTITY)	CONDITION
OHHS-20	Duct insulation	Yes	TSI	F	147 upper room and Boiler room. (900 SF)	Good
OHHS-21	Boiler insulation and components	Yes	TSI		Removed in 2018	
OHHS-22	Drywall, tape and mud	No	ММ		Classrooms, offices, hallways and associated rooms. (>10,000 SF)	
OHHS-23	Fire doors and frames	Yes	ММ	NF-II	276, 276A, 275, 273, Boiler room, 146A (3), 257, 239, 248, 253, 254, 147 upper room, 132, 133, 134, 136, 137, tunnel doors, 267, 269, 260, 252A, 252B, 249E, 249C, 237, 242, 243, 245, 247, 209, 205, 232, 214A, 299X, 322, 301B, 325, 102, 103, 103A, 191, 195, 130C, 130E, 182A, 277, 278B, 299G, 330, 331B, 359, 157 and 156. <b>(&lt;100 total)</b>	Good
OHHS-24	Roofing	Assumed	ММ	NF-I	Roofing	Good
OHHS-24A	Boiler door gasket	Yes	TSI		Removed in 2018	
OHHS-25	Boiler blower gasket	Yes	TSI		Removed in 2018	
OHHS-26	Boiler inner glazing	No	TSI		Removed in 2018	
OHHS-27	Boiler cement	No	TSI		Removed in 2018	
OHHS-28	Boiler door mud	No	TSI		Removed in 2018	
OHHS-29	Boiler port hole mud	No	TSI		Removed in 2018	
OHHS-30	Boiler jacket lag cloth	No	TSI		Removed in 2018	
OHHS-31	Inner boiler – red mud	No	TSI		Removed in 2018	
OHHS-32	Inner boiler - white brick	No	TSI		Removed in 2018	
OHHS-33	Upper tank insulation	No	TSI		Removed in 2018	
OHHS-34	Outer boiler insulation	No	TSI		Removed in 2018	
OHHS-35	Lower boiler insulation	No	TSI		Removed in 2018	
OHHS-36	Boiler door gasket	No	TSI		Removed in 2018	
OHHS-37	Boiler end insulation	No	TSI		Removed in 2018	
OHHS-38	Inner boiler troweled insulation	No	TSI		Removed in 2018	
OHHS-39	Boiler concrete liner	No	TSI		Removed in 2018	

OHHS-40	Boiler inner brick	No	TSI		Removed in 2018	
OHHS-41	Inner boiler gasket	No	TSI		Removed in 2018	
OHHS-42	Inner boiler caulk	No	TSI		Removed in 2018	
OHHS-43	Active boiler pad	No	TSI		Removed in 2018	
OHHS-44	Underground transite pipe	Yes	TSI		Removed in 2018	
OHHS-45	Boiler room ceiling	No	SM		Boiler Room	
OHHS-46	Weight room mechanical duct jacketing	No	TSI		Removed in 2018	
OHHS-47	1"x1" Splined-on ceiling tile pins and fissures	No	MM		Mall area near auditorium	
OHHS-48	2'x2' Ceiling tile	No	MM		Psychologist's office	
OHHS-49	Flooring under carpet	Flooring- <b>Yes</b> Mastic- No	MM	NF-I	Room 207	Good
OHHS-50	12"x12" Olive floor tile w/mastic	Flooring- No Mastic- No	MM	NF-I	Hallway near 247	Good
OHHS-51	Brick mortar	No	MM		All brick walls	
OHHS-52	Ceramic grout	No	MM		Ceramic tile areas	
OHHS-53	Block mortar	No	MM		All cinderblock walls	
OHHS-54	2'x4' Ceiling tile	No	MM		Band Room 101	
OHHS-55	Pipe gasket	Yes	MM	NF-II	Chiller room	Good

### FRIABILITY:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II

### MATERIAL TYPE:

TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

#### CONDITION:

Good: Little or no damage

Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

SF: Square feet LF: Linear feet FT: Fittings NQ: Not Quantified

This page has been left blank intentionally

October 25<sup>th</sup>, 2019 Project Number: MA-117-19

Mr. Marc Bennett Grand Rapids Public Schools 900 Union, NE Grand Rapids, MI 49503

Re: AHERA 3 Year Reinspection Report Grand Rapids Public Schools – **Riverside Middle School** 

Dear Mr. Bennett:



119 West Cass Street P.O. Box 908 Greenville, MI 48838 Phone: 616-302-0819 Web: microairconsulting.com Email: microairconsulting@gmail.com

MicroAir Consulting, LLC (MicroAir) was retained by Grand Rapids Public Schools (GRPS), to conduct an AHERA 3-year reinspection of Riverside Middle School located at 265 Eleanor Street, NE in Grand Rapids, Michigan. The inspection was conducted according to the protocol described in the U.S. Environmental Protection Agency Asbestos Hazard Emergency Response Act of 1986 (40 CFR 763).

### CERTIFICATION

The building inspection was conducted on October 19<sup>th</sup>, 2019 by Mr. Ryan Emmons, a State of Michigan accredited Asbestos Building Inspector. Mr. Emmons, Accreditation Number is A55220. Additional bulk samples were collected during this inspection.

### **REGULATORY BACKGROUND**

As a public and commercial building, Riverside Middle School is governed by 29 CFR 1910.1001, Occupational Health Standards for Asbestos in Construction/General Industry and the EPA's NESHAP for the normal course of business activities by GRPS employees and occupants.

There are three state agencies in Michigan that regulate asbestos in Michigan: the Michigan Department of Environmental Quality (DEQ), the Michigan Department of Licensing and Regulatory Affairs (DLARA) and the Michigan Department of State Police (MSP). The DEQ is concerned about the release of asbestos fibers to the outer air and proper waste disposal, while DLARA focuses on worker protection during renovation and demolition activities, contractor licensing, and worker training.

During construction or renovation activities, the persons performing those activities would be governed by 29 CFR 1926.1101, Occupational Health Standards for Asbestos in Construction. The Asbestos Hazard Emergency Response Act (AHERA), 40 CFR 763, (partial) and/or its associated requirements. However, there are some portions of AHERA that are used as guidelines for compliance with 29 CFR 1910.1001. In particular, 29 CFR 1910.1001(j)(1) requires owners of buildings constructed prior to 1980 to presume that certain types of building materials are asbestos-containing materials (ACM), unless the owner demonstrates that those materials are not ACM.

40 CFR Part 61, Subpart M (NESHAP) requires that a thorough inspection be conducted prior to all renovations and all demolitions. A thorough inspection for asbestos is required no matter the age of the facility because all uses of asbestos are not banned. The inspection must be completed before the commencement of a subject renovation and/or demolition activity.

### **BUILDING DESCRIPTION**

The Riverside Middle School building was constructed in 1956. Some building renovations have occurred throughout over the years.

### **PREVIOUS INSPECTION**

The most recent inspection was conducted by GRPS in 2019. MicroAir reviewed this report and incorporated the findings of the previous inspection and historical information into the current reinspection data.

In the previous inspection report suspect ACM materials were given a unique identification number (homogeneous material number), MicroAir has changed numbering from previous reports. The reinspection did

include the collection of bulk samples. Results of the sampling can be found in Appendix A along with locations of remaining ACM in the building.



### **REINSPECTION PROCEDURES**

With the assistance of GRPS maintenance staff, MicroAir re-inspected known and previously identified areas of the building including above suspended ceilings, pipe chases, and inside the tunnels.

It was beyond the scope of this reinspection to locate, identify, or quantify ACM in areas that were concealed and/or inaccessible areas, such as within walls, hard ceilings, or equipment.

### **2019 REINSPECTION FINDINGS**

The following suspect asbestos-containing materials were observed at Riverside Middle School during the asbestos inspection and the bulk sampling. Materials in **bold** were found to be greater than 1% ACM.

- Brick mortar
- Block mortar
- Concrete
- Decorative block mortar
- Decorative slab mortar
- Exterior soffits
- Exterior window caulk
- Ceramic grout
- Office plaster
- Tan cove base w/mastic
- Fire doors and frames
- Mudded pipe fittings
- 1'x1' ceiling tile splined on
- Interior window glaze
- 12"X12" floor tile tan w/mastic
- Black cove base w/mastic
- 1'x1 ceiling tile w/holes w/glue pod
- Gray cove base w/mastic
- 2'x2' ceiling tiles
- 12"X12" floor tile beige w/mastic
- Older chalkboards
- Wood floor underlayment
- Vibration dampener
- Mudded roof drain
- Gray cove base w/mastic
- Vinyl stair tread w/mastic
- 12"x12" floor tile w/squares w/mastic
- Vinyl stair tread red w/mastic
- Roofing materials

Some of the materials listed above are assumed to contain asbestos until bulk samples can be collected and analyzed.

Appendix A of this report is a table that identifies the confirmed and suspect ACM homogeneous materials in Riverside Middle School, their corresponding identification number and locations, and the general condition of ACMs identified during the reinspection.

### CONCLUSIONS AND RECOMMENDATIONS

MicroAir was retained by Grand Rapids Public Schools to conduct a 3-year asbestos-containing material (ACM) reinspection of Riverside Middle School located at 265 Eleanor Street, NE in Grand Rapids, Michigan. MicroAir completed the reinspection on October 19<sup>th</sup>, 2019. The inspection was conducted by a State of Michigan accredited Asbestos Building Inspector.

If GRPS plans to conduct any renovation or demolition, the identified ACMs should be removed by a licensed asbestos abatement contractor, as required by current federal, state, and local laws and regulations, should perform any necessary removal and disposal of the identified ACM.



MicroAir notes that if suspect ACM other than those identified during this reinspection are encountered during any renovation or demolition, such materials should be sampled and analyzed using PLM to verify presence of asbestos.

We also recommend that visual observations, verification of removal and cleanup, and air monitoring or clearance air monitoring for asbestos fibers be performed by a third party retained by GRPS to demonstrate compliance with applicable regulations, and to confirm the suitability or the area for re-entry. MicroAir can perform these services.

Warning labels should be affixed in all non-public areas where ACM or assumed ACM is present. After completion of repairs or removal of the ACM, fill out an O&M Activities Form and file it in the management plan.

As required by AHERA, GRPS should continue to send the annual notifications including information on planned response actions and reinspections. Copies of the notifications should be kept in the Management Plan.

### LIMITATIONS

The conclusions drawn from the observations and sample results are only valid for the time the observations occurred. In the process of gathering the field data included in this report, procedures were followed that represent reasonable and acceptable industrial hygiene practices and procedures in a manner consistent with the level of care and skill ordinarily exercised by other members of this profession currently practicing under similar conditions. However, the information and opinions provided in this report are not to be construed as a warranty of the conditions of this site in any way, implied or explicit. MicroAir accepts no responsibility for the use, interpretation, or reliance by other parties on the information contained herein, nor does this report represent an instrument of regulatory compliance or an asbestos abatement specification.

In conducting the reinspection there are a number of obstacles and limitations that can affect the final outcome of the report. These limitations include but are not limited to the following factors: access concerns, materials that cannot be intrusively sampled or damaged, materials that have been replaced by renovation activities, materials with conflicting laboratory results, and materials that are located in inaccessible and/or concealed areas which limits its quantification. Due to these limitations, the results of this investigation cannot be construed as a certification of the presence or absence of ACM, beyond the materials identified, but rather a diligent and prudent review of available data within an established work scope, and time and budgetary constraints.

If you have any questions or require additional information, please contact me at 616-302-0819 or microairconsulting@gmail.com. Thank you.

Sincerely,

**MicroAir Consulting, LLC** 

isten T. Decker

Christian T. Decker Accredited Building Inspector and Management Planner

# **APPENDIX A**

## TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS

### APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS RIVERSIDE MIDDLE SCHOOL INSPECTION DATE: OCTOBER 19<sup>th</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	FUNCTIONAL AREA	CONDITION
RSM-1	Brick mortar	No		All brick walls	
RSM-2	Block mortar	Assumed	NF-II	All block walls	Good
RSM-3	Concrete	No		All Concrete	
RSM-4	Decorative block mortar	No		Exterior decorative blocks	
RSM-5	Decorative slab mortar	No		Exterior decorative slab	
RSM-6	Exterior soffits	Yes	SM	Entry and soffits	Good
RSM-7	Exterior window caulk	Yes	NF-II	Exterior windows	Good
RSM-8	Ceramic grout	No		Hallways and bathrooms	
RSM-9	Office plaster	No		Walls and ceilings in the office closet	
RSM-10	Tan cove base w/mastic	No		Office	
RSM-11	Fire doors and frames	Yes	NF-II	All tagged doors	Good
RSM-12	Mudded pipe fittings	Yes	F	Tunnels	Good
RSM-13	1'x1' ceiling tile – splined on	No		Hallways	
RSM-14	Interior window glaze	Yes	NF-II	Boiler room and classroom windows	Good
RSM-15	12"X12" floor tile tan w/mastic	Assumed	NF-I	Hallways	Good
RSM-16	Black cove base w/mastic	Assumed	NF-II	Classrooms	Good
RSM-17	1'x1 ceiling tile w/holes w/glue pod	Both- No		Hallways 176, 177 and 180	
RSM-18	Gray cove base w/mastic	Assumed	NF-II	Hallway and classrooms	Good
RSM-19	2'x2' ceiling tiles	No		Hallways	

#### FRIABILITY:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II MATERIAL TYPE:

#### TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

#### **CONDITION:**

Good: Little or no damage

Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

SF: Square feet LF: Linear feet FT: Fittings NQ: Not Quantified

### APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS RIVERSIDE MIDDLE SCHOOL INSPECTION DATE: OCTOBER 19<sup>th</sup>, 2019



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	FUNCTIONAL AREA	CONDITION
RSM-20	12"X12" floor tile beige w/mastic	Assumed	NF-I	Classrooms	Good
RSM-21	Older chalkboards	Assumed	NF-II	Classrooms	Good
RSM-22	Wood floor underlayment	Assumed	NF-I	Gym	Good
RSM-23	Vibration dampener	Assumed	NF-II	HVAC ductwork	Good
RSM-24	Mudded roof drain	Assumed	F	Gym	Good
RSM-25	Gray cove base w/mastic	Assumed	NF-II	Under lockers	Good
RSM-26	Vinyl stair tread w/mastic	Assumed	NF-I	Near gym	Good
RSM-27	12"x12" floor tile w/squares w/mastic	Assumed	NF-I	Near gym	Good
RSM-28	Vinyl stair tread red w/mastic	Assumed	NF-I	Computer Lab	Good
RSM-29	Roofing materials	Assumed	NF-I	Asphalt roofing	Good

#### FRIABILITY:

F: Friable NF-I: Non-friable Category I NF-II: Non-friable Category II

#### MATERIAL TYPE:

TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material

#### **CONDITION:**

Good: Little or no damage

Damaged: Less than  $10^{\circ}$ % damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

SF: Square feet LF: Linear feet FT: Fittings NQ: Not Quantified

This page has been left blank intentionally

February 12<sup>th</sup>, 2019 Project Number: MA-158-18

Mr. Marc Bennett Grand Rapids Public Schools 900 Union, NE Grand Rapids, MI 49503

Re: AHERA 3 Year Reinspection Report Grand Rapids Public Schools – Southwest Community Campus School Consulting, LLC 119 West Cass Street P.O. Box 908 Grand Rapids, MI 48838 Phone: 616-302-0819 Web: microairconsulting.com Email: microairconsulting@gmail.com

Dear Mr. Bennett:

MicroAir Consulting, LLC (MicroAir) was retained by Grand Rapids Public Schools (GRPS), to conduct an AHERA 3-year reinspection of Southwest Community Campus School (SWCC) located at 801 Oakland Avenue SW in Grand Rapids, Michigan. The inspection was conducted according to the protocol described in the U.S. Environmental Protection Agency Asbestos Hazard Emergency Response Act of 1986 (40 CFR 763).

### CERTIFICATION

The building inspection was conducted on February 4<sup>th</sup>, 2019 by Mr. Grant Edgerly, a State of Michigan accredited Asbestos Building Inspector. Mr. Edgerly's, Accreditation Number is A41792.

### **REGULATORY BACKGROUND**

As a public and commercial building, SWCC is governed by 29 CFR 1910.1001, Occupational Health Standards for Asbestos in Construction/General Industry and the EPA's NESHAP for the normal course of business activities by GRPS employees and occupants.

There are three state agencies in Michigan that regulate asbestos in Michigan: the Michigan Department of Environmental Quality (DEQ), the Michigan Department of Licensing and Regulatory Affairs (DLARA) and the Michigan Department of State Police (MSP). The DEQ is concerned about the release of asbestos fibers to the outer air and proper waste disposal, while DLARA focuses on worker protection during renovation and demolition activities, contractor licensing, and worker training.

During construction or renovation activities, the persons performing those activities would be governed by 29 CFR 1926.1101, Occupational Health Standards for Asbestos in Construction. The Asbestos Hazard Emergency Response Act (AHERA), 40 CFR 763, (partial) and/or its associated requirements. However, there are some portions of AHERA that are used as guidelines for compliance with 29 CFR 1910.1001. In particular, 29 CFR 1910.1001(j)(1) requires owners of buildings constructed prior to 1980 to presume that certain types of building materials are asbestos-containing materials (ACM), unless the owner demonstrates that those materials are not ACM.

40 CFR Part 61, Subpart M (NESHAP) requires that a thorough inspection be conducted prior to all renovations and all demolitions. A thorough inspection for asbestos is required no matter the age of the facility because all uses of asbestos are not banned. The inspection must be completed before the commencement of a subject renovation and/or demolition activity.

### **BUILDING DESCRIPTION**

The Southwest Community Campus School building was constructed in 1915. Some building renovations have occurred throughout over the years.

### **PREVIOUS INSPECTION**

The most recent inspection was conducted by GRPS in 2018. MicroAir reviewed this report and incorporated the findings of the previous inspection and historical information into the current reinspection data.

In the previous inspection report suspect ACM materials were given a unique identification number (homogeneous material number), MicroAir has changed numbering from previous reports. The reinspection did include the collection of bulk samples. Results of the sampling can be found in Appendix A along with locations of remaining ACM in the building.



### **REINSPECTION PROCEDURES**



With the assistance of GRPS maintenance staff, MicroAir re-inspected known and previously identified areas of the building including above suspended ceilings, pipe chases, and inside the tunnels.

It was beyond the scope of this reinspection to locate, identify, or quantify ACM in areas that were concealed and/or inaccessible areas, such as within walls, hard ceilings, or equipment.

### 2019 REINSPECTION FINDINGS

The following suspect asbestos-containing materials were observed at Southwest Community Campus School during the asbestos inspection and the bulk sampling. Materials in **bold** were found to be greater than 1% ACM.

- Plaster
- Hard Plaster
- Drywall, tape and mud
- Troweled on flooring
- 12"x12" floor tile w/mastic
- Wood floor underlayment
- 1'x1' Ceiling tile w/glue pods
- Stack liner
- Sink undercoating
- Mortars
- Ceramic grout
- Fire doors and window frames
- Concrete
- Roofing

Some of the materials listed above are assumed to contain asbestos until bulk samples can be collected and analyzed.

Appendix A of this report is a table that identifies the confirmed and suspect ACM homogeneous materials in SWCC, their corresponding identification number and locations, and the general condition of ACMs identified during the reinspection.

### CONCLUSIONS AND RECOMMENDATIONS

MicroAir was retained by Grand Rapids Public Schools to conduct a 3-year asbestos-containing material (ACM) reinspection of Southwest Community Campus School located at 801 Oakland Avenue, SW in Grand Rapids, Michigan. MicroAir completed the reinspection on February 4<sup>th</sup>, 2019. The inspection was conducted by a State of Michigan accredited Asbestos Building Inspector.

During the reinspection, MicroAir identified and assessed 14 homogeneous materials remaining in Southwest Community Campus School.

Any personnel entering a tunnel or chase area must be notified of ACM locations and explained the requirement to wear personal protective equipment.

If GRPS plans to conduct any renovation or demolition, the identified ACMs should be removed by a licensed asbestos abatement contractor, as required by current federal, state, and local laws and regulations, should perform any necessary removal and disposal of the identified ACM. MicroAir notes that if suspect ACM other than those identified during this reinspection are encountered during any renovation or demolition, such materials should be sampled and analyzed using PLM to verify presence of asbestos.

We also recommend that visual observations, verification of removal and cleanup, and air monitoring or clearance air monitoring for asbestos fibers be performed by a third party retained by GRPS to demonstrate compliance with applicable regulations, and to confirm the suitability or the area for re-entry. MicroAir can perform these services.

Warning labels should be affixed in all non-public areas where ACM or assumed ACM is present. After completion of repairs or removal of the ACM, fill out an O&M Activities Form and file it in the management plan.

As required by AHERA, GRPS should continue to send the annual notifications including information on planned response actions and reinspections. Copies of the notifications should be kept in the Management Plan.



### LIMITATIONS

The conclusions drawn from the observations and sample results are only valid for the time the observations occurred. In the process of gathering the field data included in this report, procedures were followed that represent reasonable and acceptable industrial hygiene practices and procedures in a manner consistent with the level of care and skill ordinarily exercised by other members of this profession currently practicing under similar conditions. However, the information and opinions provided in this report are not to be construed as a warranty of the conditions of this site in any way, implied or explicit. MicroAir accepts no responsibility for the use, interpretation, or reliance by other parties on the information contained herein, nor does this report represent an instrument of regulatory compliance or an asbestos abatement specification.

In conducting the reinspection there are a number of obstacles and limitations that can affect the final outcome of the report. These limitations include but are not limited to the following factors: access concerns, materials that can not be intrusively sampled or damaged, materials that have been replaced by renovation activities, materials with conflicting laboratory results, and materials that are located in inaccessible and/or concealed areas which limits its quantification. Due to these limitations, the results of this investigation cannot be construed as a certification of the presence or absence of ACM, beyond the materials identified, but rather a diligent and prudent review of available data within an established work scope, and time and budgetary constraints.

If you have any questions or require additional information, please contact me at 616-302-0819 or microairconsulting@gmail.com. Thank you.

Sincerely,

**MicroAir Consulting, LLC** 

iten T. Deeker

Christian T. Decker Accredited Building Inspector and Management Planner

# **APPENDIX A**

## TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS

## **APPENDIX A- 3 YEAR REINSPECTION TESTED AND SUSPECT ASBESTOS-CONTAINING MATERIALS** SOUTHWEST COMMUNITY CAMPUS SCHOOL **INSPECTION DATE: FEBRUARY 4th, 2019**



HSA NO.	HSA MATERIAL DESCRIPTION	ASBESTOS?	MATERIAL TYPE	F/NF	FUNCTIONAL AREA	CONDITION
SWCC-1	Plaster	No	SM		Walls and ceilings	
SWCC-2	Hard Plaster	No	SM		Boiler room ceiling	
SWCC-3	Drywall, tape and mud	No	SM		Drywall walls over plaster	
SWCC-4	Troweled on flooring	Yes	SM	NF-I	Under carpet in original hallways, Base molds in hallways, Stairways including stringers, Rooms 131, 133, 230- 233, 330, 332, Entry to 120 and Boiler room floor	Damaged
SWCC-5	12"x12" floor tile w/mastic	Assumed	MM	NF-I	All 12"x12" floor tile areas	Good
SWCC-6	Wood floor underlayment	Assumed	ММ	NF-I	Under all hard wood floors	Good
SWCC-7	1'x1' Ceiling tile w/glue pods	Assumed	ММ	NF-II	Stairways	Good
SWCC-8	Stack liner	Assumed	SM	F	Inside stack from boiler room	Good
SWCC-9	Sink undercoating	Assumed	ММ	NF-II	All original caulks and sealants	Good
SWCC-10	Mortars	Assumed	MM	NF-II	All block and brick walls	Good
SWCC-11	Ceramic grout	Assumed	MM	NF-I	Ceramic tiled areas	Good
SWCC-12	Fire doors and window frames	Yes	MM	NF-II	Boiler room and other tagged fire doors, Stairway windows	Good
SWCC-13	Concrete	Assumed	MM	NF-II	All concrete	Good
SWCC-14	Roofing	Assumed	MM	NF-I	Exterior asphalt roofing	Good

FRIABILITY: F: Friable

MATERIAL TYPE:

TSI: Thermal System Insulation SM: Surfacing Material MM: Miscellaneous Material NF-II: Non-friable Category II

CONDITION:

Good: Little or no damage Damaged: Less than 10% damage of total surface area, or less than 25% damage in a localized area Significantly Damaged: Greater than 10% damage of total surface area, or greater than 25% damage in a localized area

SF: Square feet LF: Linear feet FT: Fittings NQ: Not Quantified

NF-I: Non-friable Category I

This page has been left blank intentionally